

05-May-2016 **PCN** #:E-16-005843

Subject:PTL Contacts 1971779, 80, 81, 82, 83, 84, 85, 86, 87, 88, 1237, 1238, 2232723, 2232724, 2238066 and 2238067

Description of Change: Change stabilizer shape from rounded to square. On MFBL Receptacle 2232723 only reduce the height of the Keying Tab. Important Note: the change in the Stabilizer requires a change in the anvil that is in the Crimping Applicator. This change is considered by TE Connectivity as a form change. Pending customer approval, implementation may be accelerated.

Reason: Product Improvement. Reduce potential mating issues and increase retention when used in High Temp housings with a TPA. Keying Tab change in 2238066 is to further differentiate it from the shorter length 1971783 receptacle.

Impact of Change: form - fit - function

Key Dates:

Contact By Date: 20-May-2016

Implementation Date:20-May-2016

Product Affected

1971784-1

1971782-2

1971237-1

1971787-2

1971788-1

1971784-2

1971780-1

1971238-1

1971781-2

Product Affected

- 1971785-2
- 1971786-2
- 1971238-2
- 1971785-1
- 2232723-1
- 1971779-1
- 1971786-1
- 1971788-2
- 1971779-2
- 1971787-1
- 1971781-1
- 1971782-1
- 1971783-1
- 1971783-2
- 1971780-2
- 1971237-2
- 2232724-1

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.