



Product Change Notification

Current Date: 08-Feb-2016

TE Connectivity

Product Change Notification: P-16-012578

PCN Date: 02-FEB-16

Customer: TTI Inc(0000139702)

Location: WORLDWIDE

Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

AFFECTS CUSTOMER SHIPMENTS WITHIN NORTH AMERICA ONLY Delay of Migration: Southwest DC to New El Paso DC

Description of Changes

UPDATE TO PCN P-16-012526. To ensure a smooth and stable transition from SWDC to EPDC, TE will be delaying the transition from the current Santa Teresa, NM DC (SWDC) to the new El Paso, TX DC (EPDC), originally scheduled to implement February 8th - 15th, is now scheduled to implement April 11th - 15th. This delay will allow extended testing on all SAP systems and procedures to ensure a seamless transition into the new warehouse. As we migrate the product and go-live on the new SAP WM software, it is critical to ensure this testing and training is fully incorporated into the systems and operational processes in the new El Paso warehouse. Based on the revised timing of transition, both Customer Shipments and Supplier Deliveries will continue to process from the Santa Teresa, NM location: Address: 101 Lindbergh, Santa Teresa, NM 88008, DUNS Code: 036967748. See attached Customer Letter.

Other attachments:

[Customer Letter](#)

Reason for Changes:

Customer Request. The team arrived at this decision to delay the migration with a focus on our customers and to provide a seamless transition to the new warehouse in El Paso. Per PCN P-16-012526, as of the end of August 2015, our current distribution center located in Santa Teresa, New Mexico was divested to Commscope. As a result, TE has established a new Distribution Center in El Paso, TX to support our South-West Customers. In conjunction with the relocation, our new El Paso Distribution Center will be operating on SAP Warehouse Management. The transition will be transparent with the exception of the SAP Packing List. Currently with the use of MOVE in our Santa Teresa DC, Packing Lists can only be printed by carton or by pallet. With the use of SAP Warehouse Management in our El Paso DC, the Packing Lists will be printed by shipment and/or by pallet.

Estimated Dates:

Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	11-APR-2016
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	No Mixed Shipments

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
0744754002	NO			"9-1190556-9", "HTAT-32/8-0-SP"			
0838016002	NO			"3-1190619-9", "RBK-VWS-125-NR1-X-50MM"			
0934444003	NO			"4-1198113-4", "HFT5000-40/20-0-SP", "HFT5000-40/20-0-SP"			
0989076002	NO			"6-1190724-6", "RBK-ILS-125-NR2-0-50MM"			
1-1355350-1	NO						
1-1355426-1	NO						
1-1393194-5	NO			"T77-S1D-312", "T77S1D3-12"			
1-1452024-1	NO						
1-1670571-1	NO						
1-1670915-1	NO						
1-1670918-1	NO						
1-1703498-1	NO						

1-1718643-1	NO			"EG9733-000", "AMP-1-1718643-1"			
1-1718644-1	NO						
1-1823608-1	NO						
1-188685-2	NO						
1-2141324-1	NO						
1-929504-7	NO						
1-962349-1	NO						
1-962352-1	NO						
1-963207-1	NO						
1-963211-1	NO						
1-963212-1	NO						
1-963214-1	NO						
1-963217-1	NO						
1-963221-1	NO						
1-963224-1	NO						
1-963228-1	NO						
1-963484-1	NO						
1-964330-1	NO						
1-964449-1	NO						
1-965421-1	NO						
1-965423-1	NO						
1-965426-1	NO						
1-965641-1	NO						
1-965641-3	NO						
1-965641-5	NO						
1-967241-1	NO						
1-967280-1	NO						
1-967626-4	NO						

1-967627-1	NO						
1-967627-5	NO						
1-967628-1	NO						
1-967628-2	NO						
1-967628-6	NO						
1-967629-2	NO						
1-967629-3	NO						
1-967629-4	NO						
1-967630-1	NO						
1-967630-2	NO						
1-967630-3	NO						
1-967630-5	NO						
1-968840-1	NO						
1-968879-1	NO						
100132-1	NO						
100284-1	NO						
1241388-1	NO						
1241388-2	NO						
1241390-1	NO						
1241394-1	NO						
1241394-2	NO						
1241396-1	NO						
1241396-3	NO						
1241846-2	NO						
1326646-1	NO						
1355348-1	NO						
1418760-1	NO						
1438731-4	NO						
1452317-1	NO						

1534180-1	NO						
1534181-1	NO						
1534184-1	NO						
1534579-1	NO						
1718758-3	NO						
1718760-1	NO						
1718760-2	NO						
1718760-3	NO						
185026-1	NO						
2-1703498-1	NO						
2-1823608-1	NO						
2-963207-1	NO						
2-963212-1	NO						
2-965261-1	NO						
2-967630-1	NO						
2-967677-1	NO						
2065124003	NO				"2-1198113-0", "HFT5000-20/10-0-SP"		
2177610-3	NO						
2292184003	NO				"2-1198113-4", "HFT5000-60/30-0-SP"		
2709943001	NO				"2-1197957-5", "ACW0219-0.75-9(NS)"		
3-963207-1	NO						
342413-2	NO						
344089-1	NO						
344260-1	NO						
344261-1	NO						
344274-1	NO						
345253-1	NO						

345256-1	NO						
345258-1	NO						
345259-1	NO						
345484-1	NO						
345808-1	NO						
346189-5	NO						
348461-1	NO						
4-963210-1	NO						
6979344003	NO			"6-1198112-7", "HFT5000-30/15-0-SP", "HFT5000-30/15-0-SP"			
925612-1	NO						
926554-1	NO						
926965-1	NO						
927824-2	NO						
927827-1	NO						
927827-2	NO						
927829-2	NO						
927831-1	NO						
927831-2	NO						
927835-1	NO						
927837-1	NO						
927837-2	NO						
927837-5	NO						
927839-2	NO						
927840-2	NO						
927847-2	NO						
927879-2	NO						
927892-1	NO			"AMPS-0-0927892-1", "C75578-000"			

928781-2	NO			"0-0928781-2"			
928930-2	NO			"0-0928930-2"			
928939-1	NO						
929027-1	NO						
929505-1	NO			"356738-000", "AMPS-0-0929505-1"			
929505-3	NO						
929505-4	NO						
929505-5	NO						
929505-7	NO						
962928-1	NO						
962932-1	NO						
963205-1	NO						
963208-1	NO						
963213-1	NO						
963225-1	NO						
963361-1	NO						
963534-1	NO						
963709-2	NO						
963898-2	NO						
963900-1	NO						
963902-1	NO						
963904-1	NO						
964265-2	NO						
964265-3	NO						
964267-2	NO						
964267-3	NO						
964269-2	NO						
964269-3	NO						

964269-5	NO						
964324-1	NO						
964326-1	NO						
964328-1	NO						
964693-1	NO						
967558-1	NO						
969028-2	NO						
969044-1	NO						

Customer: TTI Inc.(1305175)

Location: Maisach-Gernlinden

Agreement Number: TTI001

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
0744754002	NO		RAY0744754002	"9-1190556-9", "HTAT-32/8-0-SP"			
0838016002	NO		RAY0838016002	"3-1190619-9", "RBK-VWS-125-NR1-X-50MM"			
0934444003	NO			"4-1198113-4", "HFT5000-40/20-0-SP", "HFT5000-40/20-0-SP"			
0989076002	NO			"6-1190724-6", "RBK-ILS-125-NR2-0-50MM"			
1-1355350-1	NO		TYC1-1355350-1				
1-1355426-1	NO		TYC1-1355426-1				
1-1393194-5	NO		TYC1-1393194-5	"T77-S1D-312", "T77S1D3-12"			
1-1452024-1	NO						
1-1670571-1	NO		TYC1-1670571-1				
1-1670915-1	NO		TYC1-1670915-1				

1-1703498-1	NO		TYC1-1703498-1				
1-1718643-1	NO		TYC1-1718643-1	"EG9733-000", "AMP-1-1718643-1"			
1-1718644-1	NO		TYC1-1718644-1				
1-188685-2	NO		TYC1-188685-2				
1-929504-7	NO		TYC1-929504-7				
1-962349-1	NO		TYC1-962349-1				
1-962352-1	NO		TYC1-962352-1				
1-963207-1	NO		TYC1-963207-1				
1-963211-1	NO		TYC1-963211-1				
1-963212-1	NO		TYC1-963212-1				
1-963214-1	NO		TYC1-963214-1				
1-963217-1	NO		TYC1-963217-1				
1-963221-1	NO		TYC1-963221-1				
1-963224-1	NO		TYC1-963224-1				
1-963228-1	NO		TYC1-963228-1				
1-963484-1	NO		TYC1-963484-1				
1-964330-1	NO		TYC1-964330-1				
1-964449-1	NO		TYC1-964449-1				
1-965421-1	NO		TYC1-965421-1				
1-965423-1	NO		TYC1-965423-1				
1-965426-1	NO		TYC1-965426-1				
1-965641-1	NO		TYC1-965641-1				
1-965641-3	NO		TYC1-965641-3				
1-965641-5	NO		TYC1-965641-5				
1-967241-1	NO		TYC1-967241-1				
1-967280-1	NO		TYC1-967280-1				
1-967626-4	NO		TYC1-967626-4				
1-967627-1	NO		TYC1-967627-1				

1-967627-5	NO		TYC1-967627-5			
1-967628-1	NO		TYC1-967628-1			
1-967628-2	NO		TYC1-967628-2			
1-967628-6	NO		TYC1-967628-6			
1-967629-2	NO		TYC1-967629-2			
1-967629-3	NO		TYC1-967629-3			
1-967629-4	NO		TYC1-967629-4			
1-967630-1	NO		TYC1-967630-1			
1-967630-2	NO		TYC1-967630-2			
1-967630-3	NO		TYC1-967630-3			
1-967630-5	NO		TYC1-967630-5			
1-968840-1	NO					
1-968879-1	NO		TYC1-968879-1			
100132-1	NO		TYC100132-1			
100284-1	NO		TYC100284-1			
1241388-1	NO		TYC1241388-1			
1241388-2	NO		TYC1241388-2			
1241390-1	NO		TYC1241390-1			
1241394-1	NO		TYC1241394-1			
1241396-1	NO		TYC1241396-1			
1241396-3	NO		TYC1241396-3			
1241846-2	NO		TYC1241846-2			
1355348-1	NO		TYC1355348-1			
1418760-1	NO					
1452317-1	NO		TYC1452317-1			
1534180-1	NO					
1534181-1	NO					
1534184-1	NO		TYC1534184-1			
1534579-1	NO		TYC1534579-1			

1718758-3	NO		TYC1718758-3			
1718760-1	NO		TYC1718760-1			
1718760-2	NO					
1718760-3	NO		TYC1718760-3			
185026-1	NO		TYC185026-1			
2-1823608-1	NO		TYC2-1823608-1			
2-963207-1	NO		TYC2-963207-1			
2-963212-1	NO		TYC2-963212-1			
2-965261-1	NO					
2-967630-1	NO		TYC2-967630-1			
2-967677-1	NO					
2292184003	NO		RAY2292184003	"2-1198113-4", "HFT5000-60/30-0-SP"		
2709943001	NO		RAY2709943001	"2-1197957-5", "ACW0219-0.75-9(NS)"		
3-963207-1	NO		TYC3-963207-1			
342413-2	NO		TYC342413-2			
344089-1	NO		TYC344089-1			
344260-1	NO		TYC344260-1			
344261-1	NO		TYC344261-1			
344274-1	NO		TYC344274-1			
345253-1	NO		TYC345253-1			
345256-1	NO		TYC345256-1			
345258-1	NO		TYC345258-1			
345259-1	NO		TYC345259-1			
345484-1	NO		TYC345484-1			
345808-1	NO		TYC345808-1			
346189-5	NO		TYC346189-5			
348461-1	NO		TYC348461-1			

4-963210-1	NO					
925612-1	NO		TYC925612-1			
926965-1	NO		TYC926965-1			
927824-2	NO		TYC927824-2			
927827-1	NO		TYC927827-1			
927827-2	NO		TYC927827-2			
927829-2	NO		TYC927829-2			
927831-1	NO		TYC927831-1			
927831-2	NO		TYC927831-2			
927835-1	NO		TYC927835-1			
927837-1	NO		TYC927837-1			
927837-2	NO		TYC927837-2			
927837-5	NO		TYC927837-5			
927839-2	NO		TYC927839-2			
927847-2	NO		TYC927847-2			
927879-2	NO		TYC927879-2			
927892-1	NO		TYC927892-1	"AMPS-0-0927892-1", "C75578-000"		
928781-2	NO		TYC928781-2	"0-0928781-2"		
928930-2	NO		TYC928930-2	"0-0928930-2"		
928939-1	NO		TYC928939-1			
929027-1	NO		TYC929027-1			
929505-1	NO		TYC929505-1	"356738-000", "AMPS-0-0929505-1"		
929505-3	NO		TYC929505-3			
929505-4	NO		TYC929505-4			
929505-5	NO		TYC929505-5			
929505-7	NO		TYC929505-7			
962928-1	NO		TYC962928-1			

962932-1	NO		TYC962932-1			
963205-1	NO		TYC963205-1			
963208-1	NO		TYC963208-1			
963213-1	NO		TYC963213-1			
963225-1	NO		TYC963225-1			
963361-1	NO		TYC963361-1			
963534-1	NO		TYC963534-1			
963709-2	NO		TYC963709-2			
963898-2	NO		TYC963898-2			
963900-1	NO		TYC963900-1			
963902-1	NO		TYC963902-1			
963904-1	NO		TYC963904-1			
964265-2	NO		TYC964265-2			
964265-3	NO		TYC964265-3			
964267-2	NO		TYC964267-2			
964267-3	NO		TYC964267-3			
964269-2	NO		TYC964269-2			
964269-3	NO		TYC964269-3			
964269-5	NO		TYC964269-5			
964324-1	NO		TYC964324-1			
964326-1	NO		TYC964326-1			
964328-1	NO		TYC964328-1			
964693-1	NO		TYC964693-1			
967558-1	NO		TYC967558-1			
969028-2	NO		TYC969028-2			
969044-1	NO		TYC969044-1			

Customer: TTI Inc(168830)

Location: Fort Worth

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
0934444003	NO			"4-1198113-4", "HFT5000-40/20-0-SP", "HFT5000-40/20-0-SP"			
1-1393194-5	NO			"T77-S1D-312", "T77S1D3-12"			
1-1670918-1	NO						
1-1718643-1	NO			"EG9733-000", "AMP-1-1718643-1"			
1-1718644-1	NO						
1-2141324-1	NO						
1-963217-1	NO						
1-967628-1	NO						
1-967628-6	NO						
1-967630-1	NO						
1241390-1	NO						
1241394-2	NO						
1241396-1	NO						
1326646-1	NO						
1418760-1	NO						
1438731-4	NO						
1718760-1	NO						
1718760-2	NO						
2-1703498-1	NO						
2065124003	NO			"2-1198113-0", "HFT5000-20/10-0-SP"			
2177610-3	NO						
2292184003	NO			"2-1198113-4", "HFT5000-60/30-			

				0-SP"			
2709943001	NO			"2-1197957-5", "ACW0219-0.75-9(NS)"			
6979344003	NO			"6-1198112-7", "HFT5000-30/15-0-SP", "HFT5000-30/15-0-SP"			
926554-1	NO						
927831-2	NO						
927837-1	NO						
928930-2	NO			"0-0928930-2"			
929505-1	NO			"356738-000", "AMPS-0-0929505-1"			
929505-3	NO						
964265-2	NO						
964267-2	NO						
964269-3	NO						
964269-5	NO						
969028-2	NO						

Customer: TTI Electronics Asia Pte Ltd.(2771300)

Location: SINGAPORE

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-962349-1	NO						
926965-1	NO						
927837-5	NO						
927840-2	NO						
928930-2	NO			"0-0928930-2"			

963205-1	NO						
963904-1	NO						
964269-5	NO						

Customer: TTI INC(600629-1)

Location: FORT WORTH TEXAS

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
964267-2	NO						

Customer: TTI (MC)(2922321)

Location: Pointe-Claire

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-1703498-1	NO						
1241396-1	NO						

Customer: Shanghai TTI ELelectronics Co Ltd(1405773)

Location: Shanghai

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
-------------	---------------------------	------------------	----------------------	----------------------	------------------------	---------------------------------	---------------------------

927831-1	NO						
--------------------------	----	--	--	--	--	--	--

Customer: TTI(3003903)

Location: Fort Worth

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-967626-4	NO						
969028-2	NO						

Customer: TTI Electronics Asia Pte Ltd.(1407161)

Location: Tsuen Wan, NT

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
926965-1	NO						
927840-2	NO						
963904-1	NO						
964269-5	NO						

Customer: TTI Inc(1281288)

Location: Fort Worth

Agreement Number: TT1002

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
0934444003	NO			"4-1198113-4", "HFT5000-40/20-0-SP", "HFT5000-40/20-0-SP"			
1-1393194-5	NO			"T77-S1D-312", "T77S1D3-12"			
1-1670918-1	NO						
1-1718643-1	NO			"EG9733-000", "AMP-1-1718643-1"			
1-1718644-1	NO						
1-2141324-1	NO						
1-963217-1	NO						
1-967628-1	NO						
1-967628-6	NO						
1-967630-1	NO						
1241390-1	NO						
1241394-2	NO						
1241396-1	NO						
1326646-1	NO						
1418760-1	NO						
1438731-4	NO						
1718760-1	NO						
1718760-2	NO						
2-1703498-1	NO						
2065124003	NO			"2-1198113-0", "HFT5000-20/10-0-SP"			
2177610-3	NO						
2292184003	NO			"2-1198113-4", "HFT5000-60/30-0-SP"			

6979344003	NO			"6-1198112-7", "HFT5000-30/15-0-SP", "HFT5000-30/15-0-SP"			
926554-1	NO						
927831-2	NO						
927837-1	NO						
928930-2	NO			"0-0928930-2"			
929505-1	NO			"356738-000", "AMPS-0-0929505-1"			
929505-3	NO						
964269-3	NO						
964269-5	NO						
969028-2	NO						

Customer: TTI Inc.(3057778)

Location: Olching

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
0744754002	NO		RAY0744754002	"9-1190556-9", "HTAT-32/8-0-SP"			
0838016002	NO		RAY0838016002	"3-1190619-9", "RBK-VWS-125-NR1-X-50MM"			
0934444003	NO			"4-1198113-4", "HFT5000-40/20-0-SP", "HFT5000-40/20-0-SP"			
1-1355426-1	NO		TYC1-1355426-1				
1-1393194-5	NO		TYC1-1393194-5	"T77-S1D-312", "T77S1D3-12"			
1-1670915-1	NO		TYC1-1670915-1				
1-1703498-1	NO		TYC1-1703498-1				

1-1718643-1	NO		TYC1-1718643-1	"EG9733-000", "AMP-1-1718643-1"			
1-188685-2	NO		TYC1-188685-2				
1-929504-7	NO		TYC1-929504-7				
1-962349-1	NO		TYC1-962349-1				
1-962352-1	NO		TYC1-962352-1				
1-963207-1	NO		TYC1-963207-1				
1-963211-1	NO		TYC1-963211-1				
1-963212-1	NO		TYC1-963212-1				
1-963214-1	NO		TYC1-963214-1				
1-963217-1	NO		TYC1-963217-1				
1-963221-1	NO		TYC1-963221-1				
1-963224-1	NO		TYC1-963224-1				
1-963228-1	NO		TYC1-963228-1				
1-963484-1	NO		TYC1-963484-1				
1-964449-1	NO		TYC1-964449-1				
1-965421-1	NO		TYC1-965421-1				
1-965423-1	NO		TYC1-965423-1				
1-965426-1	NO		TYC1-965426-1				
1-965641-1	NO		TYC1-965641-1				
1-965641-3	NO		TYC1-965641-3				
1-965641-5	NO		TYC1-965641-5				
1-967241-1	NO		TYC1-967241-1				
1-967280-1	NO		TYC1-967280-1				
1-967626-4	NO		TYC1-967626-4				
1-967627-1	NO		TYC1-967627-1				
1-967627-5	NO		TYC1-967627-5				
1-967628-1	NO		TYC1-967628-1				
1-967628-2	NO		TYC1-967628-2				

1-967628-6	NO		TYC1-967628-6			
1-967629-2	NO		TYC1-967629-2			
1-967629-3	NO		TYC1-967629-3			
1-967629-4	NO		TYC1-967629-4			
1-967630-1	NO		TYC1-967630-1			
1-967630-2	NO		TYC1-967630-2			
1-967630-3	NO		TYC1-967630-3			
1-967630-5	NO		TYC1-967630-5			
1-968879-1	NO		TYC1-968879-1			
100132-1	NO		TYC100132-1			
100284-1	NO		TYC100284-1			
1241388-1	NO		TYC1241388-1			
1241388-2	NO		TYC1241388-2			
1241390-1	NO		TYC1241390-1			
1241394-1	NO		TYC1241394-1			
1241396-1	NO		TYC1241396-1			
1241396-3	NO		TYC1241396-3			
1241846-2	NO		TYC1241846-2			
1418760-1	NO					
1452317-1	NO		TYC1452317-1			
1534184-1	NO		TYC1534184-1			
1718758-3	NO		TYC1718758-3			
1718760-1	NO		TYC1718760-1			
1718760-2	NO					
1718760-3	NO		TYC1718760-3			
185026-1	NO		TYC185026-1			
2-1823608-1	NO		TYC2-1823608-1			
2-963212-1	NO		TYC2-963212-1			
2-967630-1	NO		TYC2-967630-1			

2-967677-1	NO						
2709943001	NO		RAY2709943001	"2-1197957-5", "ACW0219-0.75-9(NS)"			
3-963207-1	NO		TYC3-963207-1				
342413-2	NO		TYC342413-2				
344089-1	NO		TYC344089-1				
344260-1	NO		TYC344260-1				
344261-1	NO		TYC344261-1				
344274-1	NO		TYC344274-1				
345253-1	NO		TYC345253-1				
345258-1	NO		TYC345258-1				
345259-1	NO		TYC345259-1				
345484-1	NO		TYC345484-1				
345808-1	NO		TYC345808-1				
346189-5	NO		TYC346189-5				
348461-1	NO		TYC348461-1				
4-963210-1	NO						
926965-1	NO		TYC926965-1				
927824-2	NO		TYC927824-2				
927827-1	NO		TYC927827-1				
927827-2	NO		TYC927827-2				
927829-2	NO		TYC927829-2				
927831-1	NO		TYC927831-1				
927831-2	NO		TYC927831-2				
927837-1	NO		TYC927837-1				
927837-2	NO		TYC927837-2				
927837-5	NO		TYC927837-5				
927839-2	NO		TYC927839-2				
927847-2	NO		TYC927847-2				

927879-2	NO		TYC927879-2			
927892-1	NO		TYC927892-1	"AMPS-0-0927892-1", "C75578-000"		
928781-2	NO		TYC928781-2	"0-0928781-2"		
928930-2	NO		TYC928930-2	"0-0928930-2"		
928939-1	NO		TYC928939-1			
929505-1	NO		TYC929505-1	"356738-000", "AMPS-0-0929505-1"		
929505-3	NO		TYC929505-3			
929505-4	NO		TYC929505-4			
929505-5	NO		TYC929505-5			
929505-7	NO		TYC929505-7			
962932-1	NO		TYC962932-1			
963205-1	NO		TYC963205-1			
963208-1	NO		TYC963208-1			
963213-1	NO		TYC963213-1			
963225-1	NO		TYC963225-1			
963361-1	NO		TYC963361-1			
963709-2	NO		TYC963709-2			
963898-2	NO		TYC963898-2			
963900-1	NO		TYC963900-1			
963902-1	NO		TYC963902-1			
963904-1	NO		TYC963904-1			
964265-2	NO		TYC964265-2			
964267-2	NO		TYC964267-2			
964269-2	NO		TYC964269-2			
964269-3	NO		TYC964269-3			
964324-1	NO		TYC964324-1			
964326-1	NO		TYC964326-1			

964328-1	NO		TYC964328-1			
964693-1	NO		TYC964693-1			
967558-1	NO		TYC967558-1			
969028-2	NO		TYC969028-2			
969044-1	NO		TYC969044-1			

Customer: Shanghai TTI Electronics Co Ltd(3084965)

Location: Shanghai

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-1823608-1	NO						
1-967629-2	NO						

Customer: TTI(2914783)

Location: Austin

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1241394-1	NO						
964269-2	NO						

Customer: TTI Inc(2922318)

Location: Tustin

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
964269-2	NO						

Customer: TTI INC(600629)

Location: FORT WORTH TEXAS

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
964267-2	NO						

Customer: Shanghai TTI ELelectronics Co Ltd(3064990)

Location: Shanghai

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
927831-1	NO						



February 1st, 2016

Dear Valued Customer/Supplier:

Delay of Migration: Southwest Distribution Center to New El Paso Distribution Center

To ensure a smooth and stable transition from SWDC to EPDC, TE will be delaying the transition from the current Santa Teresa, NM Distribution Center (SWDC) to the new El Paso, TX Distribution Center (EPDC), **originally scheduled to implement February 8th - 15th, now scheduled to implement April 11th - 15th**. This delay will allow extended testing on all SAP systems and procedures to ensure a seamless transition into the new warehouse. As we migrate the product and go-live on the new SAP WM software, it is critical to ensure this testing and training is fully incorporated into the systems and operational processes in the new El Paso warehouse.

The team arrived at this decision with a focus on our customers and to provide a seamless transition to the new warehouse in El Paso. We appreciate your support of this delay.

Based on the revised timing of transition, both Customer Shipments and Supplier Deliveries will continue to process from the Santa Teresa, NM location:

- **Address: 101 Lindbergh, Santa Teresa, NM 88008**
- **DUNS Code: 036967748**

If you have any questions regarding this, please feel free to contact TE via your Customer Care Representative/Salesperson/Buyer.

Sincerely,

TE Connectivity