



26-Jul-2016

PCN #:P-16-013346

Subject:DEUTSCH Solid and S&F Socket (Female) Contacts

Description of Change: The Industrial & Commercial Transportation (ICT) business unit of TE Connectivity (TEC) is adding alternate TEC approved supplier for the socket protective sleeve (hood) used on the socket contact part numbers listed below. TEC-ICT will do its due diligence by requiring a PPAP from the supplier. This supplier has been used extensively in the past by TEC business unit with excellent performance.

Reason: Dear Customer, we inform you of this alternate supplier as part of our aggressive continuous improvement efforts on delivery. The alternate supplier process is executed by following TE internal strict procedures, which mitigates quality risk while increasing our ability to supply your products on time. The alternate supplier is governed under a TS16949 certified quality management system according to standard automotive requirements. An internal release based on our specifications will be executed before any parts are delivered.

Impact of Change:Manufacturing location change

Key Dates:

Contact By Date:01-Oct-2016

Implementation Date:01-Oct-2016

Product Affected

4062-002-12141

(Alias Part Numbers:

"4062-002-12141-MS"

"4062-002-12141-M")

4062-006-04141

(Alias Part Numbers:

Product Affected

"4062-006-04141-MS"

"4062-006-04141-M"

"ZPF000000000164378")

0462-203-04141

(Alias Part Numbers:

"ZPF000000000131884"

"0462-203-04141-AS"

"0462-203-04141-LS"

"0462-203-04141-L")

1062-20-0222

(Alias Part Numbers:

"ZPF000000000131953"

"1062-20-0222SAMPLE"

"1062-20-0222-SC"

"1062-20-0222-S")

1062-20-0277

1062-12-0144

(Alias Part Numbers:

"ZPF000000000131924")

1062-20-0144

(Alias Part Numbers:

"ZPF000000000131951"

"1062-20-0144-AS"

"1062-20-0144-LD"

"1062-20-0144-LS"

"1062-20-0144-MS"

"\$\$1062-20-0144"

"1062-20-0144-L"

"1062-20-0144-M"

"7-1899794-7")

5962-203-04141

4062-004-08141

4062-005-04141

1062-12-0244

1062-20-0177

0462-203-08141

(Alias Part Numbers:

"0462-203-08141-AS"

"0462-203-08141-LS"

"0462-203-08141-MS"

Product Affected

"0462-203-08141-L"

"0462-203-08141-M")

1062-20-0644

1062-12-0222

(Alias Part Numbers:

"ZPF000000000131922")

1062-12-0166

(Alias Part Numbers:

"ZPF000000000131926"

"1062-12-0166-LD"

"1062-12-0166-LS"

"1062-12-0166SAMPLE"

"1062-12-0166-L")

4062-003-08141

(Alias Part Numbers:

"4062-003-08141-MS"

"4062-003-08141-M")

1062-20-0122

(Alias Part Numbers:

"ZPF000000000131949"

"1062-20-0122-AS"

"1062-20-0122-LS"

"1062-20-0122-MS"

"1062-20-0122SAMPLE"

"1062-20-0122-SC"

"1062-20-0122-E"

"1062-20-0122-S"

"1062-20-0122-L"

"1062-20-0122-M")

1062-20-0622

1062-20-0244

(Alias Part Numbers:

"ZPF000000000131955")

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.