



19-Jul-2016

PCN #:P-16-013329

Subject:Faston terminals and sleeve assembly

Description of Change: Manufacturing location change. Following Part Numbers will be transferred from our Lickdale PA TE Connectivity manufacturing location to our Landisville PA TE Connectivity manufacturing location.

Reason: Dear Customer, as a result of our continuous strive for improving our processes, we hereby inform you about a transfer of tools and/or processes. The transfer is executed by following a strict transfer procedure, which guarantees no negative influence on quality, ability to supply and form-fit-function of the concerned products. The new manufacturing location is under a certified quality management system according the standard industry requirements. An internal release based on our specifications will be executed before any parts will be delivered, which guarantees the performance.

Impact of Change:Manufacturing location change

Key Dates:

Contact By Date:31-Jan-2017

Implementation Date:31-Jan-2017

Product Affected

24983-1

17435-3

27274-1

2-165565-1

17436-5

25218-1

640931-1

Product Affected

(Alias Part Numbers:

"A86505-000"

"AMPS-0-0640931-1")

21539-1

1958494-1

165670-1

640921-1

26570-1

61060-2

696419-2

27006-2

165688-1

640905-2

(Alias Part Numbers:

"402989057")

640915-2

27227-1

8-61060-1

42844-1

(Alias Part Numbers:

"AMP-0-0042844-1"

"D70990-000")

23300-1

21534-1

640905-1

(Alias Part Numbers:

"402647564"

"AMP-0-0640905-1"

"F94052-000")

640927-1

17383-3

341244

21541-1

640931-2

(Alias Part Numbers:

"1112285")

19074-1

21959-3

17820-2

640929-1

Product Affected

2-21959-0

20112-1

26731-1

640923-1

(Alias Part Numbers:
"AMPS-0-0640923-1"
"F61867-000")

640923-2

(Alias Part Numbers:
"1181513")

8-640917-0

27229-1

27006-1

696266-1

640929-2

26571-1

19371-1

21959-9

152821

696419-6

23305-5

19371-2

640907-2

(Alias Part Numbers:
"402989065"
"1140289"
"1139488")

21957-1

21958-9

8-640923-1

(Alias Part Numbers:
"AMPS-8-0640923-1"
"F77505-000")

184235-1

1958493-1

696265-1

165673-1

24982-1

184268-2

641321-2

Product Affected

(Alias Part Numbers:

"1141924")

8-696615-0

640927-2

640913-1

(Alias Part Numbers:

"AMPS-0-0640913-1"

"E76002-000")

23280-1

17820-3

640903-2

24984-1

24976-1

696419-3

640909-2

24871-1

24870-3

640919-2

8-696617-0

184262-1

21959-1

641324-2

(Alias Part Numbers:

"1120670"

"1201674")

165672-1

2-184268-2

8-640907-0

23280-4

184267-1

640906-1

(Alias Part Numbers:

"1098176")

696108-2

696108-1

21957-5

165669-1

640919-1

(Alias Part Numbers:

"AMPS-0-0640919-1"

Product Affected

"F11402-000")

640921-2

165665-2

696419-5

27623-1

17436-1

640913-2

55675-1

184261-1

640174-1

27655-2

42844-3

640911-1

(Alias Part Numbers:

"AMPS-0-0640911-1"

"E73410-000")

696419-1

26732-1

152823

696419-4

640910-1

21536-1

640918-1

8-696613-0

640911-2

60894-2

27230-1

23282-1

24869-1

17436-4

165667-1

8-640913-1

(Alias Part Numbers:

"AMPS-8-0640913-1"

"D84051-000")

640922-1

23281-1

24975-1

640916-1

21957-2

Product Affected

696018-2

184234-1

1958495-1

640925-2

640907-1

(Alias Part Numbers:

"AMPS-0-0640907-1"

"D54822-000"

"010-5590-00"

"4-16211-4031")

165667-2

640903-1

(Alias Part Numbers:

"AMP-0-0640903-1"

"E23464-000")

165671-1

184235-2

24985-1

17383-4

350871-1

55675-2

8-640903-0

640917-1

(Alias Part Numbers:

"AMPS-0-0640917-1"

"F55918-000")

640915-1

(Alias Part Numbers:

"AMPS-0-0640915-1"

"D47459-000")

640917-2

(Alias Part Numbers:

"405769969")

8-640905-0

61198-2

8-61048-1

21959-5

24868-1

61048-2

184268-1

Product Affected

640909-1

(Alias Part Numbers:

"579266-000"

"AMPS-0-0640909-1")

640904-1

24981-1

8-42844-1

696267-1

152825

3-21958-0

23305-1

1958496-1

27228-1

165668-1

184265-2

27013-1

42844-2

165665-1

184262-2

60544-3

24867-1

24977-1

21537-2

21958-1

1-21957-1

24870-4

23306-1

28832-1

2-165566-1

640925-1

(Alias Part Numbers:

"AMPS-0-0640925-1"

"F77142-000")

24870-1

27281-1

1958497-1

640902-1

17436-2

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.