



18-Aug-2016

PCN #:E-16-010976

Subject:0.5FH, performance based plating

Description of Change: change plating as performance based according to Spec 108-5560 instead of plating details. Detail information is changing gold flash on tail side to Tin plating.

Reason: Product Improvement. change plating as performance based according to Spec 108-5560 instead of plating details. Detail information is changing gold flash on tail side to Tin plating.

Impact of Change:form - fit - function

Key Dates:

Contact By Date:15-Feb-2017

Implementation Date:15-Feb-2017

Product Affected

1-5353206-0

6473379-1

1-5316560-0

5353189-7

1-5353906-0

1-5316077-0

3-6318490-6

1-5353190-0

1-5316560-1

8-5316136-0

1-5353190-1

1-5316077-1

5316077-3

Product Affected

8-5353189-0

6-6318157-1

6-5353606-6

5353190-8

1-5353729-0

1-5316136-0

3-5353606-7

3-1827231-6

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.