



13-Sep-2016
PCN #:P-16-013557

Subject:Flag_HDMI CONNECTOR

Description of Change: Plating on the solder tails changed for PN 2007435-*. Solder Tail Finish: Change from Gold flash over Nickel to Tin over Nickel. New Product Added: PN 2-2007435-1 (Extend the shell leg length, contact tail length, post length .)

Reason: Product improvement.For PN 2007435-* changed over to the original Tin over Nickel(The changes made by TE reason before for Gold flash over Nickel .Now TE Now TE has improved the process .So changed over to the original Tin over Nickel). For new product 2-2007435-1 offering at customer(Cisco) request.

Impact of Change:form - fit - function

Key Dates:

Contact By Date:31-Mar-2017

Implementation Date:31-Mar-2017

Product Affected

2007435-5
2007435-4
2007435-2
2-2007435-1
2007435-6
2007435-1
2007435-7
2007435-3

The dates on the product change notification (PCN) are best estimate dates

determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.