



22-Sep-2016

PCN #:P-16-013597

Subject:MTE HEADER ASSEMBLIES

Description of Change: Manufacturing location change. The die tooling that produces the stamped contact used in the following assembly Part Numbers will be transferred from our TE Manufacturing facility in Pennsylvania to our TE Manufacturing facility in Hermosillo, Mexico.

Reason: Dear Customer, we hereby inform you about a transfer of tools and/or processes. The transfer follows a strict procedure, which fully maintains quality, ability to supply and form-fit-function of the concerned products. The new manufacturing location operates under a certified quality management system in accordance with standard automotive requirements. A TE-internal release test based on the relevant part specifications will be executed before delivery. Upon request, a PPAP Level 2 will be available if it concerns a transfer of a tool which produces a finished TE-product. A PPAP Level 1 will be available if it concerns a component of a TE-product, where the production location of the finished TE-product remains unchanged. If you require such a PPAP, please notify the responsible TE Sales Contact within 14 calendar days after receipt of this PCN

Impact of Change:Manufacturing location change

Key Dates:

Contact By Date:23-Dec-2016

Implementation Date:23-Dec-2016

Product Affected

5-103669-9

3-103669-0

5-103639-5

5-103735-8

Product Affected

5-103669-4
5-104362-3
5-103735-4
5-104363-2
5-104363-5
5-103908-5
5-104362-2
5-104363-1
5-103669-2
5-104362-5
5-103669-7
5-103735-7
147060-1
5-103669-6
1-104450-0
5-103669-3
5-103908-3
5-104362-8
5-103735-9
5-104362-9
5-103639-1
5-104362-4
5-103908-8
5-103639-7
5-103908-7
2-103669-7
147969-4
5-103908-4
5-103639-3
2-103639-5
5-103908-2
5-103669-5
5-103735-5
1-104450-1
5-104362-6
5-103639-8
5-103669-8
5-104363-4

(Alias Part Numbers:
"2-42937-3652")

Product Affected

5-104362-7
5-103908-1
5-103908-6
5-104363-3
5-103735-3
5-103735-6
5-103639-2
5-103639-9
5-103908-9
5-104362-1
5-103735-1
5-103735-2
5-103639-4
1571796-2
5-103669-1
104363-4
104363-3
104363-2
104363-1
2-103670-3
2-103670-1
1-103670-9
1-103670-7
1-103670-5
1-103670-4
1-103670-2
104809-8
104809-7
104809-5
104809-3
104809-2
104809-1
104362-9
104362-7
104362-6
104362-5
104362-4
104362-3
104362-2
104362-1

Product Affected

1-103670-1

103670-9

103670-8

103670-7

103670-6

103670-5

103670-4

103670-3

(Alias Part Numbers:

"4-40001-6591")

103670-2

103670-1

103669-9

103669-8

103669-5

103669-4

103669-3

103669-2

103669-1

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.