



28-Sep-2016

PCN #:E-16-013723

Subject:USB 2.0 connector

Description of Change: change the material for USB 2.0 connector, from phosphor bronze to stainless steel This change is considered by TE Connectivity as a; . Location of change, see

Reason: Product Improvement. the lead time was so long for phosphor bronze, for the supply chain problems, we need to look for a new material ,replace the current material , the mechanical performance of stainless steel was better , and the lead time was acceptable,we had did some related test for the new material , it can pass the specification

Impact of Change:form - fit - function

Key Dates:

Contact By Date:31-Mar-2017

Implementation Date:31-Mar-2017

Product Affected

292303-6

1-292303-5

1-292303-8

1-292303-2

292303-3

1-292303-4

292336-1

5788336-2

5788336-1

292303-1

(Alias Part Numbers:

"CU5879-000"

Product Affected

"PER-292303-1")

292303-9

292336-2

1-292303-7

1-292303-3

5787834-2

292304-5

5787834-1

292303-4

292303-5

1932258-1

292304-3

292304-1

(Alias Part Numbers:

"C73502-000"

"PER-292304-1")

292303-2

292317-4

292304-4

1-292303-6

292304-2

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.