



03-Jan-2017

PCN #:P-17-014015

Subject:Product produced at TE Rock Hill, SC

Description of Change: TE Connectivity (TE) is moving manufacturing location of the products listed below from TE Rock Hill to TE Guangdong. Please contact your TE Sales Engineer with questions. The specific part numbers are detailed below.

Reason: After an extensive analysis of our TE business unit operations, we are announcing a plan to simplify our manufacturing footprint. As a result of this plan, product produced at our TE Rock Hill, SC OR Hermosillo, MX facilities will be relocated to other TE Connectivity locations (North America and China) by the end of November 2017. Additionally, we will relocate some product produced at our TE Dongguan China facility for our North American market to our Hermosillo, MX facility by the end of November 2017.

Impact of Change:Manufacturing location change

Key Dates:

Contact By Date:26-Jun-2017

Implementation Date:26-Jun-2017

Product Affected

4-552006-2

1-553483-2

7-554645-5

3-553484-2

4-552008-1

(Alias Part Numbers:

"4-27046-4675")

553588-3

Product Affected

3-554645-1

552006-1

552013-1

1-552007-1

554645-2

4-553484-4

552422-1

4-553484-3

552280-4

558892-1

1-553484-1

1116722-1

5229996-3

(Alias Part Numbers:

"1353453")

554333-1

554264-1

1-558693-1

(Alias Part Numbers:

"AMP-1-0558693-1"

"D07336-000"

"1085025")

554645-1

4-553484-2

553940-3

229910-4

552764-1

552006-4

554077-4

1-552010-5

569082-1

553940-7

554332-1

229902-5

4-554645-2

557574-2

569157-2

554059-3

553588-2

1-553800-3

Product Affected

229969-2

(Alias Part Numbers:

"420920-000"

"1191403"

"4-24036-0030")

2-553484-4

554294-1

553805-1

229993-1

7-554645-7

557567-2

1-552412-1

229969-4

(Alias Part Numbers:

"401554506"

"4-16211-7331")

554880-1

552495-4

229969-1

(Alias Part Numbers:

"822968-000"

"HUB-40283"

"1193320"

"4-16211-7311")

2-553484-3

552012-4

552764-2

554059-2

1-552078-1

7-554645-9

1-554644-1

557542-6

1-552010-1

4-554644-2

554293-1

553939-4

553919-7

553120-1

552412-1

552099-6

Product Affected

554262-2

552013-4

552009-4

2-229910-4

1-558693-2

2-552007-1

553918-9

7-553484-7

552962-3

7-554644-9

558045-1

5-553483-4

1-552027-1

(Alias Part Numbers:

"452852-000"

"HUB-21009"

"4-24134-0010")

554718-1

555010-1

2-552008-1

(Alias Part Numbers:

"1233995")

553939-7

3-554645-2

552422-4

2-554644-3

7-554644-5

229968-2

(Alias Part Numbers:

"1221537"

"4-24036-0140"

"1146793")

557058-1

553918-5

552009-5

553941-1

554077-3

229968-1

(Alias Part Numbers:

"900291444"

Product Affected

"221322-000"

"1162810"

"4-16211-7310")

1-552418-1

554491-2

1116720-2

552007-4

7-553483-5

553918-1

552012-1

4-554644-3

2-554245-5

4-554644-1

4-554645-1

554261-1

2-229910-1

(Alias Part Numbers:

"1162693"

"1193314"

"1156929")

553940-2

552009-1

553939-2

2-553800-3

552008-4

552011-1

(Alias Part Numbers:

"1162812")

229970-6

554679-2

554262-1

554679-1

558891-1

1116798-2

553940-1

5-554645-4

552101-2

4-553483-1

5-554645-3

558045-2

Product Affected

553919-1

553918-7

554492-2

1-554644-3

553901-2

554263-2

(Alias Part Numbers:

"CC6107-000"

"PER-554263-2")

1-552496-1

(Alias Part Numbers:

"CC1538-000"

"AMP-1-0552496-1"

"1390256"

"1205025")

553939-8

553588-1

553940-4

3-552008-1

(Alias Part Numbers:

"1080139"

"500-060-2303")

1-553484-4

552417-4

1295993

(Alias Part Numbers:

"552414-1")

3-552414-1

552495-1

8-554645-0

554680-1

555009-1

552078-1

2-554645-3

2-554245-7

554265-1

553919-2

4-554645-3

553622-1

4-553483-2

Product Affected

554333-2

552417-1

554255-2

1-552079-1

554335-3

5-554644-3

553919-5

557930-1

554332-4

4-553484-1

552760-2

552765-1

554644-2

555011-1

2-552496-1

(Alias Part Numbers:

"CC1539-000"

"AMP-2-0552496-1"

"1191312"

"4-27051-0283"

"500-060-3280"

"2-30100-0110")

554334-3

552077-1

552010-1

1-554645-3

1116722-3

1-553800-1

557542-2

5-554644-4

552760-1

2-553483-4

553919-6

3-554245-7

229971-6

2-553483-3

554335-5

554985-1

7-554645-6

554644-1

Product Affected

2-552077-1

553939-6

553939-3

3-554245-3

552278-4

7-553484-5

552731-1

(Alias Part Numbers:

"F00581-000"

"AMP-0-0552731-1"

"6428339500"

"1185352")

552414-1

(Alias Part Numbers:

"1362828")

1-552009-5

554255-1

569082-3

229910-1

(Alias Part Numbers:

"4-16211-7321"

"6428314400")

554263-1

1-554645-2

3-552422-1

554077-1

5-553483-3

554491-4

3-553483-1

557542-5

1-552011-1

(Alias Part Numbers:

"403421977"

"801286-000"

"HUB-16903")

554829-1

2-552006-1

553939-9

553588-4

1-554245-9

Product Affected

553941-2

554261-2

553940-8

7-554644-7

1-553939-1

1-554645-4

554335-2

552418-4

569083-3

554294-2

1-552009-1

1-552027-4

1-552494-1

554332-2

1-552296-1

(Alias Part Numbers:

"5W1271-000"

"4-24036-0190"

"6428336800")

7-553484-8

552496-1

(Alias Part Numbers:

"CA7203-000"

"AMP-0-0552496-1"

"500-020-2514"

"4-16211-7335")

552418-1

2-552079-1

3-552007-1

552421-4

554985-3

229969-3

(Alias Part Numbers:

"401562988"

"41902Y-000"

"1320751")

4-552007-1

569370-1

1-557542-0

2-552078-1

Product Affected

554985-4

557810-1

553918-2

1-552006-1

553919-9

5-553484-3

552927-1

554334-1

229909-1

(Alias Part Numbers:

"1162696"

"1193318"

"4-16211-7320")

2-554245-1

552765-2

4-554645-4

3-552421-1

552008-1

(Alias Part Numbers:

"E97943-000"

"AMP-0-0552008-1"

"4-16211-7367"

"4-27051-2334"

"500-020-2061"

"500-095-1116"

"6428318801")

7-554644-8

8-554644-0

552096-5

554679-3

569083-1

3-554644-1

554375-5

4-554644-4

2-554645-4

2-553800-1

4-552006-1

7-554644-6

554716-1

569157-1

Product Affected

2-552495-1

552010-4

1-552417-1

3-553483-2

553805-3

1-554644-2

1-552495-1

558045-5

552587-4

552494-1

555009-2

229904-5

1-554644-4

554391-1

552421-1

554492-4

3-552006-1

553941-4

4-554245-0

5-553484-4

553941-3

2-552494-1

552494-4

1116798-1

(Alias Part Numbers:

"AMP-0-1116798-1"

"F52941-000")

7-554645-8

558692-2

554717-1

1-553483-1

553939-1

553918-8

3-553484-1

552090-5

1-552298-1

(Alias Part Numbers:

"4-16211-7296")

229909-4

1-554645-1

Product Affected

557542-9

7-553484-6

552007-1

1-553484-2

1116720-1

(Alias Part Numbers:

"AMP-0-1116720-1"

"C27312-000")

4-553483-4

2-554245-9

1-552077-1

558871-3

1-552297-1

(Alias Part Numbers:

"5M255E-000"

"1262370")

3-554644-2

554636-1

552010-5

553805-2

229993-4

4-552007-2

2-554644-4

554830-1

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.