



17-Jan-2017

PCN #:P-17-014072

Subject:DEUTSCH CONNECTORS AND TERMINALS

Description of Change: Change of Part number of some itens ONLY FOR BRAZIL

Reason: Product improvement. Due a improvement of the process of reduction of MOQ (Minimum Order Quantity) as well as in attendance to the AEO (Authorized Economic Operator), we will effect the fractionation process of packaging of some items imported into TE Connectivity Brazil. For this new process some Part Numbers and NCM code (Mercosur Common Nomenclature) of products (ANNEX I) will be change. This amendment is necessary for the correct compliance with Brazilian legislation, given the way the national and international requirements of compliance. Therefore, we request the kindness to communicate these changes to all relevant areas of the your company, because it will be necessary to update to the new Part Numbers and NCM code in your system. The old Part Numbers can no longer be marketed. If the Part Numbers and NCM codes proposed are already in compliance with the registered by your company, the information present can be ignored.

Impact of Change:form - fit - function

Key Dates:

Contact By Date:24-Apr-2017

Implementation Date:24-Apr-2017

Product Affected

DT06-3S-EP06

(Alias Part Numbers:

"ZPF000000000130240"

"DT06-3S-EP06-LD"

Product Affected

"DT06-3S-EP06-LS"

"DT06-3S-EP06-MS"

"DT06-3S-EP06-L"

"DT06-3S-EP06-M")

1062-16-0144

(Alias Part Numbers:

"ZPF000000000131934"

"1062-16-0144-LS"

"1062-16-0144-SC"

"1062-16-0144-S"

"1062-16-0144-L")

DT06-4S-CE13

(Alias Part Numbers:

"ZPF000000000130312")

DT04-2P-RT01

(Alias Part Numbers:

"ZPF000000000130168"

"DT04-2P-RT01-LD"

"DT04-2P-RT01-MS"

"DT04-2P-RT01-L"

"DT04-2P-RT01-M")

DT04-3P-EP10

(Alias Part Numbers:

"ZPF000000000130215"

"DT04-3P-EP10-LD"

"DT04-3P-EP10-LS"

"DT04-3P-EP10-MS"

"DT04-3P-EP10-L"

"DT04-3P-EP10-M")

DT04-3P-CE03

(Alias Part Numbers:

"ZPF000000000130208")

DRB12-48PAE-L018

(Alias Part Numbers:

"ZPF000000000140760"

"DRB12-48PAE-L018-AS"

"DRB12-48PAE-L018-LD"

"DRB12-48PAE-L018-LS"

"DRB12-48PAE-L018-L"

"8-1899793-8"

Product Affected

"DRB12-48PAE-L018BR")

DRC26-60S05

(Alias Part Numbers:

"ZPF000000000131383"

"DRC26-60S05-LD"

"DRC26-60S05-LS"

"5-1899776-6"

"DRC26-60S05-L")

DRB16-48SAE-L018

(Alias Part Numbers:

"ZPF000000000140759"

"DRB16-48SAE-L018-AS"

"DRB16-48SAE-L018-LD"

"DRB16-48SAE-L018-LS"

"3-1899779-0"

"DRB16-48SAE-L018-L")

DT06-2S-EP06

(Alias Part Numbers:

"ZPF000000000130180"

"DT06-2S-EP06-LD"

"DT06-2S-EP06-LS"

"DT06-2S-EP06-MS"

"DT06-2S-EP06-E"

"DT06-2S-EP06-L"

"DT06-2S-EP06-M")

1060-16-0144

(Alias Part Numbers:

"ZPF000000000131903"

"1060-16-0144-LS"

"1060-16-0144-L")

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.