



07-Feb-2017

PCN #:E-16-015544

Subject:AMPMODU SYSTEM 50 DOUBLE ROW SHROUDED HEADER HOUSINGS AND ASSEMBLIES.

Description of Change: STANDARDIZATION OF REPLACEMENT TOOLING AS CURRENT TOOLS ARE WORN. 1. MATERIAL CHANGE FROM ZENITE LCP TO MORE READILY AVAILABLE AND TE PREFERRED SUMIKASUPER LCP.(SEE NOTE BELOW) 2. REMOVAL OF -Y- DATUM TARGET CALLOUTS AND ASSOCIATED DIMENSIONS FROM TOP VIEW OF DRAWING. 3. CHANGING LOCATION OF DATUM -Y- FROM THE OUTSIDE OF THE SHROUD TO THE INSIDE OF THE SHROUD TO BETTER AID IN INSPECTION. 4. CHANGE AMP LOGO TO TE LOGO. NOTE: MATERIAL CHANGE ON 147377, 1825601 AND 104549 SERIES IS CORRECTING THE DRAWING. DRAWING CALLS OUT PPA MATERIAL, BUT PART IS ACTUALLY MADE FROM LCP MATERIAL (SEE ITEM 1 ABOVE)

Reason: Product Improvement. STANDARDIZATION OF REPLACEMENT TOOLING AS CURRENT TOOLS ARE WORN. CHANGES BEING MADE DO NOT AFFECT FUNCTION OF PART. PARTS WILL FUNCTION THE SAME AS CURRENT PRODUCT DOES.

Impact of Change:form - fit - function

Key Dates:

Contact By Date:11-Aug-2017

Implementation Date:11-Aug-2017

Product Affected

104477-8

104477-6

5-104549-7

5-104068-2

Product Affected

5-104068-1
5-104076-5
5-104068-9
5-104666-4
5-147377-6
6-104549-0
5-104076-2
5-104076-1
6-104068-7
6-104069-3
5-104076-3
5-104068-6
5-104549-3
6-104068-2
5-147377-4
5-104069-2
5-104549-6
6-104068-0
5-147377-7
6-104068-5
5-104477-5
104666-7
6-104069-0
5-104666-1
6-104069-2
5-104069-6
5-147377-8
1825601-1
6-104068-4
5-104069-3
5-104549-9
5-147377-1
5-104666-3
6-104068-3
5-104477-4
6-104068-6
5-147377-9
6-104068-8
5-104076-7
5-104076-8

Product Affected

6-104549-1

5-104069-1

5-104477-6

5-104477-9

5-104549-8

5-104069-5

146397-1

(Alias Part Numbers:

"CV4742-000"

"AMP-0-0146397-1")

5-104549-5

6-104069-8

5-104666-2

5-104069-4

5-104666-5

5-104069-7

5-104068-5

5-104477-7

104666-6

6-104069-7

6-104069-4

5-147380-1

5-147377-3

5-104549-2

6-104477-2

6-104069-1

6-104666-1

5-147377-2

6-104666-0

6-104069-6

5-104068-4

5-104068-8

5-147377-5

5-104549-1

5-104477-2

5-104068-3

6-104068-1

6-104666-3

1-104666-1

147377-9

Product Affected

147377-8

147377-5

147377-4

147377-2

1-104549-0

104549-9

104549-8

104549-7

104549-6

104549-5

104549-3

104549-2

(Alias Part Numbers:

"1228905")

104549-1

(Alias Part Numbers:

"C77907-000"

"PER-104549-1")

104076-7

104076-5

104076-1

1-104069-8

1-104069-7

1-104069-6

1-104069-4

1-104069-3

104069-7

104069-6

104069-5

(Alias Part Numbers:

"D82896-000"

"PER-0-010469-5")

104069-4

104069-3

104069-2

104069-1

1-104068-7

1-104068-6

1-104068-4

1-104068-3

Product Affected

1-104068-2

1-104068-1

104068-9

104068-8

104068-6

104068-5

104068-4

104068-3

104068-2

104068-1

104864-1

104666-4

104666-3

104666-2

104477-9

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.