



05-May-2017

PCN #:P-17-014366

Subject:Mini Universal Mate-N-Lok

Description of Change: Manufacturing location change. Following Part Numbers will be manufactured in both locations. Mexico and TE Lickdale USA. Additional Assembly Machine added that can produce part numbers the same. Refer to PCN P-17-014294.

Reason: Dear Customer, as a result of our continuous strive for improving our processes, we hereby inform you about a additional location of tools and processes. The addition is executed by following a strict start-up procedure, which guarantees no negative influence on quality, ability to supply and form-fit-function of the concerned products. The new manufacturing location is under a certified quality management system according the standard industry requirements. An internal release based on our specifications will be executed before any parts will be delivered, which guarantees the performance.

Impact of Change:Manufacturing location change

Key Dates:

Contact By Date:01-Jun-2017

Implementation Date:01-Jun-2017

Product Affected

1-794069-1

1586609-1

1-794108-1

1-770186-1

794396-3

1-770972-1

1-770743-1

Product Affected

1-770968-1
1-794076-1
1-794071-1
1-794108-0
1-770190-1
1-770182-1
1-770971-1
1586613-1
1-794074-0
1-794077-0
1-770876-1
1-770743-0
1-770972-0
1-770873-1
1586600-1
1-794066-1
1-770186-0
1-770973-1
1586610-1
1-794072-1
1-794076-0
1-794070-1
1586599-1
1-770967-1
1-794070-0
1586608-1
1-794079-1
1-794374-1
1-770873-0
1761364-2
1586016-1
1-770178-0
1-770966-0
1-770966-1
1-794072-0
1-794067-1
1-770969-1
1-770974-1
1-770974-0
1-770621-1

Product Affected

1-794106-0
1-770969-0
1-794075-0
1-794067-0
1-794078-0
1-770876-0
1-794069-0
1-770968-0
1-794040-0
1-770971-0
1-794071-0
1-794079-0
1-794077-1
1-794107-1
1-794068-1
1-770967-0
1-770970-0
1-770858-0
2-794107-0
1-794105-1
1-794075-1
1586614-1
1-770970-1
1-794040-1
1586612-1
1-770858-1
1586611-1
1-770170-0
1-794105-0
1-770182-0
1-770859-0
1-770170-1
1-794107-0
1-770973-0
1954153-1
1-794068-0
1-794066-0
1-770621-0
1-770190-0
1-794078-1

Product Affected

1-794106-1

1-770859-1

1586748-1

794374-2

770858-1

770743-2

770743-1

770621-1

794107-1

794105-1

794077-2

794077-1

794076-2

794075-2

794074-1

794072-1

794071-1

794070-2

794069-2

794069-1

794068-2

794068-1

794067-2

794066-2

794066-1

794040-2

770974-2

770974-1

770973-2

770973-1

770972-2

770972-1

770971-1

770970-2

770970-1

770969-2

770969-1

770968-2

770968-1

770967-2

Product Affected

770967-1

(Alias Part Numbers:

"2-42939-5963")

770966-2

770966-1

(Alias Part Numbers:

"2-42939-5962")

770876-2

770876-1

770873-2

(Alias Part Numbers:

"407759927")

770873-1

770859-2

770190-1

770186-2

770186-1

770182-2

770182-1

770170-2

770170-1

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.