



Product Change Notification

Current Date: 30-Jun-2017

TE Connectivity

Product Change Notification: P-17-014546

PCN Date: 28-JUN-17

Customer: TTI Inc(0000139702)

Location: WORLDWIDE

Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

AMP MCP1.5K FLATTYPE RECEPTACLE

Description of Changes

For China local customer requirement on localization on AMP MCP1.5K FLATTYPE RECEPTACLE, New duplication production tool 11-1209324 transfer from TE Germany wort to TE Suzhou plant for production to support China marker,this duplication die involve below part numbers 1241380-1&1564324-1,for this production location change, it will shorten the L/T of delivery time and offer good service in China.

Other attachments:

[Explanation for Production Location change for AMP MCP1.5K FLATTYPE RECEPTACLE](#)

Reason for Changes:

Dear customer. we would like to infor you with this PCN about introducing a new duplication prduction tool at our TE manufacturing location in Suzhou.China. The evaluation of new tool is executed by following A strict procedure.which guarantees no negative influence on quality , ability to supply and form-fit-funtion of the concerned products. Manufacturing location is under a certified quality magement system according the standard auto motomotive requirements. An internal release based on our specifications

1241380-1	NO						
---------------------------	----	--	--	--	--	--	--

Customer: TTI Inc(168830)

Location: Fort Worth

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1241380-1	NO						

Customer: TTI Inc.(3057778)

Location: Olching

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1241380-1	NO		TYC1241380-1				

Customer: TTI(556264)

Location: Fort Worth


Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1241380-1	NO						

Explanation for Production Location Change for AMP MCP1.5K FLATTYPE RECEPTACLE (P/N:1241380-1/1564324-1/1241374-1/1564980-1/1534334-1)

1. For China local customer requirement on localization AMP MCP1.5K FLATTYPE RECEPTACLE, new duplication production tool transfer to TE Suzhou plant for production to support only China market. For this production location change, it will shorten the L/T of delivery time and offer good service in China.
2. The identification of Suzhou production part is that there is “T275” marked on the part as below:



Explanation for Production Location Change for AMP MCP1.5K FLATTYPE RECEPTACLE (P/N:1241380-1/1564324-1/1241374-1/1564980-1/1534334-1)

1. For China local customer requirement on localization AMP MCP1.5K FLATTYPE RECEPTACLE, new duplication production tool transfer to TE Suzhou plant for production to support only China market. For this production location change, it will shorten the L/T of delivery time and offer good service in China.
2. The identification of Suzhou production part is that there is “T275” marked on the part as below:

