



19-Jul-2017

PCN #:P-17-014640

Subject:HVA280 2phi Cap Assembly

Description of Change: The pigment for the Orange colorant in the molded plastic housings is being replaced by an equivalent substitute product. This replacement colorant formulation has completed TE validation testing. Both the current and replacement orange colorants meet the RAL2008 color code standard. There is no impact to the FFF of the listed end assembly/customer part numbers. Dimensionally, physically and functionally the parts will be the same as current product. There will be no change to the part numbers or revision. TEC will track the changeover internally on the manufacturing print at the component level, and will implement as a running change.

Reason: Product improvement. The supplier for the orange pigment has discontinued manufacture due to commercial reasons.

Impact of Change:form - fit - function

Key Dates:

Contact By Date:01-Nov-2017

Implementation Date:01-Nov-2017

Product Affected

2103352-2

2103191-4

2103013-1

1-2103172-1

2103534-1

2103247-2

1-2103396-5

2103177-1

2103396-1

Product Affected

5-2103177-4
1-2103247-5
1587987-8
2103172-9
1-1587987-1
2103191-1
2103191-2
2103168-1
2103352-5
2103352-4
2-2103212-7
4-2103350-2
2103744-4
2103247-1
1-2103177-4
2103177-6
4-2103587-5
2103022-1
1-2103172-8
2103245-1
2103245-5
2103172-8
1-2103234-2
1-2103275-1
1-2103177-5
2103752-2
1-2103396-1
2103396-5
1-2103124-5
2103177-2
4-2103177-5
2103346-2
2-2103172-7
2103245-6
1-2103343-1
2103321-4
2103744-2
2103181-2
1-2103177-6
1-2103275-2

Product Affected

2103385-4
4-2103015-5
2103581-5
2103177-5
5-2103177-5
4-2103587-1
1-2103278-1
1-2103124-7
2103743-2
1-1587987-7
4-2840548-1
1-2103396-4
2103247-6
1-2103212-8
1-1587987-4
2103168-3
1-1587987-5
2103744-1
1-2103212-9
1-2103396-2
2103748-2
4-2103177-1
2103321-5
2103346-1
2103212-9
2840543-1
2103352-1
2103124-5
1-2103124-1
1-2103247-1
2103013-3
1-2103247-2
2103534-6
2103247-4
4-2103177-6
4-2103015-1
2103177-4
2103020-1
4-2840548-2
1-2103212-1

Product Affected

2-2103172-9
2-2103172-8
2-2103172-2
2103343-1
2103169-6
2103534-5
2-2103212-1
2103581-1
5-2103177-6
2103396-6
2103191-6
1-2103214-2
2103628-5
1-2103124-2
1-2103247-4
2103741-2
2103245-2
2840543-2
2103396-4
2103169-4
2103744-6
1587940-2
5-2103177-1
1-2103172-9
2103321-1
1-2103172-7
1-2103212-2
2103321-2
1-2103177-2
2103396-2
2103073-1
2103212-8
2103155-1
2103581-4
2103245-4
2103169-1
2103070-1
2103169-2
1587987-9
5-2103177-2

Product Affected

1-2103124-4
2103628-2
2103744-5
2103744-9
2103234-2
2103744-7
4-2103350-1
2103534-2
2103534-4
4-2103177-7
4-2103350-5
1-2103343-5
2103124-4
2-2103212-2
4-2103015-2
4-2103587-4
2-2103278-2
4-2103177-4
1-2103396-6
4-2103177-2
2103158-6
2103736-2
4-2103015-6
4-2103015-4
1-2103212-7
2103124-1
2103742-2
2103321-6
1-2103172-2
2103340-1
2103628-7
2103343-5
2103191-5
5-2103177-7
2103124-2
2103124-6
1-2103247-6
2-2103214-2
1-1587987-3
2103628-1

Product Affected

1-2103124-6

4-2103350-4

2103124-7

2103158-8

1-2103177-1

2103628-4

2103581-2

2840410-1

1-2103214-1

2103628-6

2103169-5

4-2103587-2

2103247-5

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.