



04-Oct-2017

PCN #:P-17-014909

Subject:Selected Straight Code 40 TINEL-LOCK Adapters (TXR40AB00 and TXRAC00)

Description of Change: Additional manufacturing location for circular connector accessories products to establish additional capacity.

Reason: Dear Customer, we hereby inform you that we are establishing an additional manufacturing locations, within existing TE Connectivity facilities, to improve customer service and reduce lead-time. The alternative manufacturing locations fully maintains quality, ability to supply and form-fit-function of the concern products. This manufacturing location operates under a certified quality management system in accordance with standard industry requirements.

Impact of Change:Manufacturing location change

Key Dates:

Contact By Date:01-Dec-2017

Implementation Date:01-Dec-2017

Product Affected

629267-000

(Alias Part Numbers:

"2-1194981-0"

"TXR40AB00-1608AI")

554173-000

(Alias Part Numbers:

"5-1194375-5"

"TXR40AB00-1406AI")

822313-000

(Alias Part Numbers:

Product Affected

"9-1196412-6"

"TXR40AB00-1005BI")

723915-000

(Alias Part Numbers:

"2-1195659-3"

"TX40AB00-1205")

817388-000

(Alias Part Numbers:

"3-1200164-5"

"TX40AC00-1205")

799695-000

(Alias Part Numbers:

"7-1196182-8"

"TXR40AC00-1408AI")

116025-000

(Alias Part Numbers:

"2-1190845-5"

"TXR40AB00-1206BI")

174283-000

(Alias Part Numbers:

"5-1191267-8"

"TX40AB00-1608")

489737-000

(Alias Part Numbers:

"7-1193663-4"

"TX40AB00-1612")

461473-000

(Alias Part Numbers:

"5-1193461-6"

"TXR40AB00-1406BI")

006069-000

(Alias Part Numbers:

"5-1190046-4"

"TX40AB00-1006")

404659-000

(Alias Part Numbers:

"2-1193054-7"

"TXR40AC00-1406BI")

701373-000

(Alias Part Numbers:

Product Affected

"2-1195504-8"

"TXR40AB00-1207BI")

776553-000

(Alias Part Numbers:

"9-1196045-2"

"TXR40AB00-1207AI")

380615-000

(Alias Part Numbers:

"2-1192846-1"

"TXR40AC00-0804BI")

121571-000

(Alias Part Numbers:

"9-1190884-5"

"TXR40AB00-1610AI")

836025-000

(Alias Part Numbers:

"3-1196526-2"

"TX40AC00-0804")

472755-000

(Alias Part Numbers:

"8-1193541-5"

"TXR40AC00-1006BI")

182113-000

(Alias Part Numbers:

"4-1191323-9"

"TXR40AC00-1206AI")

254505-000

(Alias Part Numbers:

"1-1191863-8"

"TX40AC00-1208")

950899-000

(Alias Part Numbers:

"7-1197353-1"

"TX40AC00-1608")

644183-000

(Alias Part Numbers:

"8-1195088-8"

"TX40AC00-1206")

919073-000

(Alias Part Numbers:

Product Affected

"3-1197132-7"

"TXR40AC00-1004AI")

903797-000

(Alias Part Numbers:

"5-1197023-3"

"TX40AC00-2012")

234305-000

(Alias Part Numbers:

"2-1191721-9"

"TX40AB00-1406")

347169-000

(Alias Part Numbers:

"1192613-1"

"TXR40AB00-1205BI")

858024-000

(Alias Part Numbers:

"7-1201049-6"

"TXR40AA00-1006AI")

520728-000

(Alias Part Numbers:

"5-1200165-8"

"TX40AC00-1207")

880407-000

(Alias Part Numbers:

"4-1196854-8"

"TX40AC00-1408")

990207-000

(Alias Part Numbers:

"1-1197657-1"

"TXR40AB00-1408BI")

169269-000

(Alias Part Numbers:

"3-1191232-0"

"TXR40AB00-1407AI")

259725-000

(Alias Part Numbers:

"1-1191900-4"

"TXR40AB00-2012BI")

886065-000

(Alias Part Numbers:

Product Affected

"4-1196894-2"

"TXR40AB00-1005AI")

833129-000

(Alias Part Numbers:

"1-1196505-3"

"TX40AC00-1610")

D90475-000

(Alias Part Numbers:

"8-1200168-0"

"TX40AC00-1407")

093385-000

(Alias Part Numbers:

"1-1190685-0"

"TXR40AB00-1612BI")

552451-000

(Alias Part Numbers:

"6-1194366-3"

"TXR40AC00-1406AI")

664529-000

(Alias Part Numbers:

"5-1195236-1"

"TXR40AB00-1206AI")

384025-000

(Alias Part Numbers:

"4-1192880-9"

"TXR40AC00-1206BI")

255295-000

(Alias Part Numbers:

"1191869-4"

"TX40AB00-1207")

260027-000

(Alias Part Numbers:

"5-1191902-4"

"TX40AB00-1007")

596399-000

(Alias Part Numbers:

"3-1194717-2"

"TX40AC00-1006")

820593-000

(Alias Part Numbers:

Product Affected

"3-1196398-9"

"TXR40AB00-2012AI")

417922-000

(Alias Part Numbers:

"1198096-7"

"TXR40AA00-1408AI")

102789-000

(Alias Part Numbers:

"2-1190752-7"

"TX40AB00-1206")

317377-000

(Alias Part Numbers:

"6-1192404-1"

"TXR40AC00-1408BI")

106443-000

(Alias Part Numbers:

"6-1190777-4"

"TXR40AB00-1408AI")

778005-000

(Alias Part Numbers:

"9-1196055-5"

"TXR40AB00-1205AI")

031839-000

(Alias Part Numbers:

"9-1190246-1"

"TXR40AB00-1004BI")

680789-000

(Alias Part Numbers:

"5-1195354-3"

"TXR40AC00-1208AI")

850845-000

(Alias Part Numbers:

"7-1196633-8"

"TXR40AB00-1610BI")

913885-000

(Alias Part Numbers:

"8-1197095-4"

"TXR40AB00-1812AI")

193679-000

(Alias Part Numbers:

Product Affected

"4-1191405-4"

"TXR40AC00-1407BI")

CZ2450-000

(Alias Part Numbers:

"TX40AA00-1408")

423509-000

(Alias Part Numbers:

"2-1193189-8"

"TXR40AB00-1608BI")

161565-000

(Alias Part Numbers:

"5-1191166-7"

"TXR40AC00-1205AI")

658819-000

(Alias Part Numbers:

"9-1195193-4"

"TXR40AB00-1006AI")

002801-000

(Alias Part Numbers:

"6-1190021-3"

"TXR40AC00-0804AI")

489063-000

(Alias Part Numbers:

"2-1193659-7"

"TXR40AC00-1007AI")

398665-000

(Alias Part Numbers:

"5-1192989-1"

"TX40AB00-0804")

610299-000

(Alias Part Numbers:

"8-1194825-9"

"TX40AC00-1406")

931313-000

(Alias Part Numbers:

"1197219-2"

"TXR40AA00-1410AI")

373419-000

(Alias Part Numbers:

"1192797-9"

Product Affected

"TXR40AC00-1208BI")

726974-000

(Alias Part Numbers:

"8-1195681-7"

"TXR40AB00-1004AI")

019147-000

(Alias Part Numbers:

"6-1190149-1"

"TXR40AB00-1007AI")

181065-000

(Alias Part Numbers:

"8-1191315-0"

"TX40AB00-1407")

918713-000

(Alias Part Numbers:

"9-1197129-5"

"TXR40AC00-1005AI")

142565-000

(Alias Part Numbers:

"1-1191032-9"

"TX40AB00-1208")

293973-000

(Alias Part Numbers:

"7-1192227-3"

"TXR40AB00-1612AI")

E80544-000

(Alias Part Numbers:

"1200169-6"

"TX40AC00-1005")

535465-000

(Alias Part Numbers:

"2-1194204-4"

"TXR40AC00-1407AI")

150461-000

(Alias Part Numbers:

"9-1191087-1"

"TX40AB00-1408")

091659-000

(Alias Part Numbers:

"9-1190671-4"

Product Affected

"TXR40AB00-1407BI")

921653-000

(Alias Part Numbers:

"1197151-4"

"TXR40AB00-1006BI")

627933-000

(Alias Part Numbers:

"8-1194971-4"

"TXR40AC00-1207AI")

227744-000

(Alias Part Numbers:

"2-1199123-9"

"TX40AC00-1004")

259057-000

(Alias Part Numbers:

"3-1191895-6"

"TX40AC00-1410")

458497-000

(Alias Part Numbers:

"7-1193439-7"

"TXR40AB00-1410BI")

043287-000

(Alias Part Numbers:

"3-1190332-9"

"TXR40AC00-1004BI")

146995-000

(Alias Part Numbers:

"3-1191062-0"

"TXR40AB00-1410AI")

990779-000

(Alias Part Numbers:

"1197661-6"

"TX40AB00-1410")

117085-000

(Alias Part Numbers:

"7-1190852-9"

"TXR40AC00-1205BI")

902967-000

(Alias Part Numbers:

"3-1197017-4"

Product Affected

"TXR40AC00-1007BI")

690189-000

(Alias Part Numbers:

"8-1195419-0"

"TXR40AC00-1006AI")

004519-000

(Alias Part Numbers:

"5-1190034-5"

"TX40AC00-1007")

765249-000

(Alias Part Numbers:

"4-1195957-8"

"TX40AB00-1004")

978405-000

(Alias Part Numbers:

"2-1197559-3"

"TX40AB00-1005")

691787-000

(Alias Part Numbers:

"3-1195431-4"

"TX40AC00-1612")

423209-000

(Alias Part Numbers:

"1193187-1"

"TXR40AB00-0804AI")

807363-000

(Alias Part Numbers:

"2-1196255-3"

"TXR40AB00-1812BI")

861365-000

(Alias Part Numbers:

"5-1196710-6"

"TX40AB00-1610")

038625-000

(Alias Part Numbers:

"7-1190296-4"

"TXR40AB00-1208BI")

415115-000

(Alias Part Numbers:

"8-1193128-1"

Product Affected

"TXR40AB00-0804BI")

364505-000

(Alias Part Numbers:

"6-1192733-2"

"TX40AB00-2012")

497361-000

(Alias Part Numbers:

"7-1193718-5"

"TXR40AB00-1208AI")

675889-000

(Alias Part Numbers:

"1-1195315-0"

"TX40AB00-1812")

941793-000

(Alias Part Numbers:

"1-1197292-9"

"TXR40AB00-1007BI")

330651-000

(Alias Part Numbers:

"2-1192498-1"

"TXR40AC00-1207BI")

835795-000

(Alias Part Numbers:

"7-1196524-6"

"TX40AC00-1812")

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.