



09-Jan-2018

PCN #:P-18-015298

Subject:Mfg Location Change - FLHT Product move from Redwood City, CA USA to Swindon, UK

Description of Change: Dear This is a formal advisory of relocation activities for the following part numbers outlined in this notification. The transfer is executed by following a strict transfer procedure, which guarantees no impact to quality and ability to deliver on time. Our existing TE UK Swindon facility has served as the cornerstone for manufacturing for high performance wire and cable products for more than 30 years and will ensure continued customer service and product excellence. The new manufacturing location is under a certified quality management system according to the ISO 9001, AS-9100 and ISO/TS 16949 quality standards. An internal release based on our specifications will be executed before any parts will be delivered, which guarantees the performance. UL Subject 758 Style 3557 File Number E38136 (UK Mfg) File Number E303150 (US Mfg)

Reason: .

Impact of Change:Manufacturing location change

Key Dates:

Contact By Date:10-Jan-2018

Implementation Date:10-Jan-2018

Product Affected

401325-000

(Alias Part Numbers:

"3-1193030-6"

"FLHTC0311-14-2")

669149-000

(Alias Part Numbers:

Product Affected

"8-1195268-2"

"FLHTC0311-16-2")

106857-000

(Alias Part Numbers:

"4-1190780-7"

"FLHTC0311-20-9"

"FLHTC0311-20-9")

108917-000

(Alias Part Numbers:

"6-1190795-7"

"FLHTC0311-16-6")

487075-000

(Alias Part Numbers:

"8-1193644-1"

"FLHTC0311-14-0")

659306-000

(Alias Part Numbers:

"7-1199190-1"

"FLHTC0311-16-3")

239094-000

(Alias Part Numbers:

"1-1199190-9"

"FLHTC0311-16-7")

328224-000

(Alias Part Numbers:

"FLHTC0311-16-5")

290051-000

(Alias Part Numbers:

"1192199-4"

"FLHTC0311-14-6")

169965-000

(Alias Part Numbers:

"1191237-7"

"FLHTC0311-14-1")

037454-000

(Alias Part Numbers:

"8-1199189-1"

"FLHTC0311-20-1")

435829-000

(Alias Part Numbers:

Product Affected

"6-1193276-6"

"FLHTC0311-16-0")

098088-000

(Alias Part Numbers:

"8-1199155-7"

"FLHTC0311-16-9-1KF")

211123-000

(Alias Part Numbers:

"6-1191529-3"

"FLHTC0311-14-9")

735837-000

(Alias Part Numbers:

"5-1195746-2"

"FLHTC0311-14-7")

563107-000

(Alias Part Numbers:

"9-1194448-6"

"FLHTC0311-14-5")

212543-000

(Alias Part Numbers:

"8-1191537-7"

"FLHTC0311-20-4")

144469-000

(Alias Part Numbers:

"1-1191044-0"

"FLHTC0311-16-9"

"FLHTC0311-16-9")

612077-000

(Alias Part Numbers:

"6-1194839-0"

"FLHTC0311-20-5")

173925-000

(Alias Part Numbers:

"1-1191265-3"

"FLHTC0311-20-0")

192416-000

(Alias Part Numbers:

"1-1199156-2"

"FLHTC0311-20-9-1KF")

298461-000

Product Affected

(Alias Part Numbers:

"1192260-1"

"FLHTC0311-20-2"

"FLHTC0311-20-2")

determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.