

12-Jan-2018 **PCN #:**E-18-000038

Subject:B-040-22-N (005299-000), B-040-24-N (120411-000), B-040-26-N (089827-000), B-040-30-N (443631-000)

Description of Change: INNER SLEEVE ID IS: 3.3 DIA MIN, SB: 2.97 DIA MIN. . Location of change, SEE ECR.

Reason: Product Improvement. MANUFACTURING IS NOT ABLE TO ACHIEVE THIS DIMENSION. SMALLER MIN DIAMETER DOES NOT VIOLATE THE CD.

Impact of Change: form - fit - function

Key Dates: Contact By Date:02-Feb-2018 Implementation Date:02-Feb-2018

Product Affected 292151-000 (Alias Part Numbers: "9-1192214-3" "B-040-28-N") 443631-000 (Alias Part Numbers: "2-1193334-9" "B-040-30-N") 120411-000 (Alias Part Numbers: "9-1190875-3" "B-040-24-N") 005299-000

Product Affected

(Alias Part Numbers: "4-1190040-6" "B-040-22-N" "B-040-22-N") 089827-000 (Alias Part Numbers: "9-1190658-6" "B-040-26-N") 440727-000 (Alias Part Numbers: "8-1193313-3" "B-040-20-N") 696113-000 (Alias Part Numbers: "8-1195460-1" "B-040-25-01") EH8950-000 (Alias Part Numbers: "B-040-22-N-CS4118") The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.