



05-Jun-2018

PCN #:E-18-008215

Subject:1.USB 4P VERTICAL TYPE B RECEPTACLE CONN 2.SHELL, RECEPTACLE, 4 POSN, VERTICAL, TYPE B, UNIVERSAL SERIAL BUS

Description of Change: modification for the shell spring design

Reason: Product Improvement. [1.We](#) received complaints from our customers that the extraction force of the product was too large. The spring clips of the connector were pulled out. The main reason was that after we replaced the shell material from copper alloy to stainless steel, the spring fillet could not reach the level as before. [2.We](#) change the spring design, which can make the fillet corner larger, and can accommodate plugs' difference. [3.we](#) had finished the durability test,the result can meet the specification.

Impact of Change:form - fit - function

Key Dates:

Contact By Date:08-Jun-2018

Implementation Date:08-Jun-2018

Product Affected

5788336-2

5788336-1

5787834-2

5787834-1

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.