



23-Oct-2018

PCN #:E-18-016714

Subject:DEUTSCH Products - Distribution Center change from WCDC, Ontario, CA (USA) to HLDC, Hermosillo, Senora (MX)

Description of Change: THERE IS NO CHANGE TO MANUFACTURING LOCATION OR TO PARTS. Due to consolidation of Distribution Centers (DC), TE-ICT is moving the material from our Ontario, CA (USA) DC to our Hermosillo, Sonora, (Mexico) DC. The transition to Hermosillo, MX will take place during the weekend of October 27, 2018. All products you currently receive from our Ontario, CA (USA) location will be transitioned to the new Distribution Center by Monday, October 29, 2018. Here is current and new DC address and DUNS Code information. Current DC address is 1643 S. Parco Ave. Ontario CA 91761, Current DUNS Code is 040750247, New DC address is Corcom S.A. de C.V., Tyco Electronics Corporation Blvd. Industrial Norte No. 23 Hermosillo, Sonora, Mexico 83118, New DUNS Code is 812819636

Reason: Consolidation of distribution centers.

Key Dates:

Contact By Date:29-Oct-2018

Implementation Date:29-Oct-2018

Product Affected

DT04-2P-E004

DRB12-128PANE-L018

(Alias Part Numbers:

"ZPF000000000146197"

"9-1899776-3")

HDP26-18-14SE

(Alias Part Numbers:

"ZPF000000000130758"

Product Affected

"HDP26-18-14SE-AS"

"HDP26-18-14SE-LS"

"HDP26-18-14SE-MS"

"HDP26-18-14SE-SC"

"HDP26-18-14SE-L"

"HDP26-18-14SE-M"

"HDP26-18-14SE-S")

DTM04-4P

(Alias Part Numbers:

"ZPF000000000130263"

"DTM04-4P-LS"

"DTM04-4P-L"

"8202609556"

"MSE04832")

DT06-3S-P012

DTM04-4P-E004

(Alias Part Numbers:

"ZPF000000000130265")

HD10-9-1939PE-B022

(Alias Part Numbers:

"5-1899820-7")

1557506-1

DT16-18SB-K004

DRC26-50S05

(Alias Part Numbers:

"ZPF000000000131367"

"DRC26-50S05-AS")

HD34-24-21SE-059

(Alias Part Numbers:

"ZPF000000000130973")

DT04-12PB-BL04

HDP26-24-31SE-L015

(Alias Part Numbers:

"ZPF000000000131156"

"HDP26-24-31SE-L015LS"

"6-1899768-0"

"HDP26-24-31SE-L015-L")

YHDP24-24-47PEL024

(Alias Part Numbers:

"HDP24-24-47PE-L024")

Product Affected

YHDP26-24-9SE-L024

(Alias Part Numbers:
"HDP26-24-9SE-L024")

DTM06-2S-P006

(Alias Part Numbers:
"ZPF000000000130146"
"DTM06-2S-P006-LS"
"DTM06-2S-P006-L")

WB-48PA

(Alias Part Numbers:
"ZPF000000000131488"
"WB-48PA-AS"
"WB-48PA-LD"
"WB-48PA-L")

HDP26-24-16PE-L017

(Alias Part Numbers:
"ZPF000000000130809")

1557507-1

DT06-2S-CE06

(Alias Part Numbers:
"ZPF000000000140939"
"820P-37546")

HDP24-18-14PE

(Alias Part Numbers:
"ZPF000000000130750"
"HDP24-18-14PE-MS"
"HDP24-18-14PE-M")

WB-51PAL

(Alias Part Numbers:
"ZPF000000000131504"
"WB-51PAL-LD"
"WB-51PAL-LS"
"WB-51PAL-L")

HDP26-18-14SE-L017

(Alias Part Numbers:
"ZPF000000000130759"
"3-1899772-9")

DTM04-08PA

(Alias Part Numbers:
"ZPF000000000130392")

Product Affected

"DTM04-08PA-LD"

"DTM04-08PA-LS"

"DTM04-08PA-E"

"DTM04-08PA-L")

DT16-15SA-K003

HDP26-24-31SE-L017

(Alias Part Numbers:

"ZPF000000000131157"

"HDP26-24-31SE-L017AS"

"HDP26-24-31SE-L017LS"

"8-1899770-3")

HD16-5-16S

(Alias Part Numbers:

"ZPF000000000130332")

DRBF-2B

(Alias Part Numbers:

"ZPF000000000131752")

YHDP24-24-31PEL024

(Alias Part Numbers:

"HDP24-24-31PE-L024")

DT06-2S

DTM06-12SA

(Alias Part Numbers:

"ZPF000000000130575"

"DTM06-12SA-LS"

"DTM06-12SA-SC"

"DTM06-12SA-E"

"DTM06-12SA-L"

"DTM06-12SA-S")

HDC36-24

(Alias Part Numbers:

"ZPF000000000131726")

HD16-9-96S

(Alias Part Numbers:

"ZPF000000000130545")

HD10-9-1939P-B022

(Alias Part Numbers:

"8-1899770-9"

"HD10-9-1939P-B022-E")

DRB16-102SAE-L018

Product Affected

(Alias Part Numbers:

"ZPF000000000138177"
"DRB16-102SAE-L018-LD"
"DRB16-102SAE-L018-LS"
"DRB16-102SAE-L018-MS"
"3-1899772-4"
"DRB16-102SAE-L018-E"
"DRB16-102SAE-L018-L"
"DRB16-102SAE-L018-M")

HD36-18-14SE

(Alias Part Numbers:

"ZPF000000000130783"
"\$HD36-18-14SE")

DRB16-128SAE-L018

(Alias Part Numbers:

"ZPF000000000145698"
"DRB16-128SAE-L018-LS"
"8-1899773-9"
"DRB16-128SAE-L018-L")

WB-48SA

(Alias Part Numbers:

"ZPF000000000131492"
"WB-48SA-AS"
"WB-48SA-LD"
"WB-48SA-L")

DRB16-48SAE-L018

(Alias Part Numbers:

"ZPF000000000140759"
"DRB16-48SAE-L018-AS"
"DRB16-48SAE-L018-LD"
"DRB16-48SAE-L018-LS"
"3-1899779-0"
"DRB16-48SAE-L018-L")

DT04-2P

(Alias Part Numbers:

"8202612040")

DT04-3P-P006

HD16-3-96S

(Alias Part Numbers:

"ZPF000000000130257"

Product Affected

"HD16-3-96S-MS"

"HD16-3-96S-M")

DTM06-3S

(Alias Part Numbers:

"ZPF000000000130202"

"DTM06-3S-LS"

"DTM06-3S-L"

"8202609699"

"8202612555")

YHDP26-24-18SEL024

(Alias Part Numbers:

"HDP26-24-18SE-L024")

WB-51SAR

(Alias Part Numbers:

"ZPF000000000131507"

"WB-51SAR-LS"

"WB-51SAR-L")

HDP26-24-18SE-L017

(Alias Part Numbers:

"9-1899775-4")

HD14-9-1939PE

(Alias Part Numbers:

"ZPF000000000130538")

HDP24-24-31PE-L017

(Alias Part Numbers:

"ZPF000000000131139"

"HDP24-24-31PE-L017LD"

"HDP24-24-31PE-L017LS"

"5-1899768-4"

"HDP24-24-31PE-L017-L")

DRB12-128PAE-L018

(Alias Part Numbers:

"ZPF000000000145699"

"8-1899817-6")

HD10-5-16P

(Alias Part Numbers:

"ZPF000000000130329")

DT04-08PA-L012

DTM04-3P

(Alias Part Numbers:

Product Affected

"ZPF000000000130198"

"DTM04-3P-LD"

"DTM04-3P-LS"

"DTM04-3P-L")

HDB36-24-91SN-059

(Alias Part Numbers:

"ZPF000000000130526"

"3-1899777-4")

HDP24-18-8PE-L017

(Alias Part Numbers:

"ZPF000000000130491"

"ZPF000000000146152"

"8-1899773-7")

DRB12-102PAE-L018

(Alias Part Numbers:

"ZPF000000000138178"

"DRB12-102PAE-L018-MS"

"DRB12-102PAE-L018-M"

"8-1899793-9")

DRB12-48PAE-L018

(Alias Part Numbers:

"ZPF000000000140760"

"DRB12-48PAE-L018-AS"

"DRB12-48PAE-L018-LD"

"DRB12-48PAE-L018-LS"

"DRB12-48PAE-L018-L"

"8-1899793-8"

"DRB12-48PAE-L018BR")

HD34-24-91PN

YHDP24-24-18PEL024

(Alias Part Numbers:

"HDP24-24-18PE-L024")

DT06-3S-CE06

YHDP26-24-47SEL024

(Alias Part Numbers:

"HDP26-24-47SE-L024")

DT04-08PA-CL03

HD10-9-1939PE-P080

HDP26-24-23SE-L017

(Alias Part Numbers:

Product Affected

"ZPF000000000131037"

"HDP26-24-23SE-L017AS"

"8-1899773-6")

YHDP26-24-31SEL024

(Alias Part Numbers:

"HDP26-24-31SE-L024")

DTM06-4S

(Alias Part Numbers:

"ZPF000000000130267"

"8202606979")

DTP06-4S-C015

(Alias Part Numbers:

"ZPF000000000130277"

"DTP06-4S-C015-LD"

"DTP06-4S-C015-LS"

"DTP06-4S-C015-E"

"DTP06-4S-C015-L")

DTP04-4P

(Alias Part Numbers:

"ZPF000000000130270"

"DTP04-4P-AS"

"DTP04-4P-SC"

"DTP04-4P-S")

DTP06-2S-C017

HDP24-24-23PN-L017

(Alias Part Numbers:

"ZPF000000000131013")

WB-51PAR

(Alias Part Numbers:

"ZPF000000000131505"

"WB-51PAR-LD"

"WB-51PAR-LS"

"WB-51PAR-L")

DT04-12PA-BL04

HDC16-9

(Alias Part Numbers:

"ZPF000000000131711"

"HDC16-9-AS"

"HDC16-9-LS"

"HDC16-9-MS"

Product Affected

"\$\$HDC16-9"

"HDC16-9-L"

"HDC16-9-M")

DTP06-2S

(Alias Part Numbers:

"ZPF000000000130150"

"DTP06-2S-AS"

"DTP06-2S-LS"

"ZPF000000000140916")

HDP24-18-8PN

(Alias Part Numbers:

"ZPF000000000130493")

HDP24-24-9PN-L017

(Alias Part Numbers:

"7-1899842-2")

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.