



06-Nov-2018

PCN #:E-18-017160

Subject:35 Position AMPSEAL Plug assemblies

Description of Change: A new capacity mold is being built for the wire seal used on the 35 position AMPSEAL plug assemblies. This mold will be used to supplement the current mold and will not replace it. There will be no form, fit or function change to the product with the release of this new mold.

Reason: This product line has seen extensive demand increases from our customer base. This demand is outpacing the current capacity and has impacted on-time deliveries. TE is investing to ensure that the current situation is corrected, as well as for the future, consistent with our goal of on-time delivery of defect free products. If you require PPAP submission, please place request with ict-ppap-request@te.com A level 4 will be submitted upon request.

Key Dates:

Contact By Date:04-Feb-2019

Implementation Date:04-Feb-2019

Product Affected

776164-4

776164-2

776164-6

776164-1

776164-5

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any

or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.