



21-Feb-2019

PCN #:P-19-016981

Subject:AMPMODU MTE HEADER ASSEMBLIES

Description of Change: Manufacturing location change. For any orders for an end customer location that is in the Americas, for the following part numbers, the manufacturing location will change from our TE plant in Suzhou, China to our TE plant in Hermosillo, Mexico.

Reason: Dear Customer, we hereby inform you about a transfer of tools and/or processes. The transfer follows a strict procedure, which fully maintains quality, ability to supply and form-fit-function of the concerned products. The new manufacturing location operates under a certified quality management system in accordance with standard automotive requirements. A TE-internal release test based on the relevant part specifications will be executed before delivery. Upon request, a PPAP Level 2 will be available if it concerns a transfer of a tool which produces a finished TE-product. A PPAP Level 1 will be available if it concerns a component of a TE-product, where the production location of the finished TE-product remains unchanged. If you require such a PPAP, please notify the responsible TE Sales Contact within 14 calendar days after receipt of this PCN

Key Dates:

Contact By Date:25-Apr-2019

Implementation Date:25-Apr-2019

Product Affected

5-103735-4

5-103639-2

5-103639-6

6-103735-6

2-103639-6

7-103639-4

Product Affected

6-103639-7
2-103735-2
3-103639-2
6-103639-2
2-103639-2
5-103639-9
2-103639-3
2-103639-9
5-103735-2
5-103735-5
6-103639-4
6-103735-2
7-103735-1
6-103735-1
7-103639-0
5-103639-5
7-103639-3
1-103735-2
3-103639-3
7-103735-2
7-103735-3
5-103735-6
6-103735-4
6-103735-0
2-103639-4
6-103639-8
5-103735-7
5-103639-7
6-103735-8
2-103639-7
5-103639-3
7-103735-0
5-103735-8
6-103639-5
5-103735-9
7-103639-1
6-103735-9
7-103735-4
6-103639-3
6-103735-7

Product Affected

2-103735-3
1-103639-7
6-103639-1
5-103735-1
6-103639-9
1-103735-8
2-103639-8
1-103735-7
5-103639-8
5-103639-4
2-103639-0
5-103735-3
2-103639-5
1-103639-8
6-103639-0
7-103639-2
6-103639-6
6-103735-5
6-103735-3
2-103735-0
3-103639-0
1-103639-6
5-103639-1
2-103735-1
3-103639-1
2-103735-4
1-103735-9
1-103735-6
1-103735-5
1-103735-4
1-103735-3
1-103735-1
1-103735-0
103735-9
103735-8
103735-7
103735-6
103735-5
103735-4
103735-3

Product Affected

103735-2
103735-1
2-103639-1
1-103639-9
1-103639-5
1-103639-4
1-103639-3
1-103639-2
1-103639-1
1-103639-0
103639-9
103639-8
103639-7
103639-6
103639-5
103639-4
103639-3
103639-2
103639-1
2-103638-4

(Alias Part Numbers:

"1166374")
2-103638-3
2-103638-2
2-103638-1
2-103638-0
1-103638-9
1-103638-8
1-103638-7
1-103638-6
1-103638-5
1-103638-4
1-103638-3
1-103638-2
1-103638-1

(Alias Part Numbers:

"2-42937-3651")
1-103638-0
103638-9
103638-8

Product Affected

(Alias Part Numbers:

"407161207")

103638-7

103638-6

103638-5

(Alias Part Numbers:

"407161199")

103638-4

103638-3

103638-2

(Alias Part Numbers:

"407085000")

103638-1

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.