



28-Jun-2019

PCN #:P-19-017567

Subject:DMC-M - EN4165 - Layouts 20-22

Description of Change: Reengineering of DMC-M (EN4165-003) module layout 20-22 Parts concerned: DMC-M 20-22** EN4165A20-221** MBBN3330U2022** BACI10BC2022**B (**). All gender, polarization and contact delivery conditions are concerned. The peripheral sealed version and reinforced resistance to fuel are not concerned.

Reason: Product improvement. The evolution concerns the retaining clip in the module. Before evolution: Metallic clip. After evolution: Plastic clips (molded in the retaining insert). Fit and function: no impact, contacts, tooling and wiring procedure are unchanged. Form: Retaining insert becomes black instead of green. Qualification tests were conducted according to EN4165-001 standard. Tests are compiled in test report PVE 787-045 VA. The reengineering versions are EN4165 certified.

Key Dates:

Contact By Date:01-Jul-2018

Implementation Date:01-Jul-2018

Product Affected

ZPF000000000003793

(Alias Part Numbers:

"732-8223-00")

ZPF0000000000204412

(Alias Part Numbers:

"732-8100-23")

ZPF000000000109719

(Alias Part Numbers:

"DMC-M 22-07 SN"

"DMC-M22-07SN")

Product Affected

ZPF000000000114470

(Alias Part Numbers:
"DMC-M 22-07 BD")

ZPF000000000200234

(Alias Part Numbers:
"797-8010-04")

ZPF000000000202606

(Alias Part Numbers:
"732-8255-22 R")

ZPF000000000003654

(Alias Part Numbers:
"728-8001-01")

ZPF000000000015290

(Alias Part Numbers:
"DMC-M 20-22 AD")

ZPF000000000097326

(Alias Part Numbers:
"732-8248-01")

ZPF000000000114456

(Alias Part Numbers:
"DMC-M 22-05 BB")

ZPF000000000100796

(Alias Part Numbers:
"732-8260-22")

ZPF000000000167486

(Alias Part Numbers:
"797-8012-05")

ZPF000000000202064

(Alias Part Numbers:
"741-8256-04")

ZPF000000000003820

(Alias Part Numbers:
"741-8008-00")

ZPF000000000148207

(Alias Part Numbers:
"732-8297-02")

ZPF000000000003670

(Alias Part Numbers:
"732-0730-22")

ZPF000000000114469

Product Affected

(Alias Part Numbers:
"DMC-M 22-07 BC")
ZPF000000000120976

(Alias Part Numbers:
"719-8015-44")
ZPF00000000015285

(Alias Part Numbers:
"DMC-M 20-22 AA")
ZPF000000000205525

(Alias Part Numbers:
"732-0730-22 R")
ZPF00000000015303

(Alias Part Numbers:
"DMC-M 20-22 PB"
"DMC-M20-22PB")
ZPF000000000109720

(Alias Part Numbers:
"DMC-M 22-10 SN"
"DMC-M22-10SN")
ZPF00000000015306

(Alias Part Numbers:
"DMC-M 20-22 PN")
ZPF000000000205114

(Alias Part Numbers:
"797-8029-04")
ZPF00000000004091

(Alias Part Numbers:
"756-8000-04")
ZPF000000000121617

(Alias Part Numbers:
"732-0955-22")
ZPF000000000122110

(Alias Part Numbers:
"732-0959-22")
ZPF000000000202762

(Alias Part Numbers:
"784-8100-01")
ZPF000000000114455

(Alias Part Numbers:
"DMC-M 22-05 BA")

Product Affected

ZPF000000000167485

(Alias Part Numbers:

"797-8012-04")

ZPF00000000015291

(Alias Part Numbers:

"DMC-M 20-22 AN"

"BACI10BC2022PNB")

ZPF00000000003666

(Alias Part Numbers:

"732-0597-22")

ZPF00000000003795

(Alias Part Numbers:

"732-8223-02")

ZPF000000000113364

(Alias Part Numbers:

"732-0569-22")

ZPF000000000204523

(Alias Part Numbers:

"797-8027-03")

ZPF00000000015289

(Alias Part Numbers:

"DMC-M 20-22 AC")

ZPF000000000100306

(Alias Part Numbers:

"732-8256-22")

ZPF000000000202061

(Alias Part Numbers:

"741-8256-01")

ZPF000000000114460

(Alias Part Numbers:

"DMC-M 22-10 BN")

ZPF000000000085949

(Alias Part Numbers:

"DMC-M 20-22 PN-A1360")

ZPF000000000114458

(Alias Part Numbers:

"DMC-M 22-05 BD")

ZPF00000000003674

(Alias Part Numbers:

"732-0731-22")

Product Affected

ZPF000000000015287

(Alias Part Numbers:
"DMC-M 20-22 AB")

ZPF0000000000114173

(Alias Part Numbers:
"732-0946-22")

ZPF000000000015302

(Alias Part Numbers:
"DMC-M 20-22 PA"
"DMC-M20-22PA")

ZPF0000000000205113

(Alias Part Numbers:
"797-8029-05")

ZPF0000000000114461

(Alias Part Numbers:
"DMC-M 22-10 BB")

ZPF0000000000167484

(Alias Part Numbers:
"797-8012-03")

ZPF0000000000167490

(Alias Part Numbers:
"797-8013-04")

ZPF0000000000200239

(Alias Part Numbers:
"797-8011-04 A")

ZPF000000000015312

(Alias Part Numbers:
"DMC-M 20-22 SB"
"DMC-M20-22SB")

ZPF0000000000167489

(Alias Part Numbers:
"797-8013-03")

ZPF0000000000204411

(Alias Part Numbers:
"732-8100-22")

ZPF0000000000201169

(Alias Part Numbers:
"732-8279-14")

ZPF0000000000100304

(Alias Part Numbers:

Product Affected

"732-8254-22")

ZPF000000000113058

(Alias Part Numbers:

"DMC-M 22-05 SA")

ZPF000000000003809

(Alias Part Numbers:

"732-8235-03")

ZPF000000000114459

(Alias Part Numbers:

"DMC-M 22-10 BA")

ZPF000000000113685

(Alias Part Numbers:

"732-0944-22")

ZPF000000000202607

(Alias Part Numbers:

"732-8260-22 R")

ZPF00000000015305

(Alias Part Numbers:

"DMC-M 20-22 PD"

"DMC-M20-22PD")

ZPF000000000205399

(Alias Part Numbers:

"732-8256-22 R")

ZPF000000000003665

(Alias Part Numbers:

"732-0596-22")

ZPF000000000204270

(Alias Part Numbers:

"732-8333-22")

ZPF00000000022993

(Alias Part Numbers:

"732-0330-22")

ZPF000000000114467

(Alias Part Numbers:

"DMC-M 22-07 BA")

ZPF000000000204762

(Alias Part Numbers:

"732-8337-22")

ZPF00000000015298

(Alias Part Numbers:

Product Affected

"DMC-M 20-22 BD")

ZPF000000000109831

(Alias Part Numbers:

"732-8274-22")

ZPF000000000203623

(Alias Part Numbers:

"DMC-M 20-22 SN 395")

ZPF000000000205116

(Alias Part Numbers:

"797-8029-03")

ZPF000000000114463

(Alias Part Numbers:

"DMC-M 22-10 BD")

ZPF000000000134307

(Alias Part Numbers:

"732-8279-02")

ZPF000000000163615

(Alias Part Numbers:

"732-8305-22")

ZPF000000000003656

(Alias Part Numbers:

"728-8003-00")

ZPF000000000003794

(Alias Part Numbers:

"732-8223-01")

ZPF000000000146485

(Alias Part Numbers:

"732-8294-22")

ZPF000000000003657

(Alias Part Numbers:

"728-8004-00")

ZPF000000000122205

(Alias Part Numbers:

"732-0952-22")

ZPF000000000113061

(Alias Part Numbers:

"DMC-M 22-05 SD")

ZPF000000000105361

(Alias Part Numbers:

"DMC-M 22-05 SN")

Product Affected

ZPF000000000113060

(Alias Part Numbers:
"DMC-M 22-05 SC")

ZPF00000000015297

(Alias Part Numbers:
"DMC-M 20-22 BC")

ZPF000000000110281

(Alias Part Numbers:
"732-8255-22")

ZPF000000000148978

(Alias Part Numbers:
"732-8303-22")

ZPF000000000139630

(Alias Part Numbers:
"797-8001-03")

ZPF00000000015293

(Alias Part Numbers:
"DMC-M 20-22 BA")

ZPF000000000203910

(Alias Part Numbers:
"732-8332-22")

ZPF00000000015304

(Alias Part Numbers:
"DMC-M 20-22 PC"
"DMC-M20-22PC")

ZPF000000000097324

(Alias Part Numbers:
"732-8246-01")

ZPF000000000003808

(Alias Part Numbers:
"732-8235-02")

ZPF000000000148206

(Alias Part Numbers:
"732-8297-01")

ZPF00000000015295

(Alias Part Numbers:
"DMC-M 20-22 BB")

ZPF000000000114462

(Alias Part Numbers:
"DMC-M 22-10 BC")

Product Affected

ZPF000000000204525

(Alias Part Numbers:

"797-8027-01")

ZPF000000000202254

(Alias Part Numbers:

"732-8279-17")

ZPF000000000114466

(Alias Part Numbers:

"DMC-M 22-07 BN")

ZPF000000000113059

(Alias Part Numbers:

"DMC-M 22-05 SB")

ZPF000000000205355

(Alias Part Numbers:

"732-8254-22 R")

ZPF00000000015310

(Alias Part Numbers:

"DMC-M 20-22 SA"

"8-1899778-1"

"DMC-M20-22SA")

ZPF00000000015316

(Alias Part Numbers:

"DMC-M 20-22 SD"

"2-1899779-2"

"DMC-M20-22SD")

ZPF000000000114468

(Alias Part Numbers:

"DMC-M 22-07 BB")

ZPF000000000200233

(Alias Part Numbers:

"797-8010-03")

ZPF000000000200238

(Alias Part Numbers:

"797-8011-03 A")

ZPF00000000015300

(Alias Part Numbers:

"DMC-M 20-22 BN 395")

ZPF000000000139628

(Alias Part Numbers:

"797-8001-01")

Product Affected

ZPF000000000114454

(Alias Part Numbers:
"DMC-M 22-05 BN")

ZPF000000000004093

(Alias Part Numbers:
"756-8009-00")

ZPF000000000003807

(Alias Part Numbers:
"732-8235-01")

ZPF000000000114457

(Alias Part Numbers:
"DMC-M 22-05 BC")

ZPF000000000015314

(Alias Part Numbers:
"DMC-M 20-22 SC"
"DMC-M20-22SC")

ZPF000000000200235

(Alias Part Numbers:
"797-8010-05")

ZPF000000000015318

(Alias Part Numbers:
"DMC-M 20-22 SN")

ZPF000000000120980

(Alias Part Numbers:
"732-8245-03")

ZPF000000000003806

(Alias Part Numbers:
"732-8235-00")

73205630147000B

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.