



09-Sep-2019

**PCN #:**E-19-009235

**Subject:**Large heat shrink Identification sleeves, 25mm and above (1 inch and above).

**Description of Change:** Relocation of manufacture to Europe. There is no change to fit, form or function.

**Reason:** Manufacturing / Process Requirements. The existing site where these parts are made has been sold. Therefore these parts have to be relocated. A review of manufacturing footprint has prompted the relocation to an alternative TE manufacturing site in Trutnov, Cz.

**Key Dates:**

**Contact By Date:**07-Feb-2020

**Implementation Date:**07-Feb-2020

**Product Affected**

CB9667-000

(Alias Part Numbers:

"TMS-SCE-1-2.0-9-PB-CS7783")

CF6332-000

(Alias Part Numbers:

"TMS-SCE-1-2.0-4-PB-CS7783")

9209890001

(Alias Part Numbers:

"1-1197146-6"

"TMS-SCE-1-2.0-2L")

1477610001

(Alias Part Numbers:

"9-1191067-7"

"TMS-SCE-1-1/2-2.0-0")

**Product Affected**

2557290003

(Alias Part Numbers:

"7-1191871-9"

"RPS-1-400/2.0-4")

CL6529-000

(Alias Part Numbers:

"TMS-SCE-1-1/2-6-PB-CS7783")

EK5307-000

EM7776-000

996870-000

(Alias Part Numbers:

"1-1197942-5"

"TTMS-25.4-9")

CL5871-000

(Alias Part Numbers:

"HT-SCE-1K-3/4-0-PB-CS7783")

131854-000

(Alias Part Numbers:

"6-1199206-0"

"HT-SCE-1K-3/4-2.0-0")

4397130001

(Alias Part Numbers:

"3-1193304-2"

"TMS-SCE-1-2.0-9")

CF7335-000

(Alias Part Numbers:

"TMS-SCE-1-1/2-2.0-4-PB-CS7783")

2290750001

(Alias Part Numbers:

"6-1191684-9"

"TMS-SCE-1K-1-2.0-4")

142458-000

(Alias Part Numbers:

"3-1197993-3"

"TTMS-38.1-9")

1130910001

(Alias Part Numbers:

"1-1190825-3"

"TMS-SCE-1-2.0-S1-4")

CU9499-000

## **Product Affected**

CB2410-000

(Alias Part Numbers:

"HT-SCE-3/4-2.0-0-PB-CS7783")

CL5863-000

(Alias Part Numbers:

"TMS-SCE-1K-1-9-PB-CS7783")

CB9670-000

(Alias Part Numbers:

"TMS-SCE-2-2.0-9-PB-CS7783")

CB8639-000

(Alias Part Numbers:

"TMS-SCE-1-1/2-2.0-9-PB-CS7783")

6706090001

(Alias Part Numbers:

"4-1195278-6"

"TMS-SCE-1-1/2-2.0-4")

4602050003

(Alias Part Numbers:

"9-1193451-3"

"RPS-1-400/2.0-9")

6789530001

(Alias Part Numbers:

"2-1195337-1"

"TMS-SCE-1-2.0-0")

8294790001

(Alias Part Numbers:

"9-1196477-0"

"TMS-SCE-1-1/2-2.0-6")

0253350001

(Alias Part Numbers:

"6-1190196-0"

"TMS-SCE-1K-1-2.0-9")

1297970001

(Alias Part Numbers:

"6-1190942-6"

"TMS-SCE-1K-1-2.0-2")

191509-000

(Alias Part Numbers:

"8-1191388-9"

"TMS-SCE-2-1/4-2.0-9")

## **Product Affected**

CL5865-000

(Alias Part Numbers:

"TMS-SCE-1K-1-1/2-9-PB-CS7783")

C10583-000

(Alias Part Numbers:

"7-1202127-4"

"HT-SCE-3/4-2.0-9CS7783")

6896830001

(Alias Part Numbers:

"1195416-5"

"TMS-SCE-1-1/2-2.0-5")

577739-000

(Alias Part Numbers:

"5-1194582-9"

"TMS-SCE-2-2.0-9")

382637-000

(Alias Part Numbers:

"2-1192866-9"

"TTMS-25.4-0")

385630-000

(Alias Part Numbers:

"6-1198849-7"

"TTMS-38.1-0")

550819-000

(Alias Part Numbers:

"1-1194348-2"

"HT-SCE-1K-1-2.0-9")

CA5943-000

(Alias Part Numbers:

"HT-SCE-1K-3/4-2.0-6")

5414710001

(Alias Part Numbers:

"3-1194246-8"

"TMS-SCE-1-1/2-2.0-9")

7992730001

(Alias Part Numbers:

"6-1196179-1"

"TMS-SCE-1-2.0-4")

1505370001

(Alias Part Numbers:

**Product Affected**

"3-1191088-8"

"TMS-SCE-1K-1-1/2-2.0-9")

F91029-000

(Alias Part Numbers:

"5-1202111-4"

"TMS-SCE-1-2.0-6-CS7783")

CL5867-000

(Alias Part Numbers:

"TMS-SCE-1K-2-9-PB-CS7783")

4076510001

(Alias Part Numbers:

"2-1193075-3"

"TMS-SCE-1-2.0-6")

9410990001

(Alias Part Numbers:

"9-1197286-5"

"HT-SCE-3/4-2.0-9")

EG8907-000

CB9669-000

(Alias Part Numbers:

"TMS-SCE-2-2.0-4-PB-CS7783")

2209350001

(Alias Part Numbers:

"8-1191628-1"

"HT-SCE-1K-3/4-2.0-9")

5134530001

(Alias Part Numbers:

"1-1194034-6"

"TMS-SCE-1-2.0-S1-9")

CL5862-000

(Alias Part Numbers:

"TMS-SCE-1K-1-4-PB-CS7783")

CL6530-000

(Alias Part Numbers:

"TMS-SCE-2-6-PB-CS7783")

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.