



11-Mar-2020

PCN #:E-20-003312

Subject:Solder devices as per attached list of parts.

Description of Change: Eliminate Hexabromocyclododecane (HBCDD) from the flux composition

Reason: Manufacturing / Process Requirements. Based on our findings as highlighted on the NOE, we are actively working with our supplier to source an alternate flux which does not contain HBCDD. As a result of this change, we are doing all relevant tests required to ensure the new parts have the same level of performance and comply with the TE internal specifications as well as external agency specifications including the MIL approvals as and where applicable.

Key Dates:

Contact By Date:13-Mar-2020

Implementation Date:13-Mar-2020

Product Affected

534583-000

(Alias Part Numbers:

"1-1194196-5"

"RBD-75-M-02")

128469-000

(Alias Part Numbers:

"5-1190933-3"

"RBD-50-M-03")

680003-000

(Alias Part Numbers:

"8-1195345-0")

848661-000

(Alias Part Numbers:

Product Affected

"1196618-7"

"RTD-50-P-02")

052247-000

(Alias Part Numbers:

"6-1190399-9"

"PTD-50-M-00")

441975-000

(Alias Part Numbers:

"9-1193322-4"

"RTD-75-M-01")

205863-000

(Alias Part Numbers:

"1191492-9"

"RBD-75-M-03")

996227-000

(Alias Part Numbers:

"9-1197703-9"

"RBD-75-M-00")

001885-000

(Alias Part Numbers:

"2-1190014-0"

"ST63-4-00")

919008-000

(Alias Part Numbers:

"8-1197131-4"

"ST63-4-55-24-90")

120331-000

(Alias Part Numbers:

"4-1190875-0"

"RTD-50-M-04")

668131-000

(Alias Part Numbers:

"5-1195261-3"

"RTD-50-M-00")

955933-000

(Alias Part Numbers:

"1-1197401-7")

425653-000

(Alias Part Numbers:

"9-1193203-9"

Product Affected

"RTD-50-P-00")

182443-000

(Alias Part Numbers:

"7-1191325-1")

863011-000

(Alias Part Numbers:

"6-1196721-1"

"PTD-50-85-S")

333867-000

(Alias Part Numbers:

"6-1192522-1"

"RTD-75-M-04")

246393-000

(Alias Part Numbers:

"4-1191807-3"

"ST18-4-9039")

883689-000

(Alias Part Numbers:

"6-1196877-6"

"PBD-50-M-00")

579028-000

(Alias Part Numbers:

"2-1200823-5"

"B-600-31")

600363-000

(Alias Part Numbers:

"1-1194748-8"

"PTD-50-82-S")

741965-000

(Alias Part Numbers:

"3-1195790-4"

"PBD-75-M-00")

511405-000

(Alias Part Numbers:

"8-1194019-3"

"RBD-50-M-01")

573571-000

(Alias Part Numbers:

"1-1194553-6"

"RTD-50-M-03")

Product Affected

436425-000

(Alias Part Numbers:

"7-1193280-8"

"PBD-50-M-01-MS")

625190-000

(Alias Part Numbers:

"8-1194948-2")

026279-000

(Alias Part Numbers:

"9-1190203-9"

"PTD-50-83-S")

256627-000

(Alias Part Numbers:

"9-1191877-9"

"ST63-4-55-26-90")

248092-000

(Alias Part Numbers:

"4-1191819-5"

"ST18-4-00")

379759-000

(Alias Part Numbers:

"4-1192840-2"

"RBD-75-M-04")

094067-000

(Alias Part Numbers:

"6-1190689-6"

"RTD-75-M-02")

157763-000

(Alias Part Numbers:

"7-1191139-6"

"RTD-75-M-00")

992021-000

(Alias Part Numbers:

"5-1197673-1"

"RTD-50-M-00-H")

113203-000

(Alias Part Numbers:

"9-1190825-4")

648837-000

(Alias Part Numbers:

Product Affected

"8-1195121-2"

"PBD-50-M-00-MSD")

593035-000

(Alias Part Numbers:

"6-1194689-0"

"RTD-50-M-01")

312605-000

(Alias Part Numbers:

"8-1192364-0"

"B-053-70-03")

327539-000

(Alias Part Numbers:

"1192478-7"

"RTD-50-M-01-H")

601107-000

(Alias Part Numbers:

"8-1194757-5")

532505-000

(Alias Part Numbers:

"2-1194181-5"

"RBD-50-M-02")

601108-000

(Alias Part Numbers:

"9-1194757-0")

425409-000

(Alias Part Numbers:

"2-1193202-1"

"ST63-4-55-22-90")

197947-000

(Alias Part Numbers:

"5-1191434-1"

"RBD-75-M-01")

622046-000

(Alias Part Numbers:

"7-1194916-3"

"D-144-46")

621060-000

(Alias Part Numbers:

"5-1194907-0")

900469-000

Product Affected

(Alias Part Numbers:

"4-1196999-4"

"RBD-50-M-00")

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.