



Product Change Notification

Current Date: 10-Aug-2020

TE Connectivity

Product Change Notification: P-20-019438

PCN Date: 10-AUG-20

Customer: TTI, Inc. (1305175)

Location: Maisach-gernlinden

Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:
MCON 1.2 CB REC SRC AG

Description of Changes
Manufacturing Location Change. The plating of the raw material used to fabricate the Silver MCON 1.2 Receptacle Contacts, currently plated in TE Germany (Woert Plant), will be localized to TE United States (Greensboro Plant). The affected stamping processes will remain in TE United States (Greensboro Plant). No Shipping Point Change. EMEA production continues to support EMEA demand.

Reason for Changes:
Localization of the raw material plating process to the region of consumption.

| | |
|---|---|
| Estimated Dates: | |
| Last Order Date (Obsolete Parts Only): | First Date To Ship (Changed Parts Only): |
| | 30-OCT-2020 |
| Last Ship Date (Obsolete Parts Only): | Last Date for Mixed Shipments: (Changed Parts Only): |
| | No Mixed Shipments |

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|-----------------------------|---------------------------|------------------|----------------------|----------------------|------------------------|---------------------------------|---------------------------|
| 1670144-3 | NO | | TYC1670144-3 | | | | |
| 7-1452665-3 | NO | | TYC7-1452665-3 | | | | |
| 7-1452668-3 | NO | | TYC7-1452668-3 | | | | |



Product Change Notification

Current Date: 10-Aug-2020

TE Connectivity

Product Change Notification: P-20-019438

PCN Date: 10-AUG-20

Customer: TTI, Inc. (3057778)

Location: Maisach-gernlinden

Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:
MCON 1.2 CB REC SRC AG

Description of Changes
Manufacturing Location Change. The plating of the raw material used to fabricate the Silver MCON 1.2 Receptacle Contacts, currently plated in TE Germany (Woert Plant), will be localized to TE United States (Greensboro Plant). The affected stamping processes will remain in TE United States (Greensboro Plant). No Shipping Point Change. EMEA production continues to support EMEA demand.

Reason for Changes:
Localization of the raw material plating process to the region of consumption.

Estimated Dates:

| | |
|---|---|
| Last Order Date (Obsolete Parts Only): | First Date To Ship (Changed Parts Only): |
| | 30-OCT-2020 |
| Last Ship Date (Obsolete Parts Only): | Last Date for Mixed Shipments: (Changed Parts Only): |
| | No Mixed Shipments |

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|-----------------------------|---------------------------|------------------|----------------------|----------------------|------------------------|---------------------------------|---------------------------|
| 1670144-3 | NO | | TYC1670144-3 | | | | |
| 7-1452665-3 | NO | | TYC7-1452665-3 | | | | |
| 7-1452668-3 | NO | | TYC7-1452668-3 | | | | |