



Product Change Notification

Current Date: 07-Jul-2020

TE Connectivity

Product Change Notification: P-20-019266

PCN Date: 07-JUL-20

Customer: TTI, Inc. (1305175)

Location: Maisach-gernlinden

Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:
Laser marking process on modules DMC-M

Description of Changes
Te Evreux, FR will implement a new process for the cavity marking, and the part number marking on module DMC-M. Technical risk: referring to the declaration of design and performances DDP 732 313 VA, the technical risks have been highlighted These have been mitigated thanks to the qualification test report PVE 732-193 VA. Pending approval from certification authority

Reason for Changes:
Product improvement.Laser marking process will avoid, customer and internal quality alert issue due to current marking process. Current process is ink marking (legibility and marking erase). The marking of the cavities will be made at the end of the assembly process. It will avoid to have two part number for the grommet (rear male and rear female grommet). Laser proces avoid "wet"processes: no managment of peremption dates of ink, no time waisted du to curing process.

Estimated Dates:

Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	20-JUL-2020
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	20-JUL-2021

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
ZPF00000000003665	NO			732-0596-22			
ZPF00000000003666	NO			732-0597-22			
ZPF000000000015291	NO			DMC-M20-22AN,BACI10BC2022PNB, DMC-M 20-22 AN			
ZPF000000000015301	NO			DMC-M20-22BNE, DMC-M 20-22 BNE			
ZPF000000000015306	NO			DMC-M20-22PN, DMC-M 20-22 PN			
ZPF000000000015318	NO			DMC-M20-22SN, DMC-M 20-22 SN			
ZPF000000000099564	NO			732-8254-99			
ZPF000000000099565	NO			732-8256-99			
ZPF000000000099701	NO			DMC-M99-01BA, DMC-M 99-01 BA			
ZPF000000000099707	NO			DMC-M99-01AN,BACI10BC1622PNB, DMC-M 99-01 AN			
ZPF000000000099708	NO			DMC-M99-01AA, DMC-M 99-01 AA			
ZPF000000000100304	NO			732-8254-22			
ZPF000000000100308	NO		DEU732-8255-99	732-8255-99			
ZPF000000000100796	NO			732-8260-22			
ZPF000000000105361	NO			DMC-M22-05SN, DMC-M 22-05 SN			
ZPF000000000110281	NO			732-8255-22			
ZPF000000000200361	NO			DMC-M00-00PN-A1188,DMC-M00-00PN-A1188, DMC-M 00-00 PN-A1188			
ZPF000000000200366	NO			DMC-M04-12AN-A1188,DMC-M04-12AN-A1188, DMC-M 04-12 AN-A1188			
ZPF000000000200367	NO			DMC-M04-12BN-A1188,DMC-M04-12BN-A1188, DMC-M 04-12 BN-A1188			
ZPF000000000200369	NO			DMC-M08-16BN-A1188,DMC-M08-16BN-A1188, DMC-M 08-16 BN-A1188			
ZPF000000000200371	NO			DMC-M12-20BN-A1188,DMC-M12-20BN-A1188, DMC-M 12-20 BN-A1188			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
ZPF00000000200372	NO			DMC-M20-22AN-A1188, DMC-M20-22AN-A1188, DMC-M 20-22 AN-A1188			
ZPF00000000200373	NO			DMC-M20-22BN-A1188, DMC-M20-22BN-A1188, DMC-M 20-22 BN-A1188			
ZPF00000000200375	NO			DMC-M99-01AN-A1188, DMC-M99-01AN-A1188, DMC-M 99-01 AN-A1188			
ZPF00000000200378	NO			DMC-M99-01BN-A1188, DMC-M99-01BN-A1188, DMC-M 99-01 BN-A1188			
ZPF00000000201508	NO			DMC-M20-22AB-A1188, DMC-M 20-22 AB-A1188			
ZPF00000000202708	NO		DEUDMC-MR30-23PN	DMC-MR30-23PN, DMC-MR 30-23 PN			
ZPF00000000202709	NO		DEUDMC-MR30-23SN	DMC-MR30-23SN, DMC-MR 30-23 SN			
ZPF00000000204750	NO			732-0954-20A1561, 732-0954-20 A1561			



Product Change Notification

Current Date: 07-Jul-2020

TE Connectivity

Product Change Notification: P-20-019266

PCN Date: 07-JUL-20

Customer: TTI, Inc. (3057778)

Location: Maisach-gernlinden

Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:
Laser marking process on modules DMC-M

Description of Changes
Te Evreux, FR will implement a new process for the cavity marking, and the part number marking on module DMC-M. Technical risk: referring to the declaration of design and performances DDP 732 313 VA, the technical risks have been highlighted These have been mitigated thanks to the qualification test report PVE 732-193 VA. Pending approval from certification authority

Reason for Changes:
Product improvement.Laser marking process will avoid, customer and internal quality alert issue due to current marking process. Current process is ink marking (legibility and marking erase). The marking of the cavities will be made at the end of the assembly process. It will avoid to have two part number for the grommet (rear male and rear female grommet). Laser proces avoid "wet"processes: no managment of peremption dates of ink, no time waisted du to curing process.

Estimated Dates:

Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	20-JUL-2020
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	20-JUL-2021

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
ZPF000000000003665	NO			732-0596-22			
ZPF000000000003666	NO			732-0597-22			
ZPF000000000015291	NO			DMC-M20-22AN, BACI10BC2022PNB, DMC-M 20-22 AN			
ZPF000000000015301	NO			DMC-M20-22BNE, DMC-M 20-22 BNE			
ZPF000000000015306	NO			DMC-M20-22PN, DMC-M 20-22 PN			
ZPF000000000015318	NO			DMC-M20-22SN, DMC-M 20-22 SN			
ZPF0000000000099564	NO			732-8254-99			
ZPF0000000000099565	NO			732-8256-99			
ZPF0000000000099701	NO			DMC-M99-01BA, DMC-M 99-01 BA			
ZPF0000000000099708	NO			DMC-M99-01AA, DMC-M 99-01 AA			
ZPF000000000100304	NO			732-8254-22			
ZPF000000000100308	NO		DEU732-8255-99	732-8255-99			
ZPF000000000100796	NO			732-8260-22			
ZPF000000000105361	NO			DMC-M22-05SN, DMC-M 22-05 SN			
ZPF000000000110281	NO			732-8255-22			
ZPF000000000200361	NO			DMC-M00-00PN-A1188, DMC-M00-00PN-A1188, DMC-M 00-00 PN-A1188			
ZPF000000000200366	NO			DMC-M04-12AN-A1188, DMC-M04-12AN-A1188, DMC-M 04-12 AN-A1188			
ZPF000000000200367	NO			DMC-M04-12BN-A1188, DMC-M04-12BN-A1188, DMC-M 04-12 BN-A1188			
ZPF000000000200369	NO			DMC-M08-16BN-A1188, DMC-M08-16BN-A1188, DMC-M 08-16 BN-A1188			
ZPF000000000200371	NO			DMC-M12-20BN-A1188, DMC-M12-20BN-A1188, DMC-M 12-20 BN-A1188			
ZPF000000000200372	NO			DMC-M20-22AN-A1188, DMC-M20-22AN-A1188, DMC-M 20-22 AN-A1188			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
ZPF00000000200373	NO			DMC-M20-22BN-A1188, DMC-M20-22BN-A1188, DMC-M 20-22 BN-A1188			
ZPF00000000200375	NO			DMC-M99-01AN-A1188, DMC-M99-01AN-A1188, DMC-M 99-01 AN-A1188			
ZPF00000000200378	NO			DMC-M99-01BN-A1188, DMC-M99-01BN-A1188, DMC-M 99-01 BN-A1188			
ZPF00000000201508	NO			DMC-M20-22AB-A1188, DMC-M 20-22 AB-A1188			
ZPF00000000202708	NO		DEUDMC-MR30-23PN	DMC-MR30-23PN, DMC-MR 30-23 PN			
ZPF00000000202709	NO		DEUDMC-MR30-23SN	DMC-MR30-23SN, DMC-MR 30-23 SN			
ZPF00000000204750	NO			732-0954-20A1561, 732-0954-20 A1561			