



31-Mar-2021

PCN #:E-21-003395

**Subject:**DEUTSCH HD, HDB & HDP, Tool Duplication and New Supplier.

**Description of Change:** The Industrial and Commercial Transportation business unit of TE Connectivity is adding new capacity tooling for Rubber Components for the part number(s) listed below, additionally is transferring the tool from Currently approved supplier (USA) to another Approved Supplier (USA & MEXICO). These PNs are TE proprietary designs, therefore considered catalog/general market product. PPAP and/or sample requests must be submitted within 14 days of PCN submission via ict-ppap [request@te.com](mailto:request@te.com) or ePPAP system. Submission will not occur without request. If PPAP requested, disposition response is required within 14 days of submit date or it will be considered approved. Product drawing(s) are not affected.

**Reason:** Dear Customer, we hereby inform you of this change. The new tooling is necessary maintain our delivery times. The added tooling does not impact connector performance. **IMPORTANT:** No fit, form or function change. Parts off the new tool are identical to current production. Shipments from current and new tooling configurations may be mixed.

**Key Dates:**

**Contact By Date:**25-May-2021

**Implementation Date:**25-May-2021

**Product Affected**

HDP24-18-21SN

HDP26-24-23PT-L017

HDP26-24-16SN-L017

HD36-24-19SN

HDP24-24-23ST-L015

HDP24-18-21PN

**Alias Part Number**

"ZPF000000000130932"

"ZPF000000000131034"

"ZPF000000000130818"

"ZPF000000000130896",

"\$\$HD36-24-19SN"

"ZPF000000000131024"

"ZPF000000000130930"

|                    |   |
|--------------------|---|
| HD36-24-16PN       | "ZPF000000000130829",<br>"\$HD36-24-16PN",<br>"HD36-24-16PN-RU"   |
| HDFB-16-06S        |   |
| HDP24-24-23ST-L017 | "ZPF000000000131025"  |
| HDP24-18-20PN-L017 |   |
| HDP26-24-19PN      | "ZPF000000000130865"  |
| HDP26-18-14PT      |   |
| HD34-18-14PT       | "ZPF000000000130768"  |
| HD36-18-14ST-059   |   |
| YHDP26-24-16SNL024 | "HDP26-24-16SN-L024"  |
| HD34-18-21PN-059   | "ZPF000000000130961"  |
| HDP26-24-23PT      | "ZPF000000000131032"  |
| HD34-24-19SN-059   |   |
| HDP24-24-23PT-L015 | "ZPF000000000131015"  |
| HDB36-24-19SN-059  | "ZPF000000000130849"  |
| HDP24-24-19PN-L015 | "ZPF000000000130854"  |
| HDP26-24-23ST-L017 | "ZPF000000000131043"  |
| HD36-24-16SN-L005  |   |
| HD34-24-19SN-L005  | "ZPF000000000139066",<br>"HD34-24-19SN-L005-RU"                   |
| HD36-24-16SN       | "ZPF000000000130835",<br>"HD36-24-16SN-RU"                        |
| HD36-24-19SN-L005  |   |
| HD36-18-20SN-059   | "ZPF000000000130917"  |
| HD36-18-21SN-059   | "ZPF000000000130982",<br>"HD36-18-21SN-059-RU"                    |
| HD34-24-19PN-072   | "ZPF000000000130879"  |
| HD34-18-21PN       | "ZPF000000000130960"  |
| HD34-24-16SN-L005  | "ZPF000000000135957"  |
| HDP24-18-20PN      | "ZPF000000000130904"  |
| HDP24-24-19PN      | "ZPF000000000130853",<br>"HDP24-24-19PN-MS",<br>"HDP24-24-19PN-M" |
| HDP26-18-21PN-L017 |   |
| HDB36-24-16SN-059  | "ZPF000000000130797"  |
| HDP24-24-16PN-L017 | "ZPF000000000130803"  |
| HDP24-18-21PN-L017 | "ZPF000000000130931",<br><br>"8-1899794-1"                        |
| HD36-24-23ST-059   | "ZPF000000000131080"  |

|                    |  |
|--------------------|--|
| HDP24-24-16SN-L017 | "ZPF000000000130806"   |
| HDP24-18-20SN      |  |
| HDP26-24-19SN-L017 | "ZPF000000000130873",<br>"7-1899817-2"   |
| HD36-24-16SN-072   | "ZPF000000000130837"   |
| HDB36-24-19SN-072  |  |
| HDB36-24-16SN      | "ZPF000000000130796"   |
| HDB36-24-23ST      |  |
| HDP24-24-23PT      | "ZPF000000000131014",<br>"HDP24-24-23PT-LS",<br>"HDP24-24-23PT-MS",<br>"HDP24-24-23PT-M",<br>"HDP24-24-23PT-L" |
| HDB36-18-21SN      | "ZPF000000000130921"   |
| HD34-24-16SN-059   | "ZPF000000000130826"   |
| HDB36-24-23PT      | "ZPF000000000131000"   |
| YHDP26-18-20SNL024 | "HDP26-18-20SN-L024"   |
| HD36-24-19PN-059   | "ZPF000000000130890",<br>"HD36-24-19PN-059-RU"   |
| HD36-18-20SN       | "ZPF000000000130916"   |
| HD34-18-20PN-059   | "ZPF000000000130908",<br>"HD34-18-20PN-059-RU"   |
| HDP26-18-20SE      | "HDP26-18-20SE-RU"   |
| HD34-18-20SN       | "ZPF000000000130910"   |
| HD36-18-21PN       | "ZPF000000000130978"   |
| HD36-24-19PN-L005  | "ZPF000000000139064",<br>"HD36-24-19PN-L005-RU"  |
| HDP26-18-21SN-L017 | "ZPF000000000130947",<br>"7-1899794-5"   |
| HDB36-24-19PN-059  | "ZPF000000000130847"   |
| HDP24-18-14ST      |  |
| HDP24-24-16SN      | "ZPF000000000130804"   |
| HD36-24-23PT       | "ZPF000000000131069",<br>"HD36-24-23PT-RU"   |
| HD36-24-16SN-059   | "ZPF000000000130836"   |
| HDP26-24-16SN-L015 | "ZPF000000000130817"   |
| YHDP24-18-20PEL024 | "HDP24-18-20PE-L024"   |
| HD36-18-21SN-072   | "ZPF000000000130983"   |
| HDP26-18-20SE-L017 | "ZPF000000000140687"   |
| HDB36-24-19PN-072  |  |
| HDP26-18-21PN      | "ZPF000000000130945"   |

|                    |  |
|--------------------|--|
| HD34-24-23ST       | "ZPF000000000131059"   |
| HD36-24-19SN-072   | "ZPF000000000130898"   |
| HD36-18-20SN-072   | "ZPF000000000130918"   |
| HD34-18-14PT-059   | "3-1899805-2"  |
| HD34-24-23PT-059   | "ZPF000000000131051",<br>"5-1899816-5"   |
| HDFB-12-01S        |  |
| HD36-18-21PN-072   |  |
| HD34-24-19PN-059   | "ZPF000000000130878"   |
| HD36-18-14PT       |  |
| HD34-18-21SN       | "ZPF000000000130963"   |
| HD34-24-19PN-L005  |  |
| HDP26-24-19SN      | "ZPF000000000130871"   |
| HDP24-24-23PT-L017 | "ZPF000000000131016"   |
| HD34-24-19SN       | "ZPF000000000130883",<br>"\$HD34-24-19SN"  |
| HDB36-24-16PN-072  |  |
| HDP24-24-16SN-L015 | "ZPF000000000130805"   |
| HD36-24-16PN-059   | "ZPF000000000130830"   |
| HDP26-24-16PN-L015 | "ZPF000000000130811"   |
| HDP24-18-14PT      |  |
| HD34-18-21PN-072   |  |
| HDP24-24-19SN-L017 | "ZPF000000000130861"   |
| HD36-18-20PN       | "ZPF000000000130913"   |
| HD34-24-16SN-072   | "ZPF000000000130827"   |
| HDP26-24-19SN-L015 | "ZPF000000000130872",<br>"HDP26-24-19SN-L015MS",<br>"5-1899768-2",<br>"HDP26-24-19SN-L015-M" |
| HDB36-24-19PN      | "ZPF000000000130846"   |
| HDB36-24-16PN      | "ZPF000000000130794",<br>"HDB36-24-16PN-RU"  |
| HDP24-24-23ST      | "ZPF000000000131023"   |
| HDP26-24-16PN-L017 | "ZPF000000000130812"   |
| HDP26-24-23PT-L015 | "ZPF000000000131033"   |
| HD34-24-23PT       | "ZPF000000000131050",<br>"HD34-24-23PT-RU"   |
| HD36-24-23PT-059   | "ZPF000000000131070",<br>"HD36-24-23PT-059-RU"   |
| HDP24-24-16PN      | "ZPF000000000130801"   |

|                    |   |
|--------------------|---|
| HDP24-24-19PN-L017 | "ZPF000000000130855",<br>"7-1899817-1"                            |
| HDP26-18-20PN      | "ZPF000000000130905"  |
| HDB36-24-19SN      | "ZPF000000000130848",<br>"HDB36-24-19SN-RU"                       |
| HDP26-24-19PN-L017 | "ZPF000000000130867"  |
| HDP26-18-20SN-L017 | "ZPF000000000138937"  |
| HDP26-24-23ST      | "ZPF000000000131041",<br>"HDP26-24-23ST-MS",<br>"HDP26-24-23ST-M" |
| HDP26-24-19PN-L015 | "ZPF000000000130866"  |
| HDP26-18-21SN      | "ZPF000000000130946"  |
| HD34-24-16PN       | "ZPF000000000130822",<br>"HD34-24-16PN-RU"                        |
| HD34-18-21SN-059   |   |
| HD36-24-19PN       | "ZPF000000000130889"  |
| HD36-18-21SN       | "ZPF000000000130981"  |
| YHDP26-18-20SEL024 | "HDP26-18-20SE-L024"  |
| HD34-24-16PN-059   | "ZPF000000000130823"  |
| HDP24-18-21SN-L017 |   |
| HD34-18-20PN       | "ZPF000000000130907"  |
| HD36-24-19PN-072   | "ZPF000000000130891",<br>"HD36-24-19PN-072-RU"                    |
| HDP24-24-16PN-L015 | "ZPF000000000130802"  |
| HD34-24-16PN-072   |   |
| HDB36-24-16PN-059  | "ZPF000000000130795"  |
| HDP26-24-23ST-L015 | "ZPF000000000131042"  |
| HD36-24-16PN-L005  | "ZPF000000000135958",<br>"HD36-24-16PN-L005-RU"                   |
| HD34-24-19PN       | "ZPF000000000130877"  |
| HDP24-18-20PE-L017 |   |
| HD34-24-16SN       | "ZPF000000000130825",<br>"HD34-24-16SN-RU"                        |
| YHDP24-18-20PNL024 | "HDP24-18-20PN-L024"  |
| HD36-18-14ST       | "ZPF000000000130790"  |
| HD36-18-14ST-072   |   |
| HDP24-24-19SN-L015 | "ZPF000000000130860"  |
| HD36-24-19SN-059   | "ZPF000000000130897"  |
| HDP24-24-19SN      | "ZPF000000000130859"  |
| HDP26-24-16SN      | "ZPF000000000130816"  |
| HDP24-18-20PE      | "ZPF000000000140686"  |

|                  |  |
|------------------|--|
| HDP26-18-14ST    |  |
| HD36-24-23ST     | "ZPF000000000131079",<br>"HD36-24-23ST-AS"     |
| HD36-18-21PN-059 | "ZPF000000000130979"                           |
| HDP26-24-16PN    | "ZPF000000000130810"                           |
| HD36-24-16PN-072 | "ZPF000000000130831",<br>"HD36-24-16PN-072-RU" |
| HD34-24-19SN-072 | "ZPF000000000130885"                           |
| HD34-24-23PT-072 | "ZPF000000000131052"                           |
| HDP26-18-20SN    | "ZPF000000000130906",<br>"ZPF000000000146155"  |

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.

Alert document created by IHS Markit based on content provided by TE Connectivity.