

General Product Description:

Duplicate mold tooling for HV280 Plug Housing

Product Change Notification Current Date: 17-May-2021

PCN Date: 14-MAY-21

TE Connectivity

Product Change Notification: P-21-020929

Customer: TTI, Inc. (1305175) Location: Maisach-gernlinden Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

| Description of Changes | |
|--|--|
| HV280 Plug demands grow dramatically in next years, TE must du | plicate a new mold tool to meet customers demands. |
| | Duplicate mold tooling for HV280 Plug Housing |
| | HV280 Plug demands grow dramatically in next years. TE must duplicate a new mold tool to meet customers demi |
| | |
| | |
| | |
| | |
| | |
| | |
| | |

<u>Duplicate mold tooling for HV280 Plug Housing</u>

| Reason for Changes: | | | |
|--|--|--|--|
| Product improvement.HV280 Plug demands grow dramatically in next years, TE must duplicate a new mold tool to meet customers demands. | | | |
| Estimated Dates: | | | |
| Last Order Date (Obsolete Parts Only): | First Date To Ship (Changed Parts Only): | | |
| | 31-AUG-2021 | | |
| Last Ship Date (Obsolete Parts Only): | Last Date for Mixed Shipments: (Changed Parts Only): | | |
| | No Mixed Shipments | | |

Part Number(s) being Modified:

| Part Number | Part Discontinued | Customer | Customer Part | Alias Part | Substitute Part | Substitute Alias Part | Description Of |
|--------------------|-------------------|----------|----------------|------------|-----------------|-----------------------|----------------|
| | per PCN | Drawing | Number | Number(s) | Number | Number(s) | Difference |
| <u>4-2103015-1</u> | NO | | TYC4-2103015-1 | | | | |
| <u>4-2103015-5</u> | NO | | TYC4-2103015-5 | | | | |
| <u>4-2103015-6</u> | NO | | TYC4-2103015-6 | | | | |
| 4-2103177-1 | NO | | TYC4-2103177-1 | | | | |
| 4-2103177-2 | NO | | TYC4-2103177-2 | | | | |
| 4-2103177-4 | NO | | TYC4-2103177-4 | | | | |
| <u>4-2103177-5</u> | NO | | TYC4-2103177-5 | | | | |
| <u>4-2103177-6</u> | NO | | TYC4-2103177-6 | | | | |



General Product Description:

Product Change Notification

Current Date: 17-May-2021

TE Connectivity

Product Change Notification: P-21-020929

PCN Date: 14-MAY-21

Customer: TTI, Inc. (3057778)

Duplicate mold tooling for HV280 Plug Housing

Location: Maisach-gernlinden **Agreement:** Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

| Duplicate mold tooling for HV280 Plug Housing | |
|--|--|
| | |
| Description of Changes | |
| HV280 Plug demands grow dramatically in next years, TE must duplic | cate a new mold tool to meet customers demands. |
| | Duplicate mold tooling for HV280 Plug Housing |
| | HV280 Plug demands grow dramatically in next years, TE must duplicate a new mold tool to meet customers demands. |
| | |
| | |
| | |
| | |
| | |
| Other attachments: | |

Reason for Changes:

Product improvement.HV280 Plug demands grow dramatically in next years, TE must duplicate a new mold tool to meet customers demands.

| Estimated Dates: | | | |
|--|--|--|--|
| Last Order Date (Obsolete Parts Only): | First Date To Ship (Changed Parts Only): | | |
| | 31-AUG-2021 | | |
| Last Ship Date (Obsolete Parts Only): | Last Date for Mixed Shipments: (Changed Parts Only): | | |
| | No Mixed Shipments | | |

Part Number(s) being Modified:

| Part Number | Part Discontinued | Customer | Customer Part | Alias Part | Substitute Part | Substitute Alias Part | Description Of |
|--------------------|-------------------|----------|----------------|------------|-----------------|-----------------------|----------------|
| | per PCN | Drawing | Number | Number(s) | Number | Number(s) | Difference |
| <u>4-2103015-1</u> | NO | | TYC4-2103015-1 | | | | |
| <u>4-2103015-5</u> | NO | | TYC4-2103015-5 | | | | |
| <u>4-2103015-6</u> | NO | | TYC4-2103015-6 | | | | |
| 4-2103177-1 | NO | | TYC4-2103177-1 | | | | |
| 4-2103177-2 | NO | | TYC4-2103177-2 | | | | |
| 4-2103177-4 | NO | | TYC4-2103177-4 | | | | |
| <u>4-2103177-5</u> | NO | | TYC4-2103177-5 | | | | |
| <u>4-2103177-6</u> | NO | | TYC4-2103177-6 | | | | |

HV280 Plug demands grow dramatically in next years, TE must duplicate a new mold tool to meet customers demands

