



Product Change Notification

Current Date: 20-May-2021

TE Connectivity

Product Change Notification: P-21-020940

PCN Date: 19-MAY-21

Customer: TTI, Inc. (1305175)

Location: Maisach-gernlinden

Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

Duplicate a new auto machine for HV280 Plug

Description of Changes

HV280 Plug demands grow dramatically in next years, TE must duplicate a new auto-machine to meet customers demands.

New auto machine

Other attachments:
[Duplicate a new auto-machine for HV280 Plug.](#)
Reason for Changes:

Product improvement.HV280 Plug demands grow dramatically in next years, TE must duplicate a new auto-machine to meet customers demands.

Estimated Dates:

| | |
|---|---|
| Last Order Date (Obsolete Parts Only): | First Date To Ship (Changed Parts Only): |
| | 31-AUG-2021 |
| Last Ship Date (Obsolete Parts Only): | Last Date for Mixed Shipments: (Changed Parts Only): |
| | No Mixed Shipments |

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|-----------------------------|---------------------------|------------------|----------------------|----------------------|------------------------|---------------------------------|---------------------------|
| 4-2103015-1 | NO | | TYC4-2103015-1 | | | | |
| 4-2103015-5 | NO | | TYC4-2103015-5 | | | | |
| 4-2103015-6 | NO | | TYC4-2103015-6 | | | | |
| 4-2103177-1 | NO | | TYC4-2103177-1 | | | | |
| 4-2103177-2 | NO | | TYC4-2103177-2 | | | | |
| 4-2103177-4 | NO | | TYC4-2103177-4 | | | | |
| 4-2103177-5 | NO | | TYC4-2103177-5 | | | | |
| 4-2103177-6 | NO | | TYC4-2103177-6 | | | | |



Product Change Notification

Current Date: 20-May-2021

TE Connectivity

Product Change Notification: P-21-020940

PCN Date: 19-MAY-21

Customer: TTI, Inc. (3057778)

Location: Maisach-gernlinden

Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

Duplicate a new auto machine for HV280 Plug

Description of Changes

HV280 Plug demands grow dramatically in next years, TE must duplicate a new auto-machine to meet customers demands.

New auto machine



Other attachments:

[Duplicate a new auto-machine for HV280 Plug.](#)

Reason for Changes:

Product improvement.HV280 Plug demands grow dramatically in next years, TE must duplicate a new auto-machine to meet customers demands.

Estimated Dates:

| | |
|---|---|
| Last Order Date (Obsolete Parts Only): | First Date To Ship (Changed Parts Only): |
| | 31-AUG-2021 |
| Last Ship Date (Obsolete Parts Only): | Last Date for Mixed Shipments: (Changed Parts Only): |
| | No Mixed Shipments |

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|-----------------------------|---------------------------|------------------|----------------------|----------------------|------------------------|---------------------------------|---------------------------|
| 4-2103015-1 | NO | | TYC4-2103015-1 | | | | |
| 4-2103015-5 | NO | | TYC4-2103015-5 | | | | |
| 4-2103015-6 | NO | | TYC4-2103015-6 | | | | |
| 4-2103177-1 | NO | | TYC4-2103177-1 | | | | |
| 4-2103177-2 | NO | | TYC4-2103177-2 | | | | |
| 4-2103177-4 | NO | | TYC4-2103177-4 | | | | |
| 4-2103177-5 | NO | | TYC4-2103177-5 | | | | |
| 4-2103177-6 | NO | | TYC4-2103177-6 | | | | |

HV280 Plug demands grow dramatically in next years, TE must duplicate a new auto-machine to meet customers demands.

| | | | | | |
|-------------|-------------|-------------|-------------|-------------|-------------|
| 4-2103177-1 | 4-2103015-1 | 4-2103587-1 | 2310538-1 | 2361027-1 | 1-2361027-1 |
| 4-2103177-2 | 4-2103015-2 | 4-2103587-2 | 2310538-2 | 2361027-2 | 1-2361027-2 |
| 4-2103177-4 | 4-2103015-4 | 4-2103587-4 | 2310538-4 | 2361027-4 | 1-2361027-4 |
| 4-2103177-5 | 4-2103015-5 | 4-2103587-5 | 2310538-5 | 2361027-5 | 1-2361027-5 |
| 4-2103177-6 | 4-2103015-6 | 4-2840548-1 | 2310538-6 | 2361027-6 | 1-2361027-6 |
| 4-2103177-7 | 1587985-1 | 4-2840548-2 | 2310539-1 | 2361027-7 | 1-2361027-7 |
| 2310537-1 | 2358516-1 | 3-2310537-1 | 2-2310537-1 | 2-2358516-1 | |
| 2310537-2 | 2358516-2 | 3-2310537-2 | 2-2310537-2 | 2-2358516-2 | |
| 2310537-4 | 2358516-4 | 3-2310537-4 | 2-2310537-4 | 2-2358516-4 | |
| 2310537-5 | 2358516-5 | 3-2310537-5 | 2-2310537-5 | 2-2358516-5 | |
| 2310537-6 | 2358516-6 | 3-2310537-6 | 2-2310537-6 | 2-2358516-6 | |
| 2310537-7 | 2358516-7 | 3-2310537-7 | 2-2310537-7 | 2-2358516-7 | |