



28-May-2021

PCN #:P-21-020964

Subject:DYNAMIC D2000series REC/TAB HOUSING

Description of Change: Add alternative material for avoidance of urgent supply tightness risk. Product spec, Customer drawing and UL file number (E28476) are not changed.

Reason: Product improvement. Plastic material faces the delivery risk in worldwide due to unbalance of supply capacity against huge demand increase. By adding alternative material, we try to keep the production and continue supplying our products.

Key Dates:

Contact By Date:01-Sep-2021

Implementation Date:01-Sep-2021

Product Affected	Alias Part Number
-------------------------	--------------------------

2-1318115-4	
-------------	--

1-1318115-9	
-------------	--

3-1318115-6	
-------------	--

2-1318120-3	
-------------	--

9-1318119-4	
-------------	--

1-1318118-9	
-------------	--

2-1318115-6	
-------------	--

2-1318114-6	
-------------	--

9-1318118-6	
-------------	--

1-1318114-4	
-------------	--

2-1318114-9	
-------------	--

1-1473074-3	
-------------	--

1-1318114-9	
-------------	--

9-1318120-3	
-------------	--

Product Affected**Alias Part Number**

2-1318118-6
1-1318116-3
2-1318117-3
2-1318114-3
2-1318118-9
2-1318115-9
9-1318119-3
3-1318120-3
1-1318119-3
3-1318118-9
3-1318118-6
1-1318117-3
1-1318115-4
9-1318118-9
2-1318114-4
1-1318120-3
1-1318118-6
1-1318115-3
1-1318114-6
2-1318116-3
2-1318119-4
1-1318114-3
2-1318115-3
1-1318115-6
2-1318118-8
9-1318118-8
2-1318119-3
1-1318118-8
1-1318119-4

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.

Alert document created by IHS Markit based on content provided by TE Connectivity.