



Product Change Notification

Current Date: 03-Aug-2021

TE Connectivity

Product Change Notification: E-21-005720-C

PCN Date: 02-AUG-21

Customer: TTI, Inc. (3057778)

Location: Maisach-gernlinden

Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

AMPMODU MTE HEADER ASSEMBLIES

Description of Changes

ADDENDUM TO PCN E-20-000624 (ATTACHED). ONE OF THE CHANGES NOTED IN PCN E-20-000624 IS NOT BEING IMPLEMENTED DUE TO FINANCIAL IMPLICATIONS. THE TOOLING CHANGE SHOWN IN THE ATTACHED MTE SHROUDED HEADER TOOLING CHANGE FILE IS BEING MADE TO BE AT THE MOLDER'S DISCRETION. SOME PARTS MAY HAVE THIS RECESSED AREA, SOME MIGHT NOT. THERE IS NO PERFORMANCE DIFFERENCE BETWEEN THE PARTS WITH THE RECESSION AND THE PARTS WITHOUT THE RECESSION.

Reason for Cancellation:

PCN will not clear by the time the system that the EC and PCN were written in is decommissioned. Hence, this ECR and PCN is being cancelled in the old system and will be rewritten in the New EC system.

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
103638-8	NO			"407161207"			
103673-5	NO		TYC103673-5				
5-103634-3	NO		TYC5-103634-3				
5-103635-1	NO		TYC5-103635-1				
5-103635-2	NO		TYC5-103635-2				
5-103635-3	NO		TYC5-103635-3				
5-103635-4	NO		TYC5-103635-4				
5-103635-5	NO		TYC5-103635-5				
5-103635-6	NO		TYC5-103635-6				
5-103635-7	NO		TYC5-103635-7				
5-103639-2	NO		TYC5-103639-2				
5-103639-3	NO		TYC5-103639-3				
5-103639-4	NO		TYC5-103639-4				
5-103639-7	NO		TYC5-103639-7				
5-103639-8	NO		TYC5-103639-8				
5-103669-1	NO		TYC5-103669-1				
5-103669-2	NO		TYC5-103669-2				
5-103669-3	NO		TYC5-103669-3				
5-103673-1	NO		TYC5-103673-1				
5-103673-2	NO		TYC5-103673-2				
5-103673-3	NO		TYC5-103673-3				
5-103673-4	NO		TYC5-103673-4				
5-103735-1	NO		TYC5-103735-1				
5-103735-2	NO		TYC5-103735-2				
5-103735-3	NO		TYC5-103735-3				
5-103735-4	NO		TYC5-103735-4				
5-103735-7	NO		TYC5-103735-7				
5-103735-8	NO		TYC5-103735-8				
5-103904-2	NO		TYC5-103904-2				
5-103904-3	NO		TYC5-103904-3				
5-103908-1	NO		TYC5-103908-1				
5-103908-2	NO		TYC5-103908-2				
5-103908-3	NO		TYC5-103908-3				
5-104361-2	NO		TYC5-104361-2				

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
6-103639-4	NO		TYC6-103639-4				
6-103908-1	NO		TYC6-103908-1				
6-103908-9	NO		TYC6-103908-9				



Product Change Notification

Current Date: 03-Aug-2021

TE Connectivity

Product Change Notification: E-21-005720-C

PCN Date: 02-AUG-21

Customer: TTI, Inc. (1305175)

Location: Maisach-gernlinden

Agreement: TTI001

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:
AMPMODU MTE HEADER ASSEMBLIES

Description of Changes
ADDENDUM TO PCN E-20-000624 (ATTACHED). ONE OF THE CHANGES NOTED IN PCN E-20-000624 IS NOT BEING IMPLEMENTED DUE TO FINANCIAL IMPLICATIONS. THE TOOLING CHANGE SHOWN IN THE ATTACHED MTE SHROUDED HEADER TOOLING CHANGE FILE IS BEING MADE TO BE AT THE MOLDER'S DISCRETION. SOME PARTS MAY HAVE THIS RECESSED AREA, SOME MIGHT NOT. THERE IS NO PERFORMANCE DIFFERENCE BETWEEN THE PARTS WITH THE RECESSION AND THE PARTS WITHOUT THE RECESSION.

Reason for Cancellation:
PCN will not clear by the time the system that the EC and PCN were written in is decommissioned. Hence, this ECR and PCN is being cancelled in the old system and will be rewritten in the New EC system.

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
103634-2	NO		TYC103634-2				
103638-2	NO		TYC103638-2	"407085000"			
103638-3	NO		TYC103638-3				
103638-8	NO			"407161207"			
103673-1	NO		TYC103673-1				
103673-5	NO		TYC103673-5				
103735-9	NO		TYC103735-9				
2-103634-5	NO		TYC2-103634-5				
2-103634-9	NO						
2-103669-6	NO		TYC2-103669-6				
5-103634-3	NO		TYC5-103634-3				
5-103634-4	NO		TYC5-103634-4				
5-103634-5	NO		TYC5-103634-5				
5-103635-1	NO		TYC5-103635-1				
5-103635-2	NO		TYC5-103635-2				
5-103635-3	NO		TYC5-103635-3				
5-103635-4	NO		TYC5-103635-4				
5-103635-5	NO		TYC5-103635-5				
5-103635-6	NO		TYC5-103635-6				
5-103635-7	NO		TYC5-103635-7				
5-103635-8	NO		TYC5-103635-8				
5-103639-2	NO		TYC5-103639-2				
5-103639-3	NO		TYC5-103639-3				
5-103639-4	NO		TYC5-103639-4				
5-103639-5	NO		TYC5-103639-5				
5-103639-7	NO		TYC5-103639-7				
5-103639-8	NO		TYC5-103639-8				
5-103669-1	NO		TYC5-103669-1				
5-103669-2	NO		TYC5-103669-2				
5-103669-3	NO		TYC5-103669-3				
5-103669-4	NO		TYC5-103669-4				
5-103672-2	NO		TYC5-103672-2				
5-103672-3	NO		TYC5-103672-3				
5-103672-4	NO		TYC5-103672-4				

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5-103673-1	NO		TYC5-103673-1				
5-103673-2	NO		TYC5-103673-2				
5-103673-3	NO		TYC5-103673-3				
5-103673-4	NO		TYC5-103673-4				
5-103673-7	NO		TYC5-103673-7	"CW5998-000", "PER-5-103673-7"			
5-103735-1	NO		TYC5-103735-1				
5-103735-2	NO		TYC5-103735-2				
5-103735-3	NO		TYC5-103735-3				
5-103735-4	NO		TYC5-103735-4				
5-103735-5	NO		TYC5-103735-5				
5-103735-6	NO		TYC5-103735-6				
5-103735-7	NO		TYC5-103735-7				
5-103735-8	NO		TYC5-103735-8				
5-103735-9	NO		TYC5-103735-9				
5-103904-2	NO		TYC5-103904-2				
5-103904-3	NO		TYC5-103904-3				
5-103908-1	NO		TYC5-103908-1				
5-103908-2	NO		TYC5-103908-2				
5-103908-3	NO		TYC5-103908-3				
5-103908-4	NO		TYC5-103908-4				
5-103908-5	NO		TYC5-103908-5				
5-103908-7	NO		TYC5-103908-7				
5-104361-1	NO		TYC5-104361-1				
5-104361-2	NO		TYC5-104361-2				
6-103635-2	NO						
6-103635-4	NO		TYC6-103635-4				
6-103639-3	NO		TYC6-103639-3				
6-103639-4	NO		TYC6-103639-4				
6-103735-3	NO		TYC6-103735-3				
6-103735-5	NO		TYC6-103735-5				
6-103908-1	NO		TYC6-103908-1				
6-103908-9	NO		TYC6-103908-9				
7-103673-3	NO		TYC7-103673-3				
7-103735-4	NO		TYC7-103735-4				

The documents listed below are being modified. Related parts that are not explicitly listed on this PCN are not being modified or discontinued as per the PCN. The Last Order Date, Last Ship Date, First Date to Ship Changed Parts and last date for Mixed Shipments apply only to parts explicitly listed on this PCN.

Customer Drawing(s) Being Modified:

Drawing Number	Related Part Number	Customer Part Number	Current Revision	New Revision
103634	103634-2	TYC103634-2	W	
103635	5-103635-1	TYC5-103635-1	U	
103638	103638-2	TYC103638-2	T	
103639	5-103639-2	TYC5-103639-2	AA	
103669	5-103669-1	TYC5-103669-1	AC	
103672	5-103672-2	TYC5-103672-2	AE	
103673	103673-1	TYC103673-1	V	
103735	103735-9	TYC103735-9	W	
103904	5-103904-2	TYC5-103904-2	S	
103908	5-103908-1	TYC5-103908-1	S	
104361	5-104361-1	TYC5-104361-1	S	