



Product Change Notification

Current Date: 16-Aug-2021

TE Connectivity

Product Change Notification: P-21-021319

PCN Date: 13-AUG-21

Customer: TTI, Inc. (1305175)

Location: Maisach-gernlinden

Agreement: TTI001

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

HCR150 and HCR200

Description of Changes

Copper strip supplier change. The components affected by this change are the load terminals.

Reason for Changes:

Document clarification. Due to the recent floods in Germany our current copper strip supplier has no sufficient capacity to supply our demands. To counter this special situation and to position TE better within the global supply crisis caused by the Covid-19 pandemic, we inform you in advance that we intend to use an alternative copper strip supplier on our HCR relay family otherwise TE will not be able to produce parts and fulfill our delivery obligations. The alternative copper strip supplier already supplies other TE facilities and the copper material is certified against the same internal TE specifications.

Estimated Dates:

Last Order Date (Obsolete Parts Only):

First Date To Ship (Changed Parts Only):

16-AUG-2021

Last Ship Date (Obsolete Parts Only):

Last Date for Mixed Shipments: (Changed Parts Only):

31-AUG-2021

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-1393315-1	NO		TYC1-1393315-1	"V23132B2002B200"			
1-1414476-0	NO		TYC1-1414476-0	V23132-A2001-X023			
1393315-2	NO			"V23132A2001A200"			
1393315-9	NO		TYC1393315-9	"V23132B2002A200"			
1416010-1	NO		TYC1416010-1	"V23132-A2001-B200"			
1416010-4	NO		TYC1416010-4	"V23132-A2001-X020"			
9-1415001-5	NO		TYC9-1415001-5	CZ1474-000, V23132-E2001-A200			



Product Change Notification

Current Date: 16-Aug-2021

TE Connectivity

Product Change Notification: P-21-021319

PCN Date: 13-AUG-21

Customer: TTI, Inc. (3057778)

Location: Maisach-gernlinden

Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

HCR150 and HCR200

Description of Changes

Copper strip supplier change. The components affected by this change are the load terminals.

Reason for Changes:

Document clarification. Due to the recent floods in Germany our current copper strip supplier has no sufficient capacity to supply our demands. To counter this special situation and to position TE better within the global supply crisis caused by the Covid-19 pandemic, we inform you in advance that we intend to use an alternative copper strip supplier on our HCR relay family otherwise TE will not be able to produce parts and fulfill our delivery obligations. The alternative copper strip supplier already supplies other TE facilities and the copper material is certified against the same internal TE specifications.

Estimated Dates:

Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	16-AUG-2021
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	31-AUG-2021

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-1393315-1	NO		TYC1-1393315-1	"V23132B2002B200"			
1-1414476-0	NO		TYC1-1414476-0	V23132-A2001-X023			
1393315-2	NO			"V23132A2001A200"			
1393315-9	NO		TYC1393315-9	"V23132B2002A200"			
1416010-1	NO		TYC1416010-1	"V23132-A2001-B200"			
1416010-4	NO		TYC1416010-4	"V23132-A2001-X020"			
9-1415001-5	NO		TYC9-1415001-5	CZ1474-000, V23132-E2001-A200			