



03-Feb-2022

PCN #: P-22-022121

Subject : B-802, D-110, D-112, D-128, D-129. D-136, D-141, D-181, D-183, D-210, D-607, D-104, MK-0015, MK-0020, D-150.

Description of Change : SolderSleeve devices that required ROL1 flux were supplied with ROL0 flux.

Reason : Document clarification. The PCN is to inform that SolderSleeve listed should be using ROL1 flux instead ROL0 flux were supplied. TE connectivity qualified ROL1 flux on August 27, 2021

Key Dates :

Contact By Date:23-Nov-2021

Implementation Date:23-Nov-2021

Product Affected	Alias Part Number	Substitute Part Number	AliasSub Part Number
CZ5794-000			
124731-000	"7-1190906-7"		
955477-000	"7-1197397-2"		
625307N004	"1201455-6", "D-141-0108CS407C SG"		
625293N007	"8-1194950-3", "D-141-0111CS2725"		
581628-000	"1-1194608-4", "D-181-2226-90/9"		
6251590003	"3-1194948-0"		
625160N003	"3-1194948-6", "D-110-41CS1290"		

721038-000	"5-1195638-1", "D-181-1226-90/9"		
080771-000	"4-1190599-2", "D-141-0171"		
626177-000	"7-1194959-7", "D-704-0062"		
625234-000	"7-1194949-5", "D-141-0093"		
CM7095-000			
115535-000	"1190842-2"		
CF3418-000	"D-210-0213"		
426547-000	"1193210-4"		
601156-000	"6-1194758-2"		
689161-000	"4-1195412-1"		
625144-000	"1194948-1", "D-128-04"		
695296-000	"5-1195454-7"		
625157-000	"2-1194948-0"		
6242920001	"5-1194938-4", "D-146-0180"		
391911-000	"1-1192941-8", "D-110-0124"		
625127-000	"7-1194947-1", "D-141-56"		
625015N002	"3-1194945-8", "D-141-07CS1212"		
CR3737-000			
260297-000	"4-1191904-8", "D-181-1224-90/9CS554"		
395947-000	"1-1192970-7", "D-181-1222-90/9CS2800"		

624292-000	"5-1194938-3", "D-146-0180"		
635867-000	"8-1195027-7", "D-141-0113CS555"		
CR3768-000			
625351-000	"1194952-8", "D-129-0043"		
953092-000	"1-1198257-6", "D-141-0112CS1812"		
838065-000	"6-1196540-8", "D-141-0112CS370"		
625293-000	"7-1194950-6", "D-141-0111"		
A12306-000	"3-1201725-7"		
625159N004	"3-1194948-1", "D-110-35CS1290"		
434903-000	"3-1193270-7", "D-183-0038"		
1098580005	"4-1190802-3", "D-181-1222-90/9CS936"		
625016N002	"4-1194945-1", "D-141-13CS2494"		
CU3211-000			
477885-000	"8-1193578-6", "D-181-1224-90/9CS2619"		
898873-000	"8-1196986-4"		
6250570003	"5-1194946-3", "D-141-24CS2492"		
179544N003	"2-1191305-2", "D-181-2222-90/9CS2619"		
109858N001			
209211-000	"2-1191516-2"		

094103-000	"9-1190689-0"		
625289-000	"6-1194950-9", "D-141-0103"		
586723-000	"9-1194643-8", "D-141-0111CS512"		
540061-000	"7-1194236-2", "D-141-0112CS555"		
350354-000	"4-1199413-9", "D-141-51CS1199"		
192717-000	"1191398-1", "D-110-0172"		
326791-000	"7-1192472-6", "D-181-2222-90/9CS298"		
625022N003	"5-1194945-9", "D-110-00CS706"		
947687-000	"7-1197332-9", "D-150-9134"		
625003-000	"1194945-5", "D-136-02"		
109858N006	"5-1200714-2", "D-181-1222-90/9CS403"		
601164-000	"7-1194758-0"		
022689-000	"7-1190175-1"		
A35141-000	"6-1201422-0", "MK-0020-100"		
625293N006	"8-1194950-2", "D-141-0111CS1095"		
EG5014-000	"D-181-1222-90/9-CS4094"		
1795440004	"2-1191305-1", "D-181-2222-90/9CS1270"		
947687N001	"4-1200878-1", "D-150-9134CS2873"		

514861-000	"1-1194044-5", "D-181-2222-90/9CS1802"		
625008-000	"2-1194945-0", "D-129-03"		
6250220004	"5-1194945-8", "D-110-00CS1290"		
626162-000	"4-1194959-8", "D-704-0049"		
330063-000	"3-1192494-8"		
521076N001	"7-1194095-7"		
173557-000	"4-1191262-7", "D-141-0228"		
109858-000	"3-1190802-9"		
525725-000	"3-1194131-6", "D-141-0114CS370"		
957281-000	"8-1197410-3", "D-181-2222-90/9CS554"		
385193N007	"D-181-2224-90/9-CS610C"		
484153-000	"1-1193623-8", "D-110-28-RS"		
601045-000	"3-1194756-0", "D-607-03"		
CX2428-000			
625157N004	"2-1194948-4", "D-110-28CS1290"		
625250-000	"1194950-6", "D-128-0008"		
734135-000	"7-1195733-3", "D-181-1830-6-9CS584"		
625006-000	"1-1194945-3", "D-136-21"		

625057-000	"5-1194946-1", "D-141-24"		
CR6405-000			
601164N003	"7-1194758-3", "D-607-18CS220"		
601061N003	"5-1194756-0", "D-607-04-HCS220"		
CJ4552-000	"D-141-30-LF"		
205396-000	"4-1198252-8", "D-141-31CS1398"		
625307N002	"3-1194951-5", "D-141-0108CS404"		
977915-000	"3-1197555-3", "D-112-1224-9"		
CR4093-000			
CY0718-000			
372141-000	"5-1192787-5", "D-183-0037"		
625232-000	"7-1194949-0", "D-141-0091"		
812388-000	"8-1199648-5", "D-181-2222-90/9CS1384"		
521076-000	"7-1194095-4"		
F77309-000	"1-1201296-2", "D-110-41CS2885"		
625053-000	"4-1194946-5", "D-141-35"		
3099740002	"1192347-9"		
CL3203-000	"D-181-2222-90/9CS2920"		
689161N001	"4-1195412-2", "D-112-1222-9CS936"		

736913-000	"9-1195753-1", "D-141-0171CS1470"		
269550-000	"4-1191989-9"		
501703-000	"6-1193750-1"		
625159-000	"2-1194948-7"		
254033-000	"8-1191859-2"		

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.

Alert document created by IHS Markit based on content provided by TE Connectivity.