



# Product Change Notification

Current Date: 07-Feb-2022

## TE Connectivity

**Product Change Notification:** P-22-022131

**PCN Date:** 07-FEB-22

**Customer:** TTI Inc(0000139702)

**Location:** WORLDWIDE

**Agreement:** Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

**General Product Description:**

Blow molded Parts

**Description of Changes**

The raw material secondary operations manufacturing location for blow molding elastomer compound will be transferred from TE Connectivity Menlo Park, CA to TE Connectivity Redwood City, CA. The main compound manufacturing location remains the same and the blow molding manufacturing site will remain at the TE Connectivity Tijuana facility.

**Reason for Changes:**

Dear Customer, we hereby inform you about a transfer of tools and/or processes. The transfer follows a strict procedure, which fully maintains quality, the ability to supply, as well as the form, fit, and function of the concerned products. The new manufacturing location operates under a certified quality management system in accordance with standard AS9100. Internal testing, based on the relevant part specifications, will be executed before delivery. Upon request, a first article inspection (FAI) report will be available if it concerns a component of a TE-product, where the production location of the finished TE-product remains unchanged. If you require a FAI report, please notify the responsible TE Sales Contact.

**Estimated Dates:**

<b>Last Order Date</b> (Obsolete Parts Only):	<b>First Date To Ship</b> (Changed Parts Only):
	16-MAY-2022
<b>Last Ship Date</b> (Obsolete Parts Only):	<b>Last Date for Mixed Shipments:</b> (Changed Parts Only):
	No Mixed Shipments

**Part Number(s) being Modified:**

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">057837-000</a>	NO			"2-1190439-1", "202F221-51/164-0"			
<a href="#">080534-000</a>	NO			"7-1190597-0", "202F232-51/164-0"			
<a href="#">120005-000</a>	NO			"1-1190873-0", "222F263-51/164-0"			
<a href="#">122343-000</a>	NO			"1-1190890-7", "202C653-51/86-0"			
<a href="#">129263-000</a>	NO			"8-1190938-3", "202F263-51/164-0"			
<a href="#">184375-000</a>	NO			"8-1191338-1", "202F221-51-02/164-0"			
<a href="#">199339-000</a>	NO			"9-1191443-1", "202F221-51-22/164-0"			
<a href="#">298805-000</a>	NO			"202F263-51-0", "5-1192262-8"			
<a href="#">307219-000</a>	NO			"202F232-51/86-0", "1-1192327-1"			
<a href="#">352327-000</a>	NO			"222F232-51-02/164-0", "8-1192647-0"			
<a href="#">379737-000</a>	NO			"202F211-51-22/164-0", "2-1192840-6"			
<a href="#">396722-000</a>	NO			"222F211-51/164-0", "9-1192975-2"			
<a href="#">402801N001</a>	NO			"202F211-51-02-0-CS5422", "7-1193040-1"			
<a href="#">425521-000</a>	NO			"202C632-51/86-0", "1193203-7"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">430328-000</a>	NO			"202C621-51/164-0", "1-1193237-9"			
<a href="#">434863-000</a>	NO			"222F221-51/164-0", "1193270-9"			
<a href="#">476393-000</a>	NO			"222F221-51/86-0", "1-1193568-5"			
<a href="#">512452-000</a>	NO			"202C632-51/164-0", "9-1194026-3"			
<a href="#">515697-000</a>	NO			"202F221-51/86-0", "1-1194050-5"			
<a href="#">518337-000</a>	NO			"202F211-51-07-0", "6-1194068-4"			
<a href="#">538259-000</a>	NO			"202F242-51/86-0", "5-1194224-5"			
<a href="#">584831-000</a>	NO			"202C611-50/86-0", "1194631-8"			
<a href="#">662779-000</a>	NO			"222F242-51-02/164-0", "4-1195224-0"			
<a href="#">693924-000</a>	NO			"202F242-51/164-0", "1195445-9"			
<a href="#">705755-000</a>	NO			"202F242-51-22/164-0", "6-1195534-7"			
<a href="#">721355-000</a>	NO			"202F232-51-22/164-0", "6-1195640-9"			
<a href="#">752055-000</a>	NO			"222F211-51-22/164-0", "8-1195863-5"			
<a href="#">770228-000</a>	NO			"222F211-51-0", "2-1196001-2"			
<a href="#">778667-000</a>	NO			"202F253-51-22/164-0", "5-1196060-4"			
<a href="#">806233-000</a>	NO			"202C611-50-0", "1-1196233-3"			
<a href="#">806234-000</a>	NO			"202C621-50-0", "1-1196233-8"			
<a href="#">806235-000</a>	NO			"202C632-50-0", "2-1196233-2"			
<a href="#">806236-000</a>	NO			"202C642-50-0", "2-1196233-7"			
<a href="#">806237-000</a>	NO			"202C653-50-0", "3-1196233-2"			
<a href="#">806245-000</a>	NO			"202C642-51/86-0", "3-1196233-8"			
<a href="#">806250-000</a>	NO			"202C611-51-0", "4-1196233-9"			
<a href="#">806251-000</a>	NO			"202C621-51-0", "5-1196233-3"			
<a href="#">806252-000</a>	NO			"202C632-51-0", "5-1196233-8"			
<a href="#">806253-000</a>	NO			"202C642-51-0", "6-1196233-3"			
<a href="#">806254-000</a>	NO			"202C653-51-0", "6-1196233-6"			
<a href="#">811551-000</a>	NO			"202F211-50-0", "8-1196311-0"			
<a href="#">811554-000</a>	NO			"202F242-50-0", "9-1196311-0"			
<a href="#">819112-000</a>	NO			"222F242-51-0", "3-1196383-8"			
<a href="#">819115-000</a>	NO			"202F211-51-0", "5-1196383-0"			
<a href="#">819116-000</a>	NO			"202F221-51-0", "5-1196383-4"			
<a href="#">819117-000</a>	NO			"202F232-51-0", "5-1196383-8"			
<a href="#">819118-000</a>	NO			"202F242-51-0", "6-1196383-2"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">819119-000</a>	NO			"202F253-51-0", "6-1196383-6"			
<a href="#">857940-000</a>	NO			"202F253-51/164-0", "3-1196686-4"			
<a href="#">868601-000</a>	NO			"202F211-51/164-0", "1-1196762-1"			
<a href="#">879492-000</a>	NO			"202C621-51/86-0", "3-1196847-2"			
<a href="#">922143-000</a>	NO			"202F211-51/86-0", "8-1197154-5"			
<a href="#">925906-000</a>	NO			"202C611-51/164-0", "2-1197181-2"			

Customer: TTI, Inc. ( 1305175 )

Location: Maisach-germlinden

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">430328-000</a>	NO		RAY430328-000	"202C621-51/164-0", "1-1193237-9"			
<a href="#">806234-000</a>	NO		RAY806234-000	"202C621-50-0", "1-1196233-8"			
<a href="#">806235-000</a>	NO		RAY806235-000	"202C632-50-0", "2-1196233-2"			
<a href="#">806236-000</a>	NO		RAY806236-000	"202C642-50-0", "2-1196233-7"			

Customer: TTI, Inc. ( 3057778 )

Location: Maisach-germlinden

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">430328-000</a>	NO		RAY430328-000	"202C621-51/164-0", "1-1193237-9"			
<a href="#">806234-000</a>	NO		RAY806234-000	"202C621-50-0", "1-1196233-8"			
<a href="#">806235-000</a>	NO		RAY806235-000	"202C632-50-0", "2-1196233-2"			
<a href="#">806236-000</a>	NO		RAY806236-000	"202C642-50-0", "2-1196233-7"			

Customer: TTI Inc ( 168830 )

Location: Fort Worth

Agreement Number: TTI003

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">057837-000</a>	NO			"2-1190439-1", "202F221-51/164-0"			
<a href="#">080534-000</a>	NO			"7-1190597-0", "202F232-51/164-0"			
<a href="#">129263-000</a>	NO			"8-1190938-3", "202F263-51/164-0"			
<a href="#">199339-000</a>	NO			"9-1191443-1", "202F221-51-22/164-0"			
<a href="#">298805-000</a>	NO			"202F263-51-0", "5-1192262-8"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">307219-000</a>	NO			"202F232-51/86-0", "1-1192327-1"			
<a href="#">352327-000</a>	NO			"222F232-51-02/164-0", "8-1192647-0"			
<a href="#">396722-000</a>	NO			"222F211-51/164-0", "9-1192975-2"			
<a href="#">430328-000</a>	NO			"202C621-51/164-0", "1-1193237-9"			
<a href="#">434863-000</a>	NO			"222F221-51/164-0", "1193270-9"			
<a href="#">512452-000</a>	NO			"202C632-51/164-0", "9-1194026-3"			
<a href="#">515697-000</a>	NO			"202F221-51/86-0", "1-1194050-5"			
<a href="#">518337-000</a>	NO			"202F211-51-07-0", "6-1194068-4"			
<a href="#">538259-000</a>	NO			"202F242-51/86-0", "5-1194224-5"			
<a href="#">693924-000</a>	NO			"202F242-51/164-0", "1195445-9"			
<a href="#">705755-000</a>	NO			"202F242-51-22/164-0", "6-1195534-7"			
<a href="#">721355-000</a>	NO			"202F232-51-22/164-0", "6-1195640-9"			
<a href="#">770228-000</a>	NO			"222F211-51-0", "2-1196001-2"			
<a href="#">806233-000</a>	NO			"202C611-50-0", "1-1196233-3"			
<a href="#">806234-000</a>	NO			"202C621-50-0", "1-1196233-8"			
<a href="#">806235-000</a>	NO			"202C632-50-0", "2-1196233-2"			
<a href="#">806236-000</a>	NO			"202C642-50-0", "2-1196233-7"			
<a href="#">806237-000</a>	NO			"202C653-50-0", "3-1196233-2"			
<a href="#">806250-000</a>	NO			"202C611-51-0", "4-1196233-9"			
<a href="#">806251-000</a>	NO			"202C621-51-0", "5-1196233-3"			
<a href="#">806252-000</a>	NO			"202C632-51-0", "5-1196233-8"			
<a href="#">806253-000</a>	NO			"202C642-51-0", "6-1196233-3"			
<a href="#">806254-000</a>	NO			"202C653-51-0", "6-1196233-6"			
<a href="#">819112-000</a>	NO			"222F242-51-0", "3-1196383-8"			
<a href="#">819115-000</a>	NO			"202F211-51-0", "5-1196383-0"			
<a href="#">819116-000</a>	NO			"202F221-51-0", "5-1196383-4"			
<a href="#">819117-000</a>	NO			"202F232-51-0", "5-1196383-8"			
<a href="#">819118-000</a>	NO			"202F242-51-0", "6-1196383-2"			
<a href="#">819119-000</a>	NO			"202F253-51-0", "6-1196383-6"			
<a href="#">857940-000</a>	NO			"202F253-51/164-0", "3-1196686-4"			
<a href="#">868601-000</a>	NO			"202F211-51/164-0", "1-1196762-1"			
<a href="#">922143-000</a>	NO			"202F211-51/86-0", "8-1197154-5"			
<a href="#">925906-000</a>	NO			"202C611-51/164-0", "2-1197181-2"			

Customer: TTI Inc ( 1281288 )

Location: Fort Worth

Agreement Number: TTI002

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">057837-000</a>	NO			"2-1190439-1", "202F221-51/164-0"			
<a href="#">080534-000</a>	NO			"7-1190597-0", "202F232-51/164-0"			
<a href="#">120005-000</a>	NO			"1-1190873-0", "222F263-51/164-0"			
<a href="#">122343-000</a>	NO			"1-1190890-7", "202C653-51/86-0"			
<a href="#">184375-000</a>	NO			"8-1191338-1", "202F221-51-02/164-0"			
<a href="#">298805-000</a>	NO			"202F263-51-0", "5-1192262-8"			
<a href="#">307219-000</a>	NO			"202F232-51/86-0", "1-1192327-1"			
<a href="#">352327-000</a>	NO			"222F232-51-02/164-0", "8-1192647-0"			
<a href="#">379737-000</a>	NO			"202F211-51-22/164-0", "2-1192840-6"			
<a href="#">396722-000</a>	NO			"222F211-51/164-0", "9-1192975-2"			
<a href="#">402801N001</a>	NO			"202F211-51-02-0-CS5422", "7-1193040-1"			
<a href="#">425521-000</a>	NO			"202C632-51/86-0", "1193203-7"			
<a href="#">430328-000</a>	NO			"202C621-51/164-0", "1-1193237-9"			
<a href="#">434863-000</a>	NO			"222F221-51/164-0", "1193270-9"			
<a href="#">476393-000</a>	NO			"222F221-51/86-0", "1-1193568-5"			
<a href="#">512452-000</a>	NO			"202C632-51/164-0", "9-1194026-3"			
<a href="#">515697-000</a>	NO			"202F221-51/86-0", "1-1194050-5"			
<a href="#">538259-000</a>	NO			"202F242-51/86-0", "5-1194224-5"			
<a href="#">584831-000</a>	NO			"202C611-50/86-0", "1194631-8"			
<a href="#">662779-000</a>	NO			"222F242-51-02/164-0", "4-1195224-0"			
<a href="#">693924-000</a>	NO			"202F242-51/164-0", "1195445-9"			
<a href="#">705755-000</a>	NO			"202F242-51-22/164-0", "6-1195534-7"			
<a href="#">721355-000</a>	NO			"202F232-51-22/164-0", "6-1195640-9"			
<a href="#">752055-000</a>	NO			"222F211-51-22/164-0", "8-1195863-5"			
<a href="#">770228-000</a>	NO			"222F211-51-0", "2-1196001-2"			
<a href="#">778667-000</a>	NO			"202F253-51-22/164-0", "5-1196060-4"			
<a href="#">806233-000</a>	NO			"202C611-50-0", "1-1196233-3"			
<a href="#">806234-000</a>	NO			"202C621-50-0", "1-1196233-8"			
<a href="#">806235-000</a>	NO			"202C632-50-0", "2-1196233-2"			
<a href="#">806236-000</a>	NO			"202C642-50-0", "2-1196233-7"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">806245-000</a>	NO			"202C642-51/86-0", "3-1196233-8"			
<a href="#">806250-000</a>	NO			"202C611-51-0", "4-1196233-9"			
<a href="#">806251-000</a>	NO			"202C621-51-0", "5-1196233-3"			
<a href="#">806252-000</a>	NO			"202C632-51-0", "5-1196233-8"			
<a href="#">806253-000</a>	NO			"202C642-51-0", "6-1196233-3"			
<a href="#">806254-000</a>	NO			"202C653-51-0", "6-1196233-6"			
<a href="#">811551-000</a>	NO			"202F211-50-0", "8-1196311-0"			
<a href="#">811554-000</a>	NO			"202F242-50-0", "9-1196311-0"			
<a href="#">819112-000</a>	NO			"222F242-51-0", "3-1196383-8"			
<a href="#">819115-000</a>	NO			"202F211-51-0", "5-1196383-0"			
<a href="#">819116-000</a>	NO			"202F221-51-0", "5-1196383-4"			
<a href="#">819117-000</a>	NO			"202F232-51-0", "5-1196383-8"			
<a href="#">819118-000</a>	NO			"202F242-51-0", "6-1196383-2"			
<a href="#">819119-000</a>	NO			"202F253-51-0", "6-1196383-6"			
<a href="#">857940-000</a>	NO			"202F253-51/164-0", "3-1196686-4"			
<a href="#">868601-000</a>	NO			"202F211-51/164-0", "1-1196762-1"			
<a href="#">879492-000</a>	NO			"202C621-51/86-0", "3-1196847-2"			
<a href="#">922143-000</a>	NO			"202F211-51/86-0", "8-1197154-5"			
<a href="#">925906-000</a>	NO			"202C611-51/164-0", "2-1197181-2"			