



17-Feb-2022

**PCN #:** PCN-22-128545

**Subject :** Heat Shrink Tubing Stick (-STK) products

**Description of Change :** This PCN is to inform customers of changes to the packaging of the boxes used for the Heat Shrink Tubing products supplied in the Stick format (-STK, 1.2metre/4ft lengths). For more clarification check reference attachments

**Reason :**

**Key Dates :**

**Contact By Date:**04-Feb-2022

**Implementation Date:**04-Feb-2022

<b>Product Affected</b>	<b>Alias Part Number</b>	<b>Substitute Part Number</b>	<b>AliasSub Part Number</b>
4601932001	"8-1193451-0", "FPO-3/8-4-STK"		
8938892001	"2-1196952-1", "FPO-2-X-STK"		
1124012001	"3-1190820-0", "FPO-1-1/2-9-STK"		
199935L004	"9-1191447-9", "FPO-3/16-0-STK"		
E25625-000	"2-1201741-7", "SCL-3/16-0-STK-CS7793"		
360603L002	"1192705-3", "DWP-125-3/4-4-STK"		
636901P014	"8-1195035-6", "QS1500-NO.3-F7-0-STK"		

550004L023	"7-1194328-3", "SCL-3/8-2-STK-CS5930"		
5454052004	"RW-175-1/2-0-STK"		
CZ0181-000	"SCT-NO.5-Z4-0-STK"		
829131P021	"7-1196474-9", "ES2000-NO.1-C1-0-STK"		
5380932001	"3-1194223-3", "FPO-1/4-4-STK"		
4243952001	"3-1193195-3", "FPO-1/2-5-STK"		
550106L022	"1-1194340-8", "SCL-1-0-STK-CS6214"		
895231P008	"5-1196961-1", "SCT-NO.0-E8-0-STK"		
5233452001	"6-1194111-2", "DWP-125-3/8-2-STK"		
048951L002	"6-1190375-1", "DWP-125-3/8-9-STK"		
CV3397-000			
0737652001	"9-1190551-7", "FPO-3/32-2-STK"		
EM63392001	"BATTU-20.1/8.9-A1-3-STK"		
F61851-000	"1-1201234-8", "SCL-1/8-2-STK"		
4243712001	"1-1193195-7", "FPO-3/64-6-STK"		
1277872001	"8-1190928-4", "FPO-1/16-0-STK"		

D20444-000	"1-1199653-5", "FL2500-NO.1-I8-0-STK"		
1213976045	"2-1190883-3", "ES2000-NO.3-A1-0-STK"		
4511072001	"9-1193387-4", "FPO-1-4-STK"		
EH2289-000	"DWFR-6/2-0-STK"		
2961252001	"2-1192243-9", "FPO-1-X-STK"		
193197P005	"4-1191401-8", "ES1000-NO.1-A1-X-STK"		
349747-000	"4-1192631-2", "GPA-3/4-0-STK"		
848111-000	"2-1196614-0", "FPO-1-1/4-2-STK"		
9441232001	"4-1197308-6", "FPO-3/64-0-STK"		
1488852001	"3-1191076-7", "FPO-1-5-STK"		
642293-000	"1195076-9", "SCL-1/4-2-STK"		
5076682002	"DWP-125-3/4-0-STK", "1448810-3"		
EH2301-000	"DWFR-52/13-0-STK"		
CV3407-000			
E95757-000	"4-1199653-3", "FL2500-NO.4-J2-0-STK"		
5058772008	"1-1193908-1", "VERSAFIT-3/8-9-STK"		
CV3332-000			

C21246-000	"6-1201073-1", "TPEM-NR503-0-STK-CS5769"		
EH2291-000	"DWFR-12/4-0-STK"		
E43149-000	"3-1199653-6", "FL2500-NO.2-I9-0-STK"		
363884-000	"1-1199654-7", "FL2500-NO.3-J1-0-STK"		
576105P004	"7-1194570-9", "ES1000-NO.2-B9-X-STK"		
EH2296-000	"DWFR-8/2-0-STK"		
NB07172001	"BATTU-25.4/12.7-A1-2-STK", "7-1899840-6"		
196714-000	"5-1197928-3", "GPA-3/8-X-STK"		
CR2074-000			
1328812001	"3-1190965-7", "FPO-1/4-1-STK"		
534614-000	"2-1197968-2", "SCL-3/16-0-STK-CS7315"		
9588192002	"3-1197422-4", "FPO-1-0-STK"		
128766-000	"2-1201234-8", "SCL-3/4-2-STK"		
4651252001	"4-1193487-7", "FPO-3/4-X-STK"		
0016072001	"1190012-9", "DWP-125-1-2-STK"		
EM64322001	"BATTU-20.1/8.9-A1-4-STK"		

4275052001	"6-1193216-4", "FPO-3/32-6-STK"		
F84496-000	"1200968-7", "TPEM-NR7-0-STK-CS7760"		
253881-000	"7-1191858-0", "GPA-4-0-STK"		
5628512001	"1-1194447-5", "FPO-1/16-4-STK"		
2088852001	"8-1191513-2", "FPO-3/32-5-STK"		
5500102028	"2-1194329-8", "SCL-1/8-0-STK"		
5500852001	"8-1194337-3", "SCL-1/2-2-STK"		
305063-000	"1192310-3", "GPA-1-1/2-0-STK"		
8954932001	"3-1196963-6", "FPO-3/32-0-STK"		
EM63952001	"BATTU-12.7/6.1-A1-4-STK"		
006492-000	"4-1197923-2", "FPO-1/4-X-STK-BULK"		
985463-000	"1197613-4", "FPO-1-1/4-X-STK"		
035377P008	"5-1190273-2", "ES1000-NO.3-A1-X-STK"		
867538-000	"7-1199427-8", "SCL-3/4-0-STK-CS7315"		
6083312001	"7-1194811-1", "FPO-3/32-4-STK"		

E12167-000	"8-1200617-1", "HSP2000-NO.3-N8-0-STK"		
5501092019	"3-1194340-1", "SCL-1/4-0-STK"		
0471982001	"7-1190362-8", "DWP-125-1/2-2-STK"		
NB07152001	"BATTU-25.4/12.7-A1-0-STK", "7-1899840-7"		
4393892002	"1193302-3", "FPO-1/16-5-STK"		
CL9157-000	"DWP-125-1/4-6-STK"		
CP4919-000	"5-1899572-2"		
550109L035	"1194341-6", "SCL-1/4-0-STK-CS5799"		
CP4937-000	"7-1899572-0", "ES2000-NO.4-B7-0-STK-SH"		
CV3409-000			
7824712001	"5-1196077-3", "FPO-1/16-9-STK"		
8976812001	"6-1196978-1", "FPO-1/4-2-STK"		
2266412001	"8-1191668-1", "DWP-125-1/4-2-STK"		
EH2295-000	"DWFR-4/1-0-STK"		
CR2075-000			
2445812002	"2-1191794-3", "FPO-3/8-2-STK"		
3809832001	"6-1192848-1", "FPO-1/2-6-STK"		

5500312016	"8-1194332-3", "SCL-1/2-0-STK"		
130599P006	"6-1190948-4", "ES2000-NO.4-B7-0-STK"		
NB07092001	"BATTU-12.7/6.1-A1-2-STK", "8-1899840-3"		
9210472001	"6-1197146-3", "FPO-1/8-0-STK"		
F72283-000	"1201280-7", "FPO-4X-NO.3-0-STK"		
EH2299-000	"DWFR-24/6-0-STK"		
2965652001	"6-1192246-5", "FPO-1-9-STK"		
0536852001	"1190410-4", "FPO-3/16-5-STK"		
9346692002	"2-1197242-1", "DWP-125-1-0-STK"		
5500042003	"5-1194328-8", "SCL-3/8-2-STK"		
EM63332001	"BATTU-12.7/6.1-A1-3-STK"		
EH2288-000	"DWFR-3/1-0-STK"		
D94815-000	"3-1200881-2", "SCL-1/8-0-STK-CS5279"		
2173252001	"2-1191586-4", "FPO-3/16-4-STK"		
EH2300-000	"DWFR-32/8-0-STK"		
ER0470-000			
NB38262001			
EH2290-000	"DWFR-9/3-0-STK"		

D76722-000	"1200973-1", "TPEM- NR502-0- STK-CS5769"		
A40043-000	"5-1201704- 9", "FPO-4X- NO.2-0-STK"		
8430572001	"5-1196576- 3", "FPO-3-0- STK"		
CS8867-000			
CV3300-000	"RW-175- 1/16-X-STK", "16-0113", "1012482-F"		
CU4089-000			
6524372001	"1195150-8", "FPO-1-1/2-6- STK"		
CV3307-000			
761895-000	"4-1195933- 8", "GPA-3-0- STK"		
5967492001	"7-1194719- 1", "FPO- 3/64-2-STK"		
838558-000	"6-1200265- 7", "HSP2000- NO.1-N6-0- STK"		
206247P038	"2-1191495- 7", "SCT- NO.4-E2-0- STK"		
CV6465-000			
5113132001	"1-1194019- 9", "FPO-3/8- X-STK"		
8491932001	"7-1196621- 4", "FPO-1/8- 2-STK"		
8579432001	"3-1196686- 8", "FPO-1/4- 0-STK"		
CV3305-000			
550105L021	"5-1194339- 8", "SCL-3/4- 0-STK- CS5279"		



CV3304-000			
0711012001	"2-1190534-3", "FPO-3/4-5-STK"		
8563892001	"8-1196674-8", "FPO-1-1/2-2-STK"		
CV3308-000			
2149152001	"1-1191552-9", "FPO-3/8-9-STK"		
CS8868-000			
063725P049	"8-1190481-0", "ES2000-NO.2-A1-0-STK"		
NB07072001	"BATTU-12.7/6.1-A1-0-STK", "8-1899840-5"		
1981252001	"6-1191435-0", "FPO-3/4-6-STK"		
ER0469-000			
CV3404-000			
893778-000	"1-1200436-7", "HSP2000-NO.4-N9-0-STK"		
537637P041	"8-1194219-5", "SCT-NO.3-E3-0-STK"		
5500332008	"6-1194333-4", "SCL-3/16-2-STK"		
550019L028	"1194331-8", "SCL-3/8-0-STK-CS6073"		
0517992002	"6-1190396-4", "RP-4800-NO.1-4-STK"		
CL9599-000	"SCL-1-0-STK-CS7315"		
3668272001	"2-1192750-5", "FPO-1/8-9-STK"		

7629592001	"1195941-1", "FPO-1/4-9- STK"		
6009112002	"7-1194754- 0", "DWP- 125-3/16-0- STK"		
4625672001	"2-1193469- 3", "FPO- 3/16-2-STK"		
550010L046	"1-1194330- 4", "SCL-1/8- 0-STK- CS6073"		
193197P004	"4-1191401- 7", "ES1000- NO.1-C1-X- STK"		
3086372001	"6-1192337- 7", "FPO- 1/16-6-STK"		
8572332001	"9-1196680- 5", "FPO-1- 1/2-4-STK"		
9170152001	"1-1197118- 5", "DWP- 125-2-0-STK"		
6465212003	"114517-01", "1448193-1", "DWP-125- 1/2-0-STK", "16-0149"		
4846272001	"4-1193626- 8", "FPO-1/8- 4-STK"		
5501062005	"7-1194339- 5", "SCL-1-0- STK"		
CV3387-000			
EM64392001	"BATTU- 25.4/12.7-A1- 4-STK"		
1308412002	"2-1190951- 1", "FPO- 3/16-6-STK"		
E07303-000	"3-1200881- 6", "SCL-3/8- 0-STK- CS5279"		
CV3410-000			

5451522008	"RW-175-3/8-0-STK"		
577509L002	"DWP-125-3/8-4-STK", "1642280-1"		
C54718-000	"3-1201698-3", "FPO-4X-NO.10-0-STK"		
4429522003	"6-1193329-8", "DWP-125-1/8-0-STK"		
7499172001	"3-1195848-8", "FPO-1/8-5-STK"		
CP4928-000	"6-1899572-1"		
503958L012	"9-1193803-1", "TPEM-NR8-0-STK-CS5769"		
5451492001	"RW-175-1/16-0-STK"		
3074512001	"6-1192328-9", "FPO-1-1/4-0-STK"		
6741672002	"1195303-3", "FPO-1/8-6-STK"		
550028L040	"5-1194332-1", "SCL-3/16-0-STK-CS5799"		
CV3306-000			
5501052008	"1-1194339-0", "SCL-3/4-0-STK", "SCL-3/4-0-STK"		
5450842003	"RW-175-1/4-0-STK"		
BM9472-000	"ES2000-NO.11-P1-0-STK"		
EH2294-000	"DWFR-40/13-0-STK"		
774185P009	"8-1196028-7", "QS1500-NO.1-F5-0-STK"		

3367752001	"8-1192542-1", "FPO-1/16-2-STK"		
BM8687-000			
9867312001	"2-1197621-8", "FPO-2-6-STK"		
CN3839-000	"SCL-3/8-2-STK-CS7387"		
499347-000	"9-1193732-8", "GPA-2-0-STK"		
4619132001	"5-1193464-9", "FPO-3/8-5-STK"		
NB07112001	"BATTU-20.1/8.9-A1-0-STK", "8-1899840-1"		
9501492001	"5-1197348-6", "FPO-2-2-STK"		
9996212001	"1-1197728-6", "FPO-1/2-9-STK"		
3201412002	"6-1192427-1", "FPO-1/4-5-STK"		
2071412001	"6-1191501-0", "FPO-3/4-4-STK"		
CV3324-000			
CY2336-000	"FPO-0.555-X-STK"		
EH2298-000	"DWFR-16/4-0-STK"		
7118672001	"5-1195576-7", "FPO-2-9-STK"		
CZ6504-000	"7-1899806-7"		
5944092002	"3-1194699-2", "FPO-2-0-STK"		
CP4918-000	"5-1899572-1"		
CV37322001	"RW-175-E-1-X-STK", "3-1899810-8"		

5469592001	"7-1194303-4", "FPO-3/64-X-STK"		
CB0929-000	"FL2500-NO.0-I7-0-STK"		
C72046-000	"5-1201666-4", "FPO-4X-NO.6-0-STK"		
760016-000	"1200790-2", "DWP-125-1-1/2-2-STK"		
4325652001	"3-1193253-0", "FPO-1-1/2-X-STK"		
CB7580-000	"FL2500-NO.4-A1-O-STK"		
934669L008	"3-1197242-1", "DWP-125-1-0-STK-CS7034"		
NB07132001	"BATTU-20.1/8.9-A1-2-STK", "7-1899840-9"		
CL9154-000	"DWP-125-1/2-4-STK"		
CV3303-000			
436201P001	"2-1193279-6", "DWP-125-3/16-2-48IN"		
EH2292-000	"DWFR-19/6-0-STK"		
2409652002	"2-1191770-9", "FPO-3/4-0-STK"		
CV3323-000			
607381P046	"5-1194804-3", "SCT-NO.2-E5-0-STK"		
4838692001	"3-1193621-2", "FPO-3/4-2-STK"		
7580142002	"DWP-125-3/8-0-STK", "1448852-3", "16-0150"		

9553172001	"1-1197396-2", "FPO-3/64-4-STK"		
E23494-000	"4-1200881-5", "SCL-1/2-0-STK-CS5279"		
7733232001	"6-1196022-5", "FPO-1/2-0-STK"		
085193P003	"9-1190628-5", "ES1000-NO.4-B7-X-STK"		
530088-000	"3-1200265-5", "HSP2000-NO.2-N7-0-STK"		
F20555-000	"3-1202092-4", "SCL-1/8-0-STK-CS7315"		
CP4907-000	"4-1899572-1"		
CL9156-000	"DWP-125-1/4-4-STK"		
CV3301-000	"RW-175-3/32-X-STK", "16-0114", "1012478-F"		
C11219-000	"7-1201203-4", "SCL-3/8-0-STK-CS7315"		
A14310-000	"9-1201063-9", "SCL-1-2-STK"		
CV3299-000	"RW-175-3/64-X-STK"		
4001932001	"1-1193022-6", "DWP-125-0.156-9-STK"		
9904532001	"7-1197658-5", "FPO-3/32-X-STK"		
5978892002	"4-1194727-5", "DWP-125-1-1/2-0-STK"		

1999352002	"9-1191447-5", "FPO-3/16-0-STK"		
584683-000	"1194630-1", "SCL-1/4-0-STK-CS7315"		
035377P004	"4-1190273-8", "ES1000-NO.3-B8-X-STK"		
7071012001	"4-1195543-9", "FPO-1-2-STK"		
C13836-000	"1200882-8", "SCL-1/4-0-STK-CS5279"		
E96726-000	"2-1202107-9", "SCL-1/2-0-STK-CS7315"		
CV3391-000			
5500282020	"6-1194331-8", "SCL-3/16-0-STK"		
121397P024	"4-1190883-3", "ES2000-NO.3-B8-0-STK"		
CV3322-000			
2951512003	"DWP-125-1/4-0-STK", "1448670-1", "16-0151"		
CV3309-000			
9717172001	"1-1197511-4", "FPO-2-4-STK"		
8435832001	"2-1196581-5", "FPO-4-0-STK"		
CP4929-000	"6-1899572-2", "ES2000-NO.3-B8-0-STK-F-SH"		
2926172001	"2-1192218-0", "DWP-125-1/8-5-STK"		
CL9155-000	"DWP-125-1/2-6-STK"		

581913P020	"1-1194610-0", "QS1500-NO.2-F6-0-STK"		
EH2297-000	"DWFR-12/3-0-STK"		
6790932001	"2-1195338-5", "FPO-3/8-6-STK"		
1118012001	"1190816-1", "DWP-125-3/4-2-STK"		
717409-000	"9-1195611-1", "FPO-1-1/4-6-STK"		
6703712001	"1-1195277-8", "FPO-1/2-2-STK"		
2941012001	"4-1192228-9", "FPO-1-6-STK"		
8307672001	"1196487-6", "FPO-1-1/2-5-STK"		
CM1968-000			
D61501-000	"9-1200972-4", "TPEM-NR501-0-STK-CS5769"		
CL4288-000	"DWP-125-3/4-0-STK-CS8775"		
1416772002	"7-1191026-1", "FPO-3/64-9-STK"		
5500192011	"5-1194330-0", "SCL-3/8-0-STK"		
576105P006	"8-1194570-1", "ES1000-NO.2-A1-X-STK"		
3027832001	"7-1192293-4", "FPO-1-8-STK"		
8453332001	"5-1196594-1", "FPO-3/32-9-STK"		



958133P007	"1197417-6", "QS1500- NO.4-F8-0- STK"		
9261392002	"1197183-4", "FPO-1/4-6- STK"		
063725P022	"6-1190481- 1", "ES2000- NO.2-B9-0- STK", "ES2000-2- 4FOOT"		
543633P064	"5-1194264- 0", "SCT- NO.1-E6-0- STK"		
0065672002	"4-1190050- 9", "TAT- 125-1-9-STK"		
EG9473-000	"ES2000- NO.0-O9-0- STK"		
206247L039	"1191495-4", "SCT-NO.4- E2-0-STK"		
2954752001	"6-1192238- 7", "FPO- 3/16-9-STK"		
CR3556-000			
4968452001	"9-1193714- 8", "FPO-3/8- 0-STK"		
1100992001	"2-1190804- 1", "FPO-1/2- 4-STK"		
NB38252001			
EH2293-000	"DWFR-24/8- 0-STK"		
0158872002	"3-1190124- 8", "FPO-1- 1/2-0-STK"		
9121652001	"8-1197083- 6", "FPO-1/4- X-STK"		
0325192001	"3-1190252- 5", "FPO- 3/64-5-STK"		
CV3302-000			

7059732001	"3-1195536-9", "FPO-3/4-9-STK"		
2576552001	"3-1191885-4", "FPO-3/16-X-STK"		
EM63602001	"BATTU-25.4/12.7-A1-3-STK"		
829131P041	"9-1196474-8", "ES2000-NO.1-A1-0-STK"		
5058682024	"5-1193905-0"		
D50490-000	"9-1199628-1", "FPO-2-5-STK"		

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.

Alert document created by IHS Markit based on content provided by TE Connectivity.