



Product Change Notification

Current Date: 30-Mar-2022

TE Connectivity

Product Change Notification: PCN-22-133688

PCN Date: 29-MAR-22

Customer: TTI Inc(0000139702)

Location: WORLDWIDE

Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:
D2100 REC HOUSING

Description of Changes
A minor appearance change for process optimization without any performance impact. PN:1-1318118-9/2-1318118-9/3-1318118-9/9-1318118-9 ,Because the new and old molds will be produced at the same time, the two appearance products will exist at the same time Before Two Sink mark in latch face & without two Square holes in Terminal insertion face After Add two Square holes in Terminal insertion face to improve Sink mark in latch face As annex
Other attachments:
[D2100 REC Housing's appearance difference of new & existing tool](#)

Reason for Changes:

PCN Attributes:	
Product Category: Connector Housings	Kind of Change: Revision Adjustment / Part Clarification
Change Feature: Clarification/Correction	Potential Customer Impact: No Customer Impact
Remarks: D2100 REC HOUSING	

Estimated Dates:	
Last Order Date (Obsolete Parts Only):	First Ship Date of Changed Items (Changed Parts Only): 30-MAR-2022
Last Ship Date of Changed Items (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only): No Mixed Shipments
Effectivity Date:	Date of First Samples:

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-1318118-9	NO						
2-1318118-9	NO						
9-1318118-9	NO						

Customer: TTI Inc (3164508)

Location: Fort Worth

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-1318118-9	NO						
2-1318118-9	NO						

Customer: TTI, Inc. (3057778)

Location: Maisach-germlinden

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-1318118-9	NO		TYC1-1318118-9				

Customer: Shanghai TTI Electronics Co Ltd (3064990)

Location: Shanghai

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
9-1318118-9	NO						

Customer: TTI Inc (168830)

Location: Fort Worth

Agreement Number: Agreement Unknown


Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-1318118-9	NO						
2-1318118-9	NO						


D2100 REC Housing's appearance difference of new & existing tool

EVERY CONNECTION COUNTS





As the red mark, Two square holes are added to the copy die for solve the problem of product sink mark.



As the red mark, sink mark of molding before change