



Product Change Notification

Current Date: 06-Apr-2022

TE Connectivity

Product Change Notification: P-22-022461

PCN Date: 05-APR-22

Customer: TTI Inc(0000139702)

Location: WORLDWIDE

Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

Self Adhesive Labels for marking wire and Cables

Description of Changes

Manufacturing location change. The following Part Numbers will be transferred from the TE plant located at Idento Roedermark Germany to a TE manufacturing plant located in Tangier, Morocco.

Reason for Changes:

Dear Customer, as a result of our continuous strive to improve our processes, we hereby inform you about a transfer of tools and/or processes. The transfer is executed by following a strict transfer procedure, which guarantees no negative influence on quality, ability to supply and form-fit-function of the concerned products. The new manufacturing location is under a certified quality management system according to the standard industry requirements. An internal release based on our specifications will be executed before any parts will be delivered, which guarantees the performance of the product.

Estimated Dates:

Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	01-AUG-2022
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	No Mixed Shipments

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-1768019-8	NO			"C60516-000", "EET-5176P-8A"			
1-1878914-7	NO						
187752-000	NO			"4-1198202-9", "CR-107-LSR"			
1878865-2	NO						
260206-000	NO			"9-1198197-3", "CR-108-LSR"			
394378-000	NO			"1-1198187-9", "CR-110-LSR"			
4-1768422-3	NO						
416514-000	NO			"307-LE", "7-1198184-3"			
456834-000	NO			"301-LE", "6-1198180-6"			
483818-000	NO			"5-1200012-4", "HPK02WE1050"			
572792-000	NO			"319-LM", "1-1198172-5"			
6-1768018-3	NO			"F49446-000", "EET-1938P-9"			
6-1768019-8	NO			"C62650-000", "EK1119"			
6-1768021-6	NO			"E54351-000", "LBG-F-00010/2"			
6-1768703-0	NO						
7-1768021-2	NO			"C86386-000", "LBG-F-00029"			
7-1768829-1	NO						
8-1768016-3	NO			"E26941-000", "CSL-02713P-9"			
8-1768016-5	NO			"A53263-000", "CSL-03418P-9"			
8-1768016-9	NO			"E69476-000", "CSL-05525P-9"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
8-1768025-0	NO			"F84313-000", "LBG-U-01484/1"			
9-1768409-8	NO						
9-1768703-6	NO						
958144-000	NO			"325-LM", "1-1198143-9"			
A18923-000	NO			"1201774-1", "HMM-572241-5-8A"			
A37049-000	NO			"8-1200611-9", "HM-762508-2.5-8A"			
A46153-000	NO			"4-1201552-0", "HMM-762381-2.5-8A"			
A83643-000	NO			"8-1200610-6", "HM-762127-1-8A"			
C01371-000	NO			"3-1200609-3", "HW-762127-1-9"			
C21303-000	NO			"1-1200609-3", "HM-508254-5-8A"			
C37234-000	NO			"9-1200609-2", "HM-381191-5-8A"			
C53715-000	NO			"1-1200610-8", "HM-101508-2.5-8A"			
C58122-000	NO			"9-1200607-1", "HW-762508-2.5-9"			
C78178-000	NO			"5-1200608-9", "EP-101165-0.85-9"			
C78183-000	NO			"7-1200607-7", "HM-508318-2.5-8A"			
CC0109-000	NO			"HLX125YW4NEL60S", "3-1899112-6"			
CC0110-000	NO			"HLX125YW2NEL60S", "3-1899112-7"			
CT87273001	NO			"4-1899688-9"			
D07339-000	NO			"6-1200608-7", "HW-191064-10-9"			
D11430-000	NO			"7-1200608-9", "HW-095095-10-9"			
D14091-000	NO			"9-1200608-1", "EP-381191-5-9"			
D34022-000	NO			"5-1200606-9", "EP-254127-10-9"			
D34032-000	NO			"6-1200606-1", "HM-254127-10-8A"			
D57340-000	NO			"5-1200607-5", "EP-508254-5-9"			
D64030-000	NO			"7-1200607-1", "EP-762508-2.5-9"			
D69815-000	NO			"9-1202019-5", "EP-101381-2.5-9"			
D71430-000	NO			"308-LM", "5-1200605-6"			
D88272-000	NO			"5-1200605-7", "HW-381064-10-9"			
D91406-000	NO			"6-1200605-0", "EP-699254-5-9"			
E04109-000	NO			"1-1200606-9", "EP-508508-3-9"			
E14158-000	NO			"9-1200603-8", "HW-127127-10-9"			
E15075-000	NO			"6-1201552-8", "HMM-101635-2.5-8A"			
E21596-000	NO			"4-1200604-1", "EP-101508-2.5-9"			
E24103-000	NO			"4-1200604-2", "HM-699254-5-8A"			
E31556-000	NO			"1-1200604-0", "EP-381127-5-9"			
E61543-000	NO			"1200605-5", "EP-508127-5-9"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
E64127-000	NO			"1-1200605-1", "HM-101165-0.85-8A"			
E78364-000	NO			"7-1200602-2", "EP-101762-1.8-9"			
E87437-000	NO			"9-1200602-8", "HW-508095-5-9"			
E97411-000	NO			"4-1200603-9", "HW-699254-5-9"			
F05902-000	NO			"EP-762254-5-9", "6-1200835-7"			
F17521-000	NO			"5-1200601-6", "HW-254127-10-9"			
F37539-000	NO			"8-1200601-6", "HM-699191-5-8A"			
F39639-000	NO			"1-1201922-4", "HW-762254-5-9"			
F41698-000	NO			"1-1200602-0", "HW-508127-5-9"			
F61662-000	NO			"5-1200602-3", "HW-318097-10-9"			
F78410-000	NO			"1-1200601-2", "HW-101508-2.5-9"			

Customer: TTI, Inc. (1305175)

Location: Maisach-gerlninden

Agreement Number: TTI001

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-1768019-8	NO		TYC1-1768019-8	"C60516-000", "EET-5176P-8A"			
187752-000	NO		TYC187752-000, RAY187752-000	"4-1198202-9", "CR-107-LSR"			
260206-000	NO		TYC260206-000, RAY260206-000	"9-1198197-3", "CR-108-LSR"			
4-1768422-3	NO		TYC4-1768422-3				
6-1768018-3	NO		TYC6-1768018-3	"F49446-000", "EET-1938P-9"			
6-1768019-8	NO		TYC6-1768019-8	"C62650-000", "EK1119"			
6-1768021-6	NO			"E54351-000", "LBG-F-00010/2"			
6-1768703-0	NO		TYC6-1768703-0				
7-1768021-2	NO		TYC7-1768021-2	"C86386-000", "LBG-F-00029"			
7-1768829-1	NO		TYC7-1768829-1				
8-1768016-3	NO		TYC8-1768016-3	"E26941-000", "CSL-02713P-9"			
8-1768016-5	NO		TYC8-1768016-5	"A53263-000", "CSL-03418P-9"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
8-1768016-9	NO		TYC8-1768016-9	"E69476-000", "CSL-05525P-9"			
8-1768025-0	NO		TYC8-1768025-0	"F84313-000", "LBG-U-01484/1"			
9-1768409-8	NO		TYC9-1768409-8				
9-1768703-6	NO		TYC9-1768703-6				
C78178-000	NO			"5-1200608-9", "EP-101165-0.85-9"			
CC0109-000	NO		RAYCC0109-000	"HLX125YW4NEL60S", "3-1899112-6"			
CC0110-000	NO		RAYCC0110-000	"HLX125YW2NEL60S", "3-1899112-7"			
F05902-000	NO		TYCF05902-000	"EP-762254-5-9", "6-1200835-7"			
F61662-000	NO		RAYF61662-000	"5-1200602-3", "HW-318097-10-9"			

Customer: TTI, Inc. (3057778)

Location: Maisach-gernlinden

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
187752-000	NO		TYC187752-000, RAY187752-000	"4-1198202-9", "CR-107-LSR"			
260206-000	NO		TYC260206-000, RAY260206-000	"9-1198197-3", "CR-108-LSR"			
4-1768422-3	NO		TYC4-1768422-3				
6-1768018-3	NO		TYC6-1768018-3	"F49446-000", "EET-1938P-9"			
6-1768019-8	NO		TYC6-1768019-8	"C62650-000", "EK1119"			
6-1768021-6	NO			"E54351-000", "LBG-F-00010/2"			
6-1768703-0	NO		TYC6-1768703-0				
7-1768021-2	NO		TYC7-1768021-2	"C86386-000", "LBG-F-00029"			
7-1768829-1	NO		TYC7-1768829-1				
8-1768016-3	NO		TYC8-1768016-3	"E26941-000", "CSL-02713P-9"			
8-1768016-5	NO		TYC8-1768016-5	"A53263-000", "CSL-03418P-9"			
8-1768016-9	NO		TYC8-1768016-9	"E69476-000", "CSL-05525P-9"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
8-1768025-0	NO		TYC8-1768025-0	"F84313-000", "LBG-U-01484/1"			
9-1768409-8	NO		TYC9-1768409-8				
9-1768703-6	NO		TYC9-1768703-6				
C78178-000	NO			"5-1200608-9", "EP-101165-0.85-9"			
CC0109-000	NO		RAYCC0109-000	"HLX125YW4NEL60S", "3-1899112-6"			
CC0110-000	NO		RAYCC0110-000	"HLX125YW2NEL60S", "3-1899112-7"			
F05902-000	NO		TYCF05902-000	"EP-762254-5-9", "6-1200835-7"			
F61662-000	NO		RAYF61662-000	"5-1200602-3", "HW-318097-10-9"			

Customer: TTI Inc (168830)

Location: Fort Worth

Agreement Number: TTI003

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-1878914-7	NO						
1878865-2	NO						
483818-000	NO			"5-1200012-4", "HPK02WE1050"			
572792-000	NO			"319-LM", "1-1198172-5"			
C37234-000	NO			"9-1200609-2", "HM-381191-5-8A"			
D69815-000	NO			"9-1202019-5", "EP-101381-2.5-9"			
D91406-000	NO			"6-1200605-0", "EP-699254-5-9"			
E04109-000	NO			"1-1200606-9", "EP-508508-3-9"			
F05902-000	NO			"EP-762254-5-9", "6-1200835-7"			
F41698-000	NO			"1-1200602-0", "HW-508127-5-9"			

Customer: TTI Inc (1281288)

Location: Fort Worth

Agreement Number: TTI002

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
394378-000	NO			"1-1198187-9", "CR-110-LSR"			
416514-000	NO			"307-LE", "7-1198184-3"			
456834-000	NO			"301-LE", "6-1198180-6"			
572792-000	NO			"319-LM", "1-1198172-5"			
958144-000	NO			"325-LM", "1-1198143-9"			
A18923-000	NO			"1201774-1", "HMM-572241-5-8A"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
A37049-000	NO			"8-1200611-9", "HM-762508-2.5-8A"			
A46153-000	NO			"4-1201552-0", "HMM-762381-2.5-8A"			
A83643-000	NO			"8-1200610-6", "HM-762127-1-8A"			
C01371-000	NO			"3-1200609-3", "HW-762127-1-9"			
C21303-000	NO			"1-1200609-3", "HM-508254-5-8A"			
C37234-000	NO			"9-1200609-2", "HM-381191-5-8A"			
C53715-000	NO			"1-1200610-8", "HM-101508-2.5-8A"			
C58122-000	NO			"9-1200607-1", "HW-762508-2.5-9"			
C78178-000	NO			"5-1200608-9", "EP-101165-0.85-9"			
C78183-000	NO			"7-1200607-7", "HM-508318-2.5-8A"			
CT87273001	NO			"4-1899688-9"			
D07339-000	NO			"6-1200608-7", "HW-191064-10-9"			
D11430-000	NO			"7-1200608-9", "HW-095095-10-9"			
D14091-000	NO			"9-1200608-1", "EP-381191-5-9"			
D34022-000	NO			"5-1200606-9", "EP-254127-10-9"			
D34032-000	NO			"6-1200606-1", "HM-254127-10-8A"			
D57340-000	NO			"5-1200607-5", "EP-508254-5-9"			
D64030-000	NO			"7-1200607-1", "EP-762508-2.5-9"			
D69815-000	NO			"9-1202019-5", "EP-101381-2.5-9"			
D71430-000	NO			"308-LM", "5-1200605-6"			
D88272-000	NO			"5-1200605-7", "HW-381064-10-9"			
D91406-000	NO			"6-1200605-0", "EP-699254-5-9"			
E14158-000	NO			"9-1200603-8", "HW-127127-10-9"			
E15075-000	NO			"6-1201552-8", "HMM-101635-2.5-8A"			
E21596-000	NO			"4-1200604-1", "EP-101508-2.5-9"			
E24103-000	NO			"4-1200604-2", "HM-699254-5-8A"			
E31556-000	NO			"1-1200604-0", "EP-381127-5-9"			
E61543-000	NO			"1200605-5", "EP-508127-5-9"			
E64127-000	NO			"1-1200605-1", "HM-101165-0.85-8A"			
E78364-000	NO			"7-1200602-2", "EP-101762-1.8-9"			
E87437-000	NO			"9-1200602-8", "HW-508095-5-9"			
E97411-000	NO			"4-1200603-9", "HW-699254-5-9"			
F05902-000	NO			"EP-762254-5-9", "6-1200835-7"			
F17521-000	NO			"5-1200601-6", "HW-254127-10-9"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
F37539-000	NO			"8-1200601-6", "HM-699191-5-8A"			
F39639-000	NO			"1-1201922-4", "HW-762254-5-9"			
F61662-000	NO			"5-1200602-3", "HW-318097-10-9"			
F78410-000	NO			"1-1200601-2", "HW-101508-2.5-9"			