



Product Change Notification

Current Date: 18-May-2022

TE Connectivity

Product Change Notification: PCN-22-139601

PCN Date: 18-MAY-22

Customer: TTI, Inc. (1305175)

Location: Maisach-gernlinden

Agreement: TTI001

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description: (Text limited to 120 characters)
Alternative material Vectra E130i is Laperos E130i.

Description of Changes
No changes of drawing, specification, function. P2 relays use Laperos E130i and Vectra E130i with have same properties.

Reason for Changes:
P2 relay use Vectra E130i and Laperos E130i. Both materials have the same characteristics, passed the same tests and are both UL certified. The relay form (dimensions), features and ratings keep unchanged.

PCN Attributes:	
Product Category: Relays, Contactors & Switches	Kind of Change: Drawing
Change Feature: Revision Adjustment	Potential Customer Impact: No Customer Impact
Remarks: P2 relay Vectra E130i to be changed to alternative material Laperos E130i .	

Estimated Dates:	
Last Order Date (Obsolete Parts Only):	First Ship Date of Changed Items (Changed Parts Only): 23-MAY-2022
Last Ship Date of Changed Items (Obsolete Parts Only): 31-DEC-2022	Last Date for Mixed Shipments: (Changed Parts Only): No Mixed Shipments
Effectivity Date:	Date of First Samples:

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-1393788-1	NO		TYC1-1393788-1	V23079A1003B301			
1-1393788-6	NO		TYC1-1393788-6	V23079A1005B301			
1393788-3	NO		TYC1393788-3	V23079A1001B301			
2-1393788-0	NO		TYC2-1393788-0	V23079A1006B301			
2-1393788-2	NO		TYC2-1393788-2	V23079A1008B301			
2-1393789-2	NO			V23079H1205B301			
2-1393789-4	NO		TYC2-1393789-4	V23079H1208B301			
3-1393788-3	NO		TYCV23079B1201B301, TYC3-1393788-3	V23079B1201B301			
3-1393788-6	NO		TYC3-1393788-6	V23079B1203B301			
3-1393788-7	NO		TYC3-1393788-7	V23079B1205B301			
3-1393788-9	NO			V23079B1206B301			
3-1393789-5	NO		TYC3-1393789-5	V23079A2001B301			
3-1393789-7	NO			V23079A2003B301			
4-1393788-1	NO		TYC4-1393788-1	V23079B1208B301			
4-1393789-3	NO		TYC4-1393789-3	V23079D2001B301			
4-1393789-5	NO		TYC4-1393789-5	V23079D2003B301			
4-1393789-7	NO		TYC4-1393789-7	V23079D2008B301			
5-1393788-5	NO		TYC5-1393788-5	V23079D1001B301			
5-1393788-7	NO		TYC5-1393788-7	V23079D1003B301			
5-1393788-8	NO		TYC5-1393788-8	V23079D1005B301			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5-1393789-1	NO		TYC5-1393789-1	V23079G2003B301			
5-1393789-3	NO		TYC5-1393789-3	V23079G2006B301			
5-1393789-4	NO		TYC5-1393789-4	V23079G2008B301			
5-1393789-5	NO		TYC5-1393789-5	V23079G2011B301			
6-1393788-1	NO			V23079D1008B301			
6-1393788-2	NO		TYC6-1393788-2	V23079D1011B301			
6-1393788-8	NO		TYC6-1393788-8	V23079E1201B301			
6-1393788-9	NO		TYC6-1393788-9	V23079E1203B301			
7-1393788-1	NO		TYC7-1393788-1	V23079E1208B301			
7-1393788-6	NO		TYC7-1393788-6	V23079G1001B301			
7-1393788-7	NO		TYC7-1393788-7	V23079G1003B301			
7-1393788-8	NO		TYC7-1393788-8	V23079G1005B301			