



04-May-2023

PCN #: P-23-024488

Subject : Controlled Electrical Cables as per attached parts list

Description of Change : Tyco Electronics UK Ltd (TE Connectivity) have made a change to the Chemically Foamed Polyethylene insulation material used in some of our controlled electrical cables. This is a supplier-initiated change, as a supplier will no longer be able to provide an old grade of material due to a chemical blowing / foaming agent, which has been identified as a Substance of Very High Concern (SVHC) as per EU REACH regulations. The new greener Chemically Foamed Polyethylene insulation material complies with EU REACH regulations. Validation testing based on our specifications has been completed, which shows no change in the performance of the concerned products. There is a minor visual change to the colour of the finished products. See pictures below for more details.

Reason : Product improvement.

Key Dates :

Contact By Date:04-May-2023

Implementation Date:04-May-2023

Product Affected	Alias Part Number	Substitute Part Number	AliasSub Part Number
1459853001	"2-1191055-9", "EPD25986B/1(CO)"		
CT82123001	"EPD114511 B/1(CO)"		
CQ79583001	"2022A1P11-9(CO)"		
EQ09873001	"EPD108173 ACK0308/2"		
CQ49563001	"EPD109318 QCK0456/11"		
4386793001	"1193297-5", "7526A1317-0(CO)"		

2216353001	"9-1191632-2", "EPD90230A"		
440225-000	"3-1193309-5", "5020A1311-0"		
2013633001	"7-1191459-1", "EPD60303B"		
378213-000	"1192832-5", "5024A1811-0"		
4418243001	"0022D0311-9(S)", "9-1193321-7"		
3656973001	"2-1192742-2", "EPD77127L/1-1L(CO)"		
5286403001	"9-1200883-9", "EPD60603C/1-9(CO)"		
3752853001	"5-1192811-2", "9530A1318-9(CO)"		
3689553001	"9-1192764-7", "EPD32856A/2"		
EQ08473001	"EPD121866A-0CK0547"		
CT98873001	"EPD115973A"		
A039143001	"3-1200831-8", "EPD95723Q/1-1L(CO)"		
CQ20523001	"EPD109318Q/1-1L(MARK1)"		
CQ74803001	"EPD121441A"		
3570413001	"2-1192679-9", "EPD32856A/1-N"		
C187273001	"EPD104308A/1-1L(CO)"		

0867823001	"9-1200146-7", "EPD97331L/1(CO)"		
CQ71073001	"EPD117170 ACK0298/2"		
136423-000	"1190989-8", "5020A3811-0"		
D936633001	"1201442-9", "5026A3814-0"		
CQ72903001	"EPD121343 A"		
EQ10493001	"EPD123167 A"		
0215893001	"6-1190167-2", "EPD4044/2-1L(CO)"		
7173233001	"2-1195611-1", "EPD87108Q/1-9(CO)"		
F492613001	"9-1201461-9", "EPD4045-C/5(CO)"		
8975153001	"3-1196977-2", "EPD65701F"		
5663973001	"8-1194472-9", "EPD61702L"		
1371093001	"9-1190993-3", "EPD86425A"		
CQ95283001	"EPD121038 A"		
9036793001	"6-1197022-4", "EPD73247A"		
3379473001	"1192551-1", "5026A1314-02(CO)"		
9711773001	"5028A1P18-9(CO)", "2-1197507-6"		

CQ92403001	"EPD109318 QCK0456/55"		
CQ83663001	"EPD116265 A/2(CO)"		
A113163001	"2-1200715- 0", "EPD78905A CK0323"		
CQ77073001	"EPD121137 A/1-9(CO)"		
7650513001	"5026A1P17- 1L(CO)", "9- 1195955-9"		
CT73933001	"2-1899634- 3", "120- OHM-2SJFR- 22-1L(CO)"		
CQ73803001	"EPD121402 A"		
3280333001	"6-1192481- 0", "EPD26168D "		
CQ87823001	"EPD35767Q CK0206"		
2694013001	"3-1191988- 1", "EPD72124B"		
1054663001	"5-1199016- 8", "7522A1811- 0(4M)"		
CQ42033001	"EPD119030 A/1-9"		
CD84263001	"EPD107551 A/2(CO)", "3- 1899479-9"		
CQ34153001	"EPD109318 Q/1- 9(M2)CK039 9"		
5934333001	"2524E0P11- 9(CO)", "2- 1194692-6"		
CT69673001	"EPD114764 A/1-9(CO)"		
CD53033001	"EPD107883 B", "8- 1899347-9"		

8712693001	"0024E0811-0", "9-1196780-1"		
1914933001	"8-1191388-1", "EPD73248A"		
CQ32933001	"EPD118663A"		
CD72963001	"EPD65220QCK0503", "4-1899435-6"		
9479293001	"5019D3318-0(CO)", "5-1197334-6"		
CT71563001	"120-OHM-CSJR-0(4M)"		
CQ28243001	"EPD94392BCK0206/1"		
CQ72373001	"EPD121290A"		
2021383001	"6-1198863-4", "EPD89109Q/1-1L(CO)"		
C928993001	"EPD104309A/1-1L(CO)"		
1996613001	"2-1191446-9", "EPD44533B"		
CQ12533001	"EPD117622A/5(CO)"		
E820243001	"5-1200996-1", "EPD99292B/1-6(CO)"		
3253493001	"1192462-1", "9530A1317-0(CO)"		
CD21803001	"EPD105670A", "3-1899193-1"		
7757053001	"1196040-8", "EPD91385ACK0183"		
4324313001	"3-1193252-9", "EPD60844B"		
CD76913001	"EPD105601A/2", "1899449-2"		

A954783001	"5-1200773-5", "EPD2029J/2(CO)"		
440101-002	"1-1193308-0", "9530A1318-0"		
4025273001	"7-1193038-6", "EPD87667A/4-9"		
CQ80103001	"EPD119201A"		
C825373001	"2-1201012-3", "EPD100170A"		
D654573001	"1201920-3", "EPD98957B/1-9(FS)"		
3562433001	"1-1192674-7", "EPD67364QCK0208"		
7724573001	"7-1196016-6", "EPD60325A/1-9(CO)"		
4532933001	"3-1193403-6", "EPD49113Q"		
F044573001	"CLFH-179-0(CO)", "4-1201019-2"		
4401073001	"1-1193308-8", "5028A1314-0"		
CD83193001	"EPD109729A", "6-1899473-3"		
CQ74483001	"EPD117170ACK0298/3"		
6342653001	"7-1195016-2", "EPD69569B/1-9(CO)"		
4142103001	"6-1193122-5", "EPD25986B"		

CQ60633001	"EPD120520 A/1(CO)"		
CQ91653001	"0024K1811- 0(M1)"		
CD69803001	"5026C1P14- N(CO)", "2- 1899423-5"		
CD93853001	"7-1899514- 0", "EPD111093 A/2-0(6M)"		
CT02403001	"EPD108852L ", "1- 1899549-3"		
CT04903001	"EPD113319 A", "2- 1899555-7"		
3476353001	"2-1192616- 8", "EPD60651B/ 1-9(CO)"		
CQ04173001	"EPD33374A CK0094/1"		
3171853001	"2-1192403- 3", "5012A3811- 0"		
CQ02083001	"EPD116816 ACK0206"		
CQ34073001	"EPD117755 ACK0298"		
CD68443001	"EPD108173 ACK0266", "7-1899416- 2"		
CQ83853001	"EPD118179 A/5(CO)"		
CQ48063001	"EPD117416 ACK0016"		
D952573001	"3-1201284- 1", "EPD99482B CK0400"		
EQ10183001	"EPD35077A CK0647/2"		
2004993001	"9-1191452- 0", "5018A1P11- 1L"		
CQ69693001	"EPD120794 A"		

1290073001	"9-1190936-8", "EPD82097A"		
0980283001	"1199212-2", "EPD95437Q/1-9(CO)"		
CQ41773001	"EPD116262B/3(CO)"		
CD35993001	"4-1899258-4", "EPD104098A/1-6(CO)"		
A543043001	"7-1201018-5", "EPD60608D/1-9(CO)"		
CQ82693001	"EPD120795A"		
EQ06053001	"EPD121860BCK0202"		
200556-000	"3-1191453-5", "7520A1P11-1L"		
6489053001	"3-1195122-7", "EPD20662B/3-6(CO)"		
F759343001	"EPD25986A/1-1L(CO)", "5-1201019-7"		
C435203001	"9-1201344-2", "0022D0311-96(CO)"		
9939973001	"5018D3311-9", "5-1197688-5"		
1770573001	"1-1191287-5", "EPD33631A"		
EQ12273001	"EPD122828ACK0624"		
6647563001	"4-1199422-1", "7524A1811-0(3M)"		

D349773001	"5026A1P11-9(SFS)", "5-1200802-6"		
2389763001	"3-1201141-0", "EPD94821L/1-1L(CO)"		
5973233001	"6-1194723-7", "EPD69095A"		
CQ72813001	"EPD121334A"		
CQ18403001	"EPD113842Q/1-1L(FS)"		
CD93773001	"EPD111033A/2(CO)", "6-1899514-2"		
C138163001	"6-1200773-2", "EPD2029J/1-1L(CO)"		
CT89493001	"EPD116118A/1-1L(CO)"		
6362853001	"9-1195030-6", "EPD20697A/1-1L(CO)"		
E141933001	"5-1201766-3", "EPD101039L"		
CQ85303001	"EPD120934A"		
CQ65813001	"EPD35077ACK0647"		
CQ70193001	"EPD118342B/1-2(CO)"		
200165-000	"2-1191450-8", "5028A1P14-1L"		
4379153001	"4-1193291-9", "5026A1P11-N(CO)"		
461539W002	"1193462-6", "5024A1P11-9"		
E761733001	"EPD104314A/1-1L(CO)"		

7828163001	"9-1196079-9", "EPD25986B(M)"		
5444253001	"8-1194270-3", "EPD73307R/1-2(CO)"		
CD29303001	"CLFH179/1(FS)", "9-1899222-3"		
CD56173001	"EPD108041 A/1-1L/9(CO)", "5-1899362-7"		
0157653001	"5-1190123-5", "EPD82741Q"		
EQ03553001	"EPD95014A CK0213/2"		
CQ61523001	"EPD120653 A"		
4408383001	"8-1193314-5", "5018D3311-0"		
9814713001	"0024A0311-0(CO)", "6-1197583-0"		
CT98383001	"5018F1811-0(2M)"		
CQ19273001	"EPD118014 A/1-1L(CO)"		
420030W002	"3-1193164-0", "5019D3318-0"		
8244473001	"5-1196438-1", "EPD65984Q"		
4402253016	"3-1193309-9", "5020A1311-0"		
EQ10503001	"EPD123179 ACK0298"		
CQ99213001	"EPD122349 A/1(CO)"		

E475663001	"9-1201921-1", "EPD102735 A"		
CT92613001	"9524A0P11-9(CO)"		
CD00353001	"EPD100733 Q", "9-1899089-5"		
8764493001	"6-1196817-1", "EPD63054C/1-6(CO)"		
EQ06663001	"0024K1811-4(CO)"		
9024013001	"4-1197013-0", "EPD65742A"		
7173193001	"5030A1P17-1L(CO)", "1-1195611-7"		
CD46053001	"EPD107519 A/1(CO)", "3-1899313-4"		
1202853001	"1190875-6", "EPD46419Q/1-1L(CO)"		
CQ79223001	"EPD121405 A"		
CQ36873001	"EPD96642A CK0518"		
0318873001	"3-1190247-3", "EPD67364Q-0(CO)"		
CQ47243001	"EPD111050 ACK0298/2"		
9338513001	"7530A1P17-1L(CO)", "8-1197236-1"		
5787123001	"8-1201165-7", "EPD100566 A/1-9(CO)"		
F214353001	"5-1201143-6", "EPD94821M /1-1L(CO)"		

7672073001	"1195979-8", "EPD62444Q "		
CQ86303001	"EPD121730 ACK0627"		
CQ98043001	"0024A0311- 0CK0202"		
CT67163001	"EPD104313 B/1-9(CO)"		
CT98863001	"EPD115853 A"		
CQ12163001	"EPD113842 QCK0456/20"		
CQ19233001	"EPD118024 A"		
EQ05043001	"EPD122871 A/3-0/9(CO)"		
0059873001	"8-1190045- 4", "EPD77127L/ 2-1L/9(CO)"		
CQ11963001	"EPD117497 ACK8500"		
4263353001	"5-1193208- 3", "EPD61324Q "		
3991963003	"1192995-3", "FILLER- ROD-FOAM- 045"		
EQ05133001	"100-OHM- 2SJR-24- 5(CO)"		
CQ86563001	"EPD120896 B"		
CT05913001	"EPD28251A CK0440/2", "4-1899558- 1"		
CQ42213001	"EPD119031 B"		
2005363001	"1-1191453- 6", "5030A1P17- 1L"		
CQ79573001	"2022A1P11- 1L(CO)"		
CQ73003001	"EPD121352 A"		

D774053001	"8-1200681-7", "EPD98824A"		
CQ41963001	"EPD119030 A/2(CO)"		
CD56093001	"EPD108036 A/1-1L-9(CO)", "5-1899362-0"		
CQ16033001	"EPD117622 ACK0202"		
EQ05963001	"EPD44533B CK0656"		
E716903001	"8-1202053-2", "EPD101729 M/1-1L(CO)"		
CQ15373001	"EPD117597 A"		
1501813001	"1191086-1", "EPD61455Q"		
CQ73733001	"EPD121177 A"		
EQ08463001	"EPD116255 A-0CK0547"		
CQ76573001	"EPD118397 ACK0298"		
CQ04183001	"EPD109318 Q/1-1L(M1)"		
C635293001	"EPD104343 A/1-9(CO)"		
4128833001	"4-1193113-4", "5020A3311-0(CO)"		
1490543001	"8-1199484-2", "5020A1811-0(12M)"		
2052513001	"3-1191487-2", "EPD69813A"		
CQ44593001	"7518A1311-0CK0503"		
CQ23453001	"EPD105670 ACK0206"		

EQ03453001	"EPD109318 QCK0456/2"		
CQ17513001	"EPD117862 A"		
1901273001	"1-1191379- 8", "EPD26467Q "		
2007783001	"1191455-5", "2524E0P11- 1L"		
3H06613001	"9-1193003- 6", "EPD7032B"		
CD55573001	"EPD108017 BCK0202", "1-1899361- 9"		
A169333001	"2-1201148- 3", "EPD95079A "		
CQ56183001	"EPD116267 A/3(CO)"		
0349323001	"5-1197947- 9", "EPD80977A "		
CQ00323001	"EPD116027 A"		
9015333001	"2-1197007- 6", "EPD87108Q/ 1-1L(CO)"		
445133-000	"0022E0311- 0", "4- 1193345-1"		
4400943001	"9-1193307- 4", "5026A1318- 0"		
1571233001	"4-1191135- 6", "EPD70340L/ 1-9(CO)"		
CT83673001	"9530A1318- 9(8M)"		
9242893001	"9-1197169- 2", "EPD86166R/ 1-1L(CO)"		

5443493001	"5018A1P11-9(CO)", "9-1194269-0"		
CT69723001	"EPD114765 A/1-9(CO)"		
CD69973001	"5026C1314-02(CO)", "8-1899423-7"		
9738633001	"5-1197526-8", "EPD26168D/1-0(M)"		
5592173001	"3-1194414-9", "EPD77124A/1(CO)"		
CQ79743001	"EPD91158L CK0624"		
A599173001	"4-1202050-1", "EPD101750 B/2(CO)"		
D832503001	"7-1202176-7", "EPD48679R/1-9(CO)"		
9493573001	"1197344-7", "EPD30885Q/1-9(CO)"		
CT74223001	"5020A3312-0(CO)"		
9982293001	"7530E1P14-1L(CO)", "7-1197718-7"		
4345053001	"6-1193267-8", "EPD42233A"		
CD37373001	"EPD106513 A", "6-1899264-5"		
CT64743001	"EPD113520L"		
E296603001	"6-1202053-8", "EPD101729 M/2(CO)"		
2751053001	"6-1192037-2", "EPD69568A"		

3012713001	"4-1192282-4", "7530A1P14-1L(CO)"		
440569-000	"3-1193312-1", "5026A1311-0"		
1582153001	"1191143-1", "EPD60608B/1-1L(CO)"		
CQ76073001	"EPD121487A"		
CT53363001	"EPD113521L"		
A771503001	"8-1201400-3", "EPD98957BCK0900"		
CQ45653001	"EPD118392A"		
A702313001	"5-1200682-7", "EPD98370B"		
440060-011	"9-1193306-5", "5024A1311-0"		
CQ99893001	"EPD94392B"		
CQ60623001	"0024B8911(CO)"		
1986983001	"1198701-8", "EPD44774N/1-0(8M)"		
CQ21073001	"EPD117761A"		
2386973001	"7-1191754-0", "EPD62976A/1-1L(CO)"		
CQ40393001	"7528A1814-0(M)"		
CT75433001	"5020A3312-0(3M)"		
CD76953001	"EPD105568A/1-6(CO)", "1899449-7"		
CQ02453001	"100-OHM-2SJFR-24-1L(CO)"		

CQ27953001	"EPD113842 Q/1- 1LCK0399/3"		
CQ07523001	"EPD90230A CK0271"		
1580643001	"2-1201141- 4", "EPD94821L/ 1-9(CO)"		
2002173001	"7-1191450- 7", "7528A1P17- 1L"		
F318073001	"EPD97565Q/ 1-1L(CO)", "5-1200674- 1"		
4097163001	"5-1199663- 6", "EPD23197B(2M)"		
440094W003	"1193308-1", "5026A1318- 0"		
CD62993001	"EPD108393 A", "4- 1899388-6"		
5447453001	"1-1194273- 1", "7522A1311- 0(CO)"		
CQ93183001	"EPD94392B CK0206/7"		
CT87673001	"EPD115985 A"		
4313853001	"6-1193244- 9", "EPD69568A/ 1-9"		
CQ37903001	"EPD118397 A"		
CQ67763001	"EPD120650 A/1-2(CO)"		
2001213001	"6-1191449- 0", "5019D3P18- 1L"		
4418903001	"4-1193322- 1", "5024A1311- 94"		

9279423001	"6-1200777-4", "EPD98932A"		
4885483001	"4-1193655-6", "7526A1811-0"		
CQ72213001	"EPD121274A"		
CT87683001	"EPD115985A/1(CO)"		
0577973001	"9-1190438-6", "5028A1314-9(CO)"		
2000113002	"0022D0P11-9", "5-1191448-3"		
CD02293001	"EPD104855A/1-1L(CO)", "3-1899102-1"		
CQ07293001	"EPD78640LCK0121/7"		
CQ72893001	"EPD121342A"		
EQ07233001	"EPD108750A"		
8170973001	"4-1196367-0", "EPD38753A"		
CQ70533001	"EPD118745ACK0202/1"		
7950893001	"0022D0P11-1L(CO)", "4-1196155-3"		
6723003001	"9-1195289-4", "EPD24477A"		
CQ59603001	"EPD109318QCK0456/6"		
2008503001	"0020D0P11-1L", "7-1191455-2"		
5185653001	"1-1194070-8", "EPD60897A"		

C742633001	"5024A1311-0(2M)", "4-1200424-3"		
1752153001	"1191274-4", "EPD33537R"		
CQ83693001	"EPD116265 A/1-9(CO)"		
440107W003	"1-1193308-9", "5028A1314-0"		
1239673001	"6-1190901-8", "EPD23197B"		
8151373001	"7524A1811-0", "3-1196352-1"		
2987203001	"5-1199502-1", "9530A1317-9(8M)"		
8567713001	"7528A1P14-1L(CO)", "6-1196677-4"		
CD43163001	"2024A0P11-9(CO)", "4-1899299-6"		
CQ70243001	"EPD109382 ACK0298/5"		
E863193001	"8-1201288-0", "EPD96643A"		
CT95223001	"EPD116439 A"		
D335463001	"8-1200819-3", "EPD99111A"		
4182033001	"5-1193151-8", "EPD72718A"		
D035093001	"1-1200878-5", "EPD98370B CK0339"		
EQ01913001	"EPD122153 A"		
CQ83793001	"EPD118179 A/1-1(CO)"		

EQ01903001	"7526A1317-0(M)"		
CQ11953001	"EPD117498 ACK8500"		
4419293001	"6-1193322-6", "5020A3311-9"		
6748533001	"8-1195307-1", "EPD87667A/ 2(CO)"		
CQ45873001	"EPD116816 ACK0206/2"		
A389363001	"3-1202050-4", "EPD101744 B/1-9(CO)"		
CT78683001	"EPD115223 A/1-1L(CO)"		
440672W002	"3-1193313-2", "7520A1311-0"		
1834333001	"3-1191332-8", "EPD33017Q "		
8125533001	"4-1196321-1", "EPD30885Q/ 1-1L(CO)"		
CQ62943001	"7528A1814-0(CO)"		
CQ28053001	"EPD113842 Q/1-9(M2)(FS)"		
6902833001	"4-1195420-4", "EPD72947A/ 1-9(CO)"		
CQ13703001	"EPD117487 A"		
D784493001	"8-1202050-1", "EPD101754 B/1-1L(CO)"		
CQ67853001	"EPD120650 A"		
CQ28923001	"EPD117254 ACK0202"		

2866813001	"3-1192171-0", "EPD20662B/1-9(CO)"		
CQ78263001	"EPD116448 ACK0298"		
EQ08423001	"5024D3314-0"		
CD93893001	"EPD111035 A/1-1L(CO)", "7-1899514-6"		
CQ18413001	"EPD113842 Q/1-9(FS)"		
5194933001	"4-1194076-1", "7520A1P11-1L(CO)"		
CQ03433001	"0024A0311-0CK0300"		
1532593001	"3-1191107-8", "EPD7875M"		
D288443001	"EPD104307 A/1-9(CO)"		
CQ22833001	"EPD62444Q CK0206/6"		
7010533001	"7-1195502-7", "7526A1P11-1L(CO)"		
4615393001	"1193462-5", "5024A1P11-9"		
CQ51983001	"EPD119924 A/3(CO)"		
CQ83843001	"EPD118179 A/4(CO)"		
0869713001	"8-1190641-0", "EPD69065Q"		
CT89523001	"EPD116119 A/1-9(CO)"		
C042653001	"0024A0311-0(4M)", "4-1200292-5"		
4400883003	"7-1193307-5", "7528A1318-0"		

8679423001	"9-1197946-2", "EPD94102A"		
7708113001	"1-1196005-7", "EPD48367A"		
CT92493001	"EPD116097A"		
3W02273001	"6-1193017-6", "EPD21472B"		
871269-000	"8-1202162-2", "0024E0811-0"		
1814413001	"4-1191318-9", "EPD60947Q"		
4407103001	"6-1193313-7", "7524A1311-9"		
CQ17693001	"120-OHM-2SJFR-26-1L(CO)"		
3145253001	"6-1192380-0", "5021K1P11-1L(CO)"		
EQ05103001	"100-OHM-2SJR-24-1(CO)"		
CQ39853001	"EPD45898QCK0503"		
CQ14263001	"EPD94392BCK0206"		
440788-000	"4-1193314-1", "5030A1318-9"		
D630573001	"9-1199924-1", "EPD96717A"		
CQ72613001	"EPD121314A"		
D066293001	"EPD104313A/1-1L(CO)"		

0022173001	"1190017-8", "EPD45898Q "		
7500973001	"8-1195849- 2", "EPD49551R/ 1-9"		
6658793001	"5026A1P17- 9(CO)", "3- 1195246-5"		
4276993001	"1193218-7", "7520A1311- 0(M)"		
9750493001	"1-1197535- 1", "EPD84488A "		
CT36333001	"EPD113286 A", "7- 1899562-4"		
0071903001	"9-1199973- 8", "EPD96496A/ 1-6(CO)"		
4959483001	"1200145-6", "EPD93086R"		
CQ70183001	"EPD118342 B/1-0(CO)"		
F945593001	"EPD91814A ", "1- 1200450-3"		
6778253001	"1-1195329- 5", "EPD66710Q/ 2-1L(CO)"		
CD04033001	"EPD98865Q/ 1-2(CO)", "7- 1899110-9"		
EQ05163001	"EPD122871 A/3-2/0(CO)"		
4400605013	"1193307-6", "5024A1311- 0"		
CD63423001	"EPD107799 A", "8- 1899390-8"		
CQ79623001	"EPD117758 ACK0624"		
F707893001	"EPD94996L/ 1-9(CO)", "4- 1200931-0"		

F830823001	"3-1201424-9", "EPD95315Q/1-0(CO)"		
CQ34143001	"EPD109318Q/1-1L(M1)CK0399"		
CQ72703001	"EPD121323A"		
598901-000	"0024F0611-9", "1-1194735-0"		
CD17353001	"7528A1P18-9(FS)", "1-1899165-2"		
345115-000	"4-1192598-4", "EPD32991Q"		
CQ41803001	"EPD116262B/1-0(CO)"		
CT69993001	"CLFH178(FS)"		
CQ21043001	"EPD117758A"		
2901053001	"6-1192199-5", "EPD26467Q(S8M)"		
EQ15063001	"EPD118745ACK0202/5"		
1511013001	"4-1191092-6", "7526A1P17-9(CO)"		
6373453001	"8-1195038-9", "EPD69569B/1-1L(CO)"		
7358383001	"7-1199210-4", "EPD95412Q/1-1L(CO)"		
3422853001	"0024A0P11-1L(CO)", "1-1192580-7"		
CD40563001	"100-OHM-2SJFR-26-1L(CO)", "2-1899281-7"		

CT94933001	"EPD116422 A"		
EQ04163001	"EPD122605 ACK0427"		
E472043001	"6-1200523- 0", "EPD96002A/ 1-2(CO)"		
CQ67753001	"EPD120650 A/1-0(CO)"		
CQ60863001	"EPD116262 A/1-9(CO)"		
C312383001	"6-1200339- 4", "EPD98008L/ 2(CO)"		
3112553001	"7-1192355- 5", "EPD73089L"		
7743313001	"1196030-1", "EPD92872A "		
1450463001	"3-1191048- 9", "EPD26334B"		
A494623001	"3-1202050- 8", "EPD101753 B/1-1L(CO)"		
8176533001	"5-1196371- 6", "EPD46481D "		
C588213001	"5-1202050- 7", "EPD101747 B/1-9(CO)"		
CQ20603001	"EPD62444Q CK0206/5"		
0198333001	"5-1190154- 2", "EPD62977A CK0206"		
CQ56203001	"EPD116267 A"		
CQ53823001	"EPD107550 G/3(CO)"		
A228193001	"7-1201141- 8", "EPD94822M /2(CO)"		

CT75473001	"EPD115224 A/1-1L(CO)"		
4200303001	"2-1193164- 8", "5019D3318- 0"		
CD97503001	"EPD111118 A/1(CO)", "8- 1899527-3"		
5199403001	"5026A1317- 92(CO)", "4- 1198905-8"		
8279633001	"7528A1318- 0(M)", "1- 1196466-6"		
9253893001	"0024E0811- 0(CO)", "7- 1197177-8"		
CT94923001	"EPD107550 G/2-N(CO)"		
4710813001	"9-1193529- 0", "EPD70340L/ 1-1L(CO)"		
440077-003	"4-1193307- 6", "7524A1311- 0", "7524A1311- 0"		
1633733001	"2-1191179- 3", "EPD32856A/ 1-N(CO)"		
1442783003	"9-1191042- 0", "7820G0111- 9"		
CQ74633001	"EPD118342 C"		
D361883001	"3-1200932- 0", "EPD94996L/ 2(CO)"		
9193093001	"9-1197133- 3", "EPD32644A/ 7(CO)"		
2000723001	"1-1191449- 7", "5022A1P11- 1L"		

CT69663001	"EPD114764 A/1-1L(CO)"		
4262533001	"1193208-1", "5028A1P17- 1L(CO)"		
E050843001	"8-1202050- 7", "EPD101755 B/2(CO)"		
9528673001	"5024A1311- 0(CO)", "6- 1197378-0"		
C205553001	"9-1201424- 7", "EPD96684Q/ 1-9(CO)"		
7716403001	"1-1197945- 6", "EPD90786Q/ 1-0(CO)"		
CQ95333001	"EPD121046 A"		
CQ88533001	"EPD111051 ACK0624"		
CQ48073001	"EPD91697A CK0016"		
9850413001	"7522A1311- 02(CO)", "6- 1197609-3"		
CQ18653001	"EPD106513 ACK0213/2"		
C878183001	"6-1202050- 4", "EPD101755 B/1-9(CO)"		
4624353001	"3-1193468- 8", "5028A1P18- 1L(CO)"		
CT75873001	"0024K1811- 0(CO)"		
6306293001	"7-1194990- 7", "EPD8851F/3 -95(CO)"		
CD93053001	"EPD109318 Q/1-1L(M", "1899511-1"		
CQ61883001	"EPD120656 A/1-1L(M)"		

CQ30073001	"7524A1311-0(M2)CK2240"		
A210433001	"4-1201344-8", "2530A1318-0(CO)"		
6820833001	"6-1195361-3", "EPD24187D/1"		
4477173001	"3-1193364-2", "EPD4673G/2-1L(CO)"		
1978513001	"9-1191433-2", "CLFH316/1(CO)"		
CQ95383001	"EPD121054A"		
CD29293001	"CLFH178/1(FS)", "9-1899222-4"		
CD90373001	"EPD94436B", "7-1899500-3"		
CD67783001	"EPD75422B/1(CO)", "2-1899412-6"		
C565283001	"1-1201353-9", "2530A1P18-1L(CO)"		
8315683001	"2524E0311-9(2M)", "2-1199424-3"		
2366773001	"2-1191740-8", "EPD40252B"		
A906603001	"3-1201553-7", "EPD101496ACK0062"		
CQ76603001	"EPD117760ACK0298"		
CQ60823001	"EPD116262ACK0547"		
9658233001	"2524E0311-9(M)", "3-1197469-2"		

8664743001	"7-1199192-8", "EPD95011L CK0232"		
EQ06423001	"EPD122750 A"		
CT69733001	"EPD114765 A/2(CO)"		
5525433001	"5026A1311-0(CO)", "3-1194367-2"		
CT96803001	"EPD109318 QCK0646"		
CQ42253001	"EPD119031 A"		
C455603001	"7-1199955-4", "EPD78640L CK0121/5"		
1575013001	"1191138-3", "EPD85875A/ 1-1L(CO)"		
3V00253002	"1-1193016-6", "EPD21929A "		
CQ17563001	"EPD117898 A"		
CQ60663001	"EPD120521 A"		
2751653001	"0020D0P11-1L(CO)", "9-1192037-9"		
EQ00273001	"EPD121839 A/1(M)"		
C360583001	"9-1201799-8", "0024F0P11-1L(CO)"		
8719113001	"2-1196785-4", "CLFH316(S50)"		
CQ78393001	"EPD106513 ACK0213/4"		
5283113001	"9-1194149-1", "EPD61702L/ 1-0(M)"		

4297893001	"8-1193232-7", "5012A3311-0(CO)"		
CT68233001	"EPD105335 B"		
CD79663001	"EPD109318 QCK0456", "1-1899458-0"		
D849033001	"8-1200805-6", "EPD99114A"		
CT95973001	"EPD116546 A/1-1L(CO)"		
CQ76533001	"EPD109382 ACK0298/6"		
7506633001	"1-1195854-0", "EPD79182A/2(CO)"		
D767253001	"2524E0P11-9(SFS)", "1-1200677-5"		
6936963001	"5026A1311-9(CO)", "7-1197946-3"		
CD81963001	"0024K1811-0(3M)", "8-1899469-5"		
CQ42313001	"EPD31475Q CK0213/2"		
1473633001	"1191065-2", "EPD77622L/1-9(CO)"		
9453673001	"7522A1P11-9(CO)", "5-1197316-7"		
C382263001	"EPD104317 A/2(CO)"		
8798113001	"5030A1P17-9(CO)", "7-1196849-8"		
CQ82173001	"EPD121826 ACK0627"		
2734973001	"9-1192025-0", "EPD26168B"		
CT53353001	"EPD113521L /1(CO)"		

CD15673001	"EPD86888C/ 1-9(CO)", "9- 1899160-6"		
D313923001	"7-1202050- 2", "EPD101750 B/1-9(CO)"		
A228263001	"5-1200886- 3", "EPD99528A/ 1-9(CO)"		
CT64513001	"2020E0P11- 9(CO)"		
5982693001	"0024E0811- 0(M)", "4- 1194730-8"		
9780353001	"2530A1P17- 1L(CO)", "4- 1197556-2"		
CQ72343001	"EPD121287 A"		
C124923001	"5-1200831- 6", "EPD95723Q/ 1-9(CO)"		
2993173001	"1192266-9", "EPD20662B/ 1-1L(CO)"		
A752373001	"7-1200885- 0", "EPD99529A/ 1-9(CO)"		
CQ20693001	"EPD113842 Q(FS)"		
CQ79413001	"2018A1811- 0(CO)"		
CD95833001	"EPD111253 A/1(CO)", "2- 1899521-0"		
445133W002	"0022E0311- 0", "4- 1193345-3"		
CQ11923001	"EPD117497 A/1-9(M)"		
CQ72533001	"EPD121306 A"		
CQ02493001	"7522D5811- 0(3M)"		

E353583001	"2-1201866-6", "EPD95014A"		
CQ66853001	"EPD119343 ACK0206"		
CQ02463001	"100-OHM-2SJFR-24-9(CO)"		
9175513001	"9-1197121-0", "9530A1P17-1L(CO)"		
CQ42203001	"EPD119030 B"		
CQ55913001	"EPD77622M"		
CQ77083001	"EPD121137 A/1-6(CO)"		
5142593001	"5026A1P11-9(CO)", "1194040-3"		
CQ05143001	"EPD117170 A/1(CO)"		
7305333001	"1195707-2", "EPD44774N OBS"		
9994573001	"7522A1P12-1L(CO)", "8-1197726-5"		
CT74173001	"EPD114357 A/1-1L(CO)"		
CQ83803001	"EPD118179 A/1-91(CO)"		
EQ05223001	"EPD122871 A/3-5/9(CO)"		
A843803001	"2-1201166-7", "EPD100566 A/3(CO)"		
D923253001	"7-1201122-7", "EPD99496A"		
EQ06333001	"0024K1811-5(CO)"		
4451333001	"0022E0311-0", "4-1193345-2"		

C015353001	"1-1201761-1", "EPD101186 A/2(CO)"		
9785693001	"3-1197560-0", "EPD66400A "		
CQ42243001	"EPD119030 A"		
C951483001	"2-1200866-3", "CLFH178(C O)"		
440564K003	"2-1193312-7", "7522A1311-0"		
2433293001	"6-1191785-4", "EPD87667A/ 1(CO)"		
CT68203001	"EPD105062 C/1(CO)"		
9453513001	"4-1197316-9", "EPD4044/1-0(M)"		
3886093001	"6-1192917-4", "EPD67422A "		
CQ88133001	"EPD111051 A"		
5284033001	"4-1194150-9", "EPD44306A "		
445190-000	"0024A0311-0", "9-1193345-6"		
4229513001	"1-1193185-6", "EPD30506A "		
CQ57953001	"EPD35767Q CK0499"		
E440393001	"5-1201288-2", "EPD100153 A/1(M)"		

CQ95373001	"EPD121052 A"		
CQ56233001	"EPD116267 ACK0547"		
CD31413001	"EPD48325L/ 1(CO)", "2- 1899236-2"		
CT82893001	"EPD108704 ACK0254"		
F400213001	"EPD104315 A/1-1L(CO)"		
871269W002	"0024E0811- 0", "9- 1196780-2"		
CD38793001	"EPD66813R/ 1-9(CO)", "4- 1899272-9"		
D080913001	"1202044-7", "EPD101747 B"		
4435493001	"7-1193333- 6", "7530A1P17- 9(CO)"		
CD51433001	"EPD107883 A/1(CO)", "5- 1899338-0"		
CQ91613001	"0024K1811- 0(M1)(FS)"		
7211733001	"4-1195639- 3", "CLFH179/1(CO)"		
4451733004	"2524E0311- 0", "7- 1193345-0"		
CQ28083001	"EPD113842 Q/1-1L(M3)"		
CQ83573001	"EPD118179 A-0CK0547"		
CQ95303001	"EPD121041 A"		
440710-000	"6-1193313- 6", "7524A1311- 9"		
CQ61093001	"2530A0P14- 9(CO)"		

4330573001	"3-1193257-5", "5026A1P11-1L(CO)"		
CQ63113001	"7530A1318-9(CO)"		
509531-000	"7-1194005-4", "EPD22545D"		
F313813001	"8-1202044-6", "EPD101755 B"		
4644273001	"4-1193482-8", "7520A1811-0(M)"		
4401323004	"4-1193308-8", "5026A1317-9"		
2779793001	"4-1192058-2", "5020A1P11-N(CO)"		
A865373001	"2-1201166-8", "EPD100566 A/2(CO)"		
4235633001	"6-1193189-7", "EPD22252C"		
1446853001	"0024A0P11-9(CO)", "8-1191045-1"		
CT88123001	"120-OHM-2SJFR-24-9(CO)"		
1100893001	"1-1190804-6", "EPD32856A/1-1L(CO)"		
CQ77343001	"EPD60947Q CK0503/1"		
CQ61893001	"EPD120656 A/1-9(M)"		
CD67373001	"EPD108704 A", "9-1899409-4"		

2331513001	"5-1191712-7", "EPD44091Q"		
CQ44463001	"EPD35077A CK0503/2"		
D156513001	"1-1199934-8", "EPD84497B"		
CT85693001	"100-OHM-2SJFR-22-1L(CO)"		
0594953001	"4-1190451-6", "5020A3311-9(CO)"		
CQ70213001	"EPD118342 B"		
E372033001	"3-1200775-4", "EPD98957B/ 1-9(CO)"		
C412993001	"4-1200475-6", "EPD91814A/ 1-0(4M)"		
815137W002	"7524A1811-0", "3-1196352-2"		
798383W001	"2530A0614-9", "6-1196175-7"		
CQ74563001	"EPD118341 C/1-2(CO)"		
CQ18893001	"120-OHM-2SJFR-26-2(CO)"		
7786663001	"EPD104306 A/1-1L(CO)"		
893343-000	"0024A0311-0(FS)", "5-1196948-0"		
A806593001	"3-1201747-6", "EPD98865Q/ 1-9(CO)"		
200121-000	"5-1191449-9", "5019D3P18-1L"		

9813323001	"2524E0311-0(2M)", "5-1199424-7"		
A404573001	"EPD104311A/1-9(CO)"		
2001363002	"8-1191449-1", "5024A1P11-1L"		
5231813001	"4-1194110-5", "EPD48915Q"		
D767463001	"7520A1P11-9(CO)", "1-1200600-7"		
E862443001	"5019D3P18-9(CO)", "7-1200745-1"		
8778363001	"5-1199972-0", "EPD96496A/2(CO)"		
368955-000	"9-1192764-6", "EPD32856A/2"		
EQ02643001	"EPD35077ACK0206/4"		
CQ98663001	"EPD122399ACK0308"		
1722873001	"2-1191253-6", "EPD71607A/1-1L"		
9778713001	"1197555-7", "EPD7881J"		
F023493001	"EPD104448A/1-1L(CO)"		
CD24363001	"9530A1P18-N(CO)", "6-1899201-4"		
5244353001	"6-1194119-1", "6624D1P12-1L(CO)"		
4405643001	"2-1193312-6", "7522A1311-0"		

F456163001	"2-1201505-0", "EPD98738L/1-1L(CO)"		
420079-000	"7-1193164-4", "5028A3318-9"		
CD05093001	"EPD103722 A/1(CO)", "2-1899117-1"		
6772713001	"2-1195325-0", "7524A1P11-1L(CO)"		
CQ34183001	"EPD116438 A"		
E710853001	"1200885-7", "EPD99529A/5(CO)"		
4409013001	"4-1193315-7", "EPD64720Q"		
D774143001	"6-1200811-7", "EPD99113A/1-1L/9(CO)"		
3317493001	"8-1192506-4", "EPD69821Q"		
0058173001	"4-1190044-8", "EPD88002A"		
F119313001	"3-1201156-9", "EPD100628 A/1-9(CO)"		
CD76923001	"EPD105601 A/1-2(CO)", "1899449-3"		
D787103001	"EPD104346 A/1-1L(CO)"		
4326313001	"7-1193253-7", "EPD72946Q/1-1L"		
CQ95343001	"EPD121048 A"		

9618813001	"3-1197441-5", "EPD70340L/2"		
3969933001	"7-1192977-4", "EPD72946Q/1-9(CO)"		
4451903001	"0024A0311-0", "9-1193345-7"		
E338833001	"9-1202050-5", "EPD101744 B/2(CO)"		
3N08363001	"1193015-2", "EPD20664B"		
2832193001	"2-1192133-6", "EPD83126A"		
440473-000	"3-1193311-2", "5024A1312-9"		
A750053001	"8-1201400-0", "EPD98487C CK0900"		
CQ72123001	"EPD121265 A"		
CQ67843001	"EPD120650 A/5(CO)"		
CQ60583001	"0024B0P11-1L(CO)"		
4402953001	"1193310-8", "5026A1318-9"		
D548603001	"4-1200503-8", "EPD97016A"		
440094-000	"9-1193307-3", "5026A1318-0"		
A469083001	"0024A0P11-1L(SFS)", "1-1200767-7"		
CT98833001	"EPD115850 A"		

4406723001	"3-1193313-1", "7520A1311-0"		
A878313001	"9530A1P14-9(CO)", "1200600-7"		
D430333001	"1-1199839-8", "7526A1317-0(12M)"		
EQ12043001	"EPD112330L CK0624"		
CD93763001	"6-1899514-1", "EPD111033 A/1-9(CO)"		
CQ74573001	"EPD118341 C/1-6(CO)"		
CD75193001	"EPD104280 A/1-9(CO)", "6-1899443-5"		
CT74303001	"EPD115106 QCK0456/1"		
8109673001	"9-1196301-8", "EPD32178C"		
C979413001	"5-1201790-6", "EPD101039L /2-1L/9(M)"		
CQ72593001	"EPD121312 A"		
CD43343001	"0028G1P14-9(CO)", "2-1899300-5"		
9146933001	"4-1197101-2", "EPD26337B"		
C619973001	"5-1202050-9", "EPD101753 B/2(CO)"		
144278W001	"9-1191042-3", "7820G0111-9"		
5661153001	"9-1194470-3", "EPD66710Q/ 1(CO)"		

6542573001	"5026A1P18-1L(CO)", "1195162-9"		
EQ05263001	"100-OHM-2SJR-24-9(CO)"		
A926993001	"0024A0P11-9(SFS)", "2-1200767-7"		
A284773001	"3-1201408-0", "7524A1811-0(5M)"		
CQ72563001	"EPD121309 A"		
CQ18953001	"EPD117888 A/2(CO)"		
CQ21033001	"EPD117757 A"		
C825683001	"2-1200878-5", "EPD60603C"		
EM0645-000	"2022A1811-0"		
5851123001	"4-1199515-6", "EPD64983B/1-9(2M)"		
CD31553001	"120-OHM-2SJR-22-9(CO)", "1899237-7"		
CD85073001	"EPD35077A CK0206", "5-1899482-5"		
D660153001	"1-1201872-9", "CLFH316"		
7324733001	"8-1195721-8", "EPD72947A/1-1L(CO)"		
1875353001	"1-1191361-9", "EPD25986C/1-9(CO)"		
CQ76543001	"EPD117757 ACK0298/1"		
CQ11913001	"EPD117497 A/1-1L(M)"		

2009433001	"8-1191456-7", "5012A3P11-1L"		
4675233001	"3-1193504-7", "EPD62976A/1-9(CO)"		
2770673001	"7-1192051-7", "EPD73307R/1-9(CO)"		
6433013001	"8-1195082-6", "EPD79182A"		
CQ56153001	"EPD116267A/1-96(CO)"		
CT88113001	"120-OHM-2SJFR-24-1L(CO)"		
4189773001	"8-1193156-2", "5030A1114-9(CO)"		
EQ02793001	"EPD120795B"		
E257633001	"0024A0311-0(2M)", "5-1199713-8"		
C495213001	"3-1201419-3", "EPD95313A"		
CQ74623001	"EPD118342C/1-6(CO)"		
5944953001	"9-1194699-8", "EPD91387A/1-9"		
CT62693001	"7530A1318-9(M)", "7-1899599-6"		
CT82763001	"EPD115671A/1-9(CO)"		
9268273001	"7-1197187-9", "CLFH178(S50)"		

A752283001	"3-1201192-4", "EPD92472A"		
CQ89573001	"EPD35589A CK0213/1"		
CQ83713001	"EPD121866 A/1-6(CO)"		
CQ73783001	"EPD121177 A/1-1L"		
CQ73523001	"EPD121391 A"		
CQ42053001	"EPD119031 A/1-9"		
CD56143001	"EPD108037 A/1-1L/9(CO)", "5-1899362-4"		
CT82753001	"EPD115671 A/1-1L(CO)"		
CD22533001	"EPD106301 A", "6-1899197-6"		
155497-000	"5-1191123-5", "EPD33374A"		
CD37363001	"CLFH-179-0(3M)", "6-1899264-4"		
A777173001	"7-1201422-6", "EPD96684Q/ 2-1L/9(CO)"		
C772663001	"6-1202050-2", "EPD101747 B/2(CO)"		
CQ76673001	"EPD118141 ACK0298"		
CQ70203001	"EPD118342 B/1-6(CO)"		
1013813001	"1190742-2", "EPD40889J"		
CQ16073001	"EPD117248 A"		
CQ65783001	"EPD65220Q CK0647"		

1330073001	"1190966-1", "5020A1811- 0(M)"		
8725713001	"8-1196789- 7", "EPD66710Q "		
A840543001	"7-1201422- 9", "EPD94988A/ 1(CO)"		
EQ03223001	"EPD122728 A"		
CQ78353001	"EPD118102 ACK0298"		
E736713001	"1201058-3", "FMC- 0002A/1- 9(CO)"		
A187633001	"EPD104317 A/1-9(CO)"		
1313073001	"7-1190954- 2", "EPD83644L/ 1-9(M)"		
794567-000	"2-1196151- 0", "EPD35077A "		
1395113001	"7-1191011- 4", "EPD32856A/ 1-1L"		
CQ13743001	"EPD117489 A"		
440564-000	"2-1193312- 5", "7522A1311- 0"		
F539293001	"1-1202051- 8", "EPD101750 B/1-1L(CO)"		
F640103001	"EPD98077L/ 1(CO)", "2- 1200659-8"		
9441473001	"5024A1P11- 9(FS)", "6- 1197308-4"		
CQ34043001	"EPD118102 A"		

CQ98143001	"EPD120794 ACK1120"		
D141413001	"2-1200827- 1", "EPD95723Q "		
CQ71913001	"EPD105273 ACK0298/4"		
7596283001	"5020A3311- 0(3M)", "8- 1198920-2"		
810967-000	"9-1196301- 7", "EPD32178C"		
CD16643001	"EPD104312 B/2-1L/9- 0(CO)", "4- 1899162-1"		
CQ29913001	"5020A1311- 0(M1)CK224 0"		
A635943001	"4-1201452- 2", "CLFH- 179-0(8M)"		
4780483001	"5-1197947- 2", "EPD93789A/ 1-1L/9(CO)"		
8221353001	"7-1196411- 2", "EPD85875A/ 1-0(CO)"		
F455343001	"6-1201547- 6", "7528A1P14- N(CO)"		
CQ67813001	"EPD120650 A/2(CO)"		
CD16833001	"EPD104312 B/1-1L(CO)", "8-1899162- 0"		
CQ20703001	"EPD113842 QCK5700"		
CD59693001	"EPD106482 A/1-9(CO)", "3-1899377- 9"		
EQ05233001	"EPD122871 A/3-6/9(CO)"		

CQ51973001	"EPD119924 A/1-9(CO)"		
CQ98353001	"EPD29057A CK0206"		
CT98953001	"EPD116681 A"		
CD72743001	"EPD107922 ACK0210", "2-1899435- 0"		
0194653001	"9-1190151- 2", "EPD67891L"		
D515533001	"1201175-8", "9530A1114- 9(8M)"		
7086793001	"1-1195554- 5", "EPD69569A "		
6716173002	"9-1195284- 5", "EPD42811B(HB)-OBS"		
CD13843001	"EPD105685 A", "9- 1899153-1"		
CQ95293001	"EPD121039 A"		
2682223001	"6-1199602- 8", "5030A1P14- 9(CO)"		
CT01923001	"EPD113292 A", "8- 1899547-2"		
EQ05393001	"EPD122844 ACK0624"		
D597253001	"6-1201419- 0", "EPD94863L"		
C522643001	"EPD104448 A/1-9(CO)"		
CD22323001	"7528A1318- 0(3M)", "4- 1899196-7"		
CQ56143001	"EPD116267 A/1-93(CO)"		
F698023001	"EPD104319 A/1-1L(CO)"		

4419443001	"0024A0311-9", "7-1193322-4"		
200217-000	"7-1191450-6", "7528A1P17-1L"		
CQ74763001	"EPD121437 A"		
D435543001	"1-1200674-4", "EPD97565Q/1-9(CO)"		
E900633001	"8-1201288-1", "CLFH-179CK0135"		
4404203001	"8-1193310-7", "5038A1318-9"		
1397653001	"5-1191013-7", "5028A1P14-1L(CO)"		
440555-000	"1-1193312-4", "7522A1312-0"		
CT98823001	"EPD115849 A"		
CQ45263001	"EPD105273 ACK0298/2"		
440088W007	"7-1193307-9", "7528A1318-0"		
E781803001	"9-1201419-3", "EPD96684Q"		
CD17533001	"7528A1318-0(CO)", "9-1899165-8"		
CQ84803001	"EPD29116D"		
F766673001	"EPD99529A/2(CO)", "3-1200885-8"		
CQ84233001	"EPD106513 ACK0213/5"		

CD62733001	"EPD108392 A", "3- 1899387-4"		
CQ83753001	"EPD118179 A/1-3(CO)"		
CQ79183001	"EPD121023 A"		
E773543001	"4-1200536- 8", "EPD98516B"		
CQ60833001	"EPD116262 ACK0547/2"		
CQ87003001	"EPD121857 B"		
4101093001	"3-1193093- 4", "5026A1317- 0(CO)"		
5167273001	"8-1194057- 0", "EPD77564A "		
E621563001	"9-1200930- 5", "EPD94996L/ 1-1L(CO)"		
3425653001	"2-1192581- 5", "EPD72004A "		
E827303001	"1-1201830- 5", "EPD93792A/ 1(CO)"		
E020373001	"5-1201004- 1", "EPD99489Q "		
CD93863001	"7-1899514- 1", "EPD111093 A/1-9(CO)"		
CQ83763001	"EPD118179 A/1-93(CO)"		
E859813001	"EPD104346 A", "7- 1899071-1"		
4405633002	"2-1193312- 4", "7526A1317- 0"		

1755183001	"7-1198899-8", "5026A1317-96(CO)"		
8268013001	"2-1196458-1", "EPD66677A"		
F407103001	"0022E0P11-9(CO)", "1-1200480-0"		
CQ27963001	"EPD113842 Q/1-9CK0399/2"		
CQ06413001	"EPD109318 QCK0456/25"		
E847763001	"6-1201021-7", "EPD100319 A/1-1L(CO)"		
5897653001	"1-1194666-6", "EPD69569A/1-1L"		
CT91983001	"EPD106513 ACK0202/3"		
F804103001	"5-1202088-8", "0026A0014-9(CO)"		
5992853001	"2524E0P11-9(M)", "7-1194737-3"		
2001653001	"2-1191450-9", "5028A1P14-1L"		
F959153001	"EPD2029J", "1200752-2"		
C124163001	"1-1201142-0", "EPD94821L/2(CO)"		
CQ05063001	"EPD117170 ACK0298"		
630519W002	"1-1194990-0", "EPD35767Q"		
4406403001	"1193313-4", "9530A1317-9"		

7729693001	"9-1196019-5", "EPD43356A"		
CD84023001	"EPD109365 A/5(CO)", "1-1899478-1"		
1554973001	"5-1191123-6", "EPD33374A"		
CD02303001	"EPD104855 A/1-9(CO)", "3-1899102-2"		
1983053001	"6-1191436-6", "EPD60608B/1-9(CO)"		
CD86953001	"EPD108829 QCK0355", "1-1899490-5"		
9332133001	"5-1197232-9", "EPD36388Q"		
3535293001	"1-1192655-7", "EPD85996A/1(CO)"		
5320833001	"2-1194178-0", "EPD31173A"		
CQ77583001	"EPD94392B CK0206/6"		
CD84233001	"EPD63976A/1-1L(CO)", "3-1899479-4"		
CQ74503001	"EPD118396 ACK0298"		
6870993001	"5024A1P14-9(CO)", "8-1195394-7"		
8816993001	"6-1196863-0", "EPD86444A/1(CO)"		

CD78743001	"EPD62444Q CK0206/4", "6-1899452- 2"		
A383613001	"6-1201424- 0", "EPD96684Q/ 1-1L(CO)"		
CQ79393001	"2018A1P11- 1L(CO)"		
CQ53763001	"EPD119989 A"		
CQ87563001	"EPD115373 ACK0193"		
CQ17703001	"120-OHM- 2SJFR-26- 9(CO)"		
CQ91683001	"0024K1811- 0(M4)"		
CQ31663001	"EPD118141 A"		
8279833001	"7526A1811- 0(CO)", "2- 1196466-9"		
8958613001	"1196966-3", "EPD23197B/ 1-9(CO)"		
CQ64083001	"EPD119157 A"		
CQ73513001	"EPD121390 A"		
CD31483001	"EPD106743 A/2(CO)", "7- 1899236-3"		
CD28673001	"7528A1318- 0(2M)", "2- 1899220-0"		
CQ82593001	"EPD121661 A/1-1L(CO)"		
944147-000	"5024A1P11- 9(FS)", "6- 1197308-3"		
4414673001	"5-1193319- 8", "5024A1811- 0(M)"		
CQ48543001	"EPD119844 A"		

4400775007	"5-1193307-1", "7524A1311-0"		
445190K004	"0024A0311-0", "1193346-1"		
7438733001	"5028A1318-0(CO)", "3-1195803-5"		
965823-000	"2524E0311-9(M)", "3-1197469-1"		
C468603001	"8-1200522-4", "EPD96002A/2(CO)"		
9007623001	"9-1197946-9", "EPD93901A/1-1L/9(CO)"		
5858753001	"3-1194638-0", "EPD87667A/3-9(M)"		
7611813001	"6-1195928-1", "EPD39928B"		
F777963001	"2-1201349-5", "EPD98750A/2(CO)"		
CQ83673001	"EPD116265 A/3(CO)"		
CD31493001	"EPD106743 A/3(CO)", "7-1899236-4"		
595063-000	"1194706-8", "EPD4044/2-1L"		
CD50143001	"7524A1P11-N(CO)", "1899332-8"		
0267773001	"5-1190207-1", "EPD71607A/1-1L(CO)"		
C857773001	"5-1201566-6", "EPD102033 A"		

6746283001	"1197959-3", "EPD83644L/ 1-1L(CO)"		
5667093001	"1-1194475- 0", "EPD71607A "		
CT73943001	"120-OHM- 2SJFR-22- 9(CO)"		
1593473001	"3-1191151- 6", "7524A1811- 0(CO)"		
9581923001	"1-1201148- 7", "EPD95070A "		
CQ46813001	"EPD111051 ACK0298/1"		
8987793001	"2-1196986- 4", "EPD73248A/ 1-9(M)"		
CD69773001	"5026C1314- 0(CO)", "1899423-1"		
EQ05173001	"EPD122871 A/3- 2/1L(CO)"		
CD43153001	"2024A0P11- 1L(CO)", "4- 1899299-5"		
CQ30083001	"7524A1311- 0(M3)CK224 0"		
5946793001	"3-1194701- 8", "EPD49551R/ 1-1L(CO)"		
1952313001	"1191416-4", "EPD42812B"		
CD08963001	"9524A1P11- 9(CO)", "9- 1899132-6"		
6271753001	"6-1194966- 0", "EPD36197L"		
6029273001	"3-1194772- 4", "EPD66921L"		

CD69263001	"9530A1318-90(CO)", "2-1899421-0"		
CD89583001	"EPD106672 A", "4-1899498-6"		
CD22573001	"7528A1318-0(5M)", "1899198-2"		
9741233001	"3-1197528-4", "EPD72946Q(S101)"		
A345503001	"2-1201708-7", "EPD45898QCK0391"		
C424833001	"7-1200885-1", "EPD99530A/1-1L(CO)"		
D247363001	"EPD104312 A/2-1L/9(CO)"		
C108323001	"4-1201459-1", "EPD24256A/1-1L(CO)"		
CQ20423001	"EPD67364QCK0603"		
4405993001	"7-1193312-6", "7528A1318-9"		
CQ42063001	"EPD119031 A/1-1L"		
CQ12293001	"EPD111557 A"		
CQ36083001	"EPD117603 ACK0298/1"		
5000693001	"2-1193738-5", "EPD71607A/2"		
5963563001	"8-1200337-7", "EPD98008L/1-1L(CO)"		
CQ70123001	"EPD118341 B"		

F993703001	"2-1201767-4", "EPD101036Q"		
CT85703001	"100-OHM-2SJFR-22-9(CO)"		
A084833001	"9-1201877-6", "EPD103284Q/1-1L(CO)"		
E442733001	"8-1201419-2", "EPD94988A"		
C384143001	"EPD104314A/1-9(CO)"		
9579623001	"5026A1317-9(CO)", "1-1198896-2"		
CQ70253001	"EPD111050ACK0298/3"		
D177133001	"3-1201348-1", "EPD101254A/1(CO)"		
0270753001	"6-1190209-6", "5030A1318-9(CO)"		
F722923001	"2-1201349-4", "EPD98750A/1-9(CO)"		
CQ76903001	"EPD31475QCK0206/5"		
CQ91623001	"0024K1811-0(M2)(FS)"		
CD18383001	"7520A1811-0(3M)", "1899172-4"		
F930513001	"EPD104308A/1-9(CO)"		
CQ87733001	"EPD122014ACK0193"		
CD51243001	"0024E0P11-1L(CO)", "8-1899337-8"		
CQ88013001	"EPD111050ACK0624"		

CQ77103001	"EPD121138 A/1-9(CO)"		
4645913001	"8-1193483- 0", "EPD83644L"		
CQ72193001	"EPD121272 A"		
CD93493001	"120-OHM- 2SJR-24- 9(CO)", "3- 1899512-4"		
CQ75423001	"EPD94392B CK0206/4"		
A054943001	"4-1200886- 9", "EPD99528A/ 4(CO)"		
CQ45683001	"EPD31475Q CK0213/3"		
CD59713001	"EPD35077A CK0503", "6- 1899377-1"		
D322563001	"EPD104307 A/1-1L(CO)"		
CQ77653001	"EPD31475Q CK0206/6"		
CQ02133001	"EPD115540 A"		
4405553001	"1-1193312- 5", "7522A1312- 0"		
1051653001	"8-1190768- 2", "EPD64158A "		
D450303001	"EPD104343 A/1-1L(CO)"		
7202573001	"5-1195632- 2", "EPD29110Q "		
CQ45563001	"7528F1P14- 9(CO)"		
CQ68293001	"EPD94392B CK0206/2"		
CQ38263001	"EPD118758 A"		

1981143001	"4-1199482-6", "5030A1P14-1L(CO)"		
CT89513001	"EPD116119 A/1-1L(CO)"		
CQ28103001	"EPD113842 Q/1-9(M4)"		
0517093001	"8-1190395-9", "9530A1317-9(CO)"		
CQ72293001	"EPD121282 A"		
CQ17553001	"EPD117867 A"		
6943913001	"5026A1811-0(CO)", "1-1195448-4"		
CQ88103001	"EPD122008 A"		
D351403001	"EPD104310 A/1-1L(CO)"		
9302513001	"4-1197211-8", "EPD63054C/2(CO)"		
EQ10443001	"5026C1314-0(M)"		
0454333001	"1-1190349-7", "CLFH400/1(CO)"		
CQ28093001	"EPD113842 Q/1-9(M2)"		
CD74833001	"EPD108166 A", "2-1899441-9"		
4407873001	"4-1193314-0", "7522A1311-9"		
6284413001	"4-1194975-1", "7530E1P14-9(CO)"		
1341963001	"1200147-2", "EPD93086R/1-9(CO)"		

431175-000	"1193243-4", "EPD32707A/ 1"		
EQ06243001	"EPD122605 B/1(CO)"		
CD00973001	"EPD104855 A/2(CO)", "3- 1899094-6"		
CQ20433001	"EPD67364Q CK0603/1"		
E381493001	"9-1201545- 1", "EPD101379 Q"		
F615273001	"6-1201500- 8", "5020A3811- 02(CO)"		
CD45233001	"EPD45898Q CK0054", "9- 1899308-4"		
E508573001	"5-1200834- 3", "EPD91697A "		
CQ28063001	"EPD113842 Q/1- 9(M4)(FS)"		
CQ69713001	"EPD119343 ACK0206/1"		
6076173001	"5-1194806- 6", "7522A1811- 0(CO)"		
420030-000	"2-1193164- 7", "5019D3318- 0"		
CT64843001	"2020E0811- 0-UK"		
3451153001	"4-1192598- 5", "EPD32991Q "		
4311753001	"1193243-5", "EPD32707A/ 1"		
440555W002	"1-1193312- 6", "7522A1312- 0"		

7672533001	"5022A1P11-1L(CO)", "3-1195979-7"		
440808W002	"5-1193314-7", "9530A1318-9"		
CQ73413001	"EPD121378 A"		
CD80823001	"EPD107731 A", "6-1899466-9"		
CQ38203001	"0028A0P11-1L(CO)"		
CD56453001	"120-OHM-2SJR-20-1L(CO)", "9-1899362-9"		
EQ02423001	"EPD122640 A"		
6343393001	"2-1195017-2", "EPD31173A/1-1L(CO)"		
CD76593001	"EPD108998L", "5-1899447-8"		
9808893001	"7-1197579-5", "EPD25986C"		
3782133001	"1192832-6", "5024A1811-0"		
CQ41973001	"EPD119030 A/3(CO)"		
2572753001	"8-1191882-8", "EPD49551R/1-9(CO)"		
A926753001	"7820G0111-9(3M)", "7-1200716-0"		
CT89133001	"EPD107550 G/2(CO)"		
CQ83723001	"EPD121866 A/1-9(CO)"		
7915673001	"8-1196130-2", "EPD44774M OBS"		

EQ05143001	"100-OHM-2SJR-24-6(CO)"		
A487383001	"8-1201286-0", "CLFH179-0(M)"		
6305193001	"1194990-9", "EPD35767Q"		
440640-000	"1193313-3", "9530A1317-9"		
5494953001	"7-1194323-9", "EPD66997B"		
5774563001	"4-1198981-6", "CLFH400"		
A056163001	"1-1202176-4", "EPD48679R/ 1-1L(CO)"		
E234503001	"2-1201194-5", "7820G0111-9(4M)"		
5144513001	"2-1194041-8", "EPD23197B(M)"		
A389093001	"EPD104306 A/1-9(CO)"		
CQ41873001	"EPD116255 A/1-9(CO)"		
CQ19023001	"EPD35077A CK0440"		
CQ13013001	"2024A0111-9(CO)"		
9500073001	"7-1197347-8", "EPD70340L/ 1-1L"		
183433-000	"3-1191332-7", "EPD33017Q"		

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.

Alert document created by IHS Markit based on content provided by TE Connectivity.