



# Product Change Notification

Current Date: 11-Jun-2023

## TE Connectivity

**Product Change Notification:** P-23-024676

**PCN Date:** 08-JUN-23

**Customer:** TTI EMEA USD ( 2843232 )

**Location:** Maisach-Gerlinden

**Agreement:** Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

**General Product Description:**  
Polamco brand Backshells and accessories

**Description of Changes**  
Second source qualification. Following Part Numbers are being approved to be manufactured at an outside vendor.

**Reason for Changes:**  
Dear Customer, as a result of our continuous strive to aid our lead-time recovery initiative, we hereby inform you about the use of a second source for components used in these products, the secondary operations remain as today. The qualification is executed by following a strict transfer procedure, which guarantees no negative influence on quality, ability to supply and form-fit-function of the concerned products. The second manufacturing location is under a certified quality management system according to standard industry requirements. An internal release based on our specifications will be executed before any parts will be delivered, which guarantees the performance.

Estimated Dates:	
<b>Last Order Date</b> (Obsolete Parts Only):	<b>First Date To Ship</b> (Changed Parts Only):
	07-AUG-2023
<b>Last Ship Date</b> (Obsolete Parts Only):	<b>Last Date for Mixed Shipments:</b> (Changed Parts Only):
	No Mixed Shipments

**Part Number(s) being Modified:**

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">638339-000</a>	NO			8-1195045-7, TXR40AB00-1414AI			
<a href="#">928279-000</a>	NO			1197198-1, TXR41AB90-1006AI			
<a href="#">F17064-000</a>	NO			8-1200561-2, TXR76AU90-1006BI			



# Product Change Notification

Current Date: 11-Jun-2023

## TE Connectivity

**Product Change Notification:** P-23-024676

**PCN Date:** 08-JUN-23

**Customer:** TTI, Inc. ( 1305175 )

**Location:** Maisach-gernlinden

**Agreement:** EU-TTI-MASTK

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

**General Product Description:**

Polamco brand Backshells and accessories

**Description of Changes**

Second source qualification. Following Part Numbers are being approved to be manufactured at an outside vendor.

**Reason for Changes:**

Dear Customer, as a result of our continuous strive to aid our lead-time recovery initiative, we hereby inform you about the use of a second source for components used in these products, the secondary operations remain as today. The qualification is executed by following a strict transfer procedure, which guarantees no negative influence on quality, ability to supply and form-fit-function of the concerned products. The second manufacturing location is under a certified quality management system according to standard industry requirements. An internal release based on our specifications will be executed before any parts will be delivered, which guarantees the performance.

**Estimated Dates:**

<b>Last Order Date</b> (Obsolete Parts Only):	<b>First Date To Ship</b> (Changed Parts Only):
	07-AUG-2023
<b>Last Ship Date</b> (Obsolete Parts Only):	<b>Last Date for Mixed Shipments:</b> (Changed Parts Only):
	No Mixed Shipments

**Part Number(s) being Modified:**

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">002801-000</a>	NO		RAY002801-000	6-1190021-3, <b>TXR40AC00-0804AI</b>			
<a href="#">031121-000</a>	NO			5-1190241-9, <b>TXR40AB00-2210AI</b>			
<a href="#">121571-000</a>	NO		RAY121571-000, RAYTXR40AB00-1610AI	9-1190884-5, <b>TXR40AB00-1610AI</b>			
<a href="#">131191-000</a>	NO		RAY131191-000	7-1190953-1, <b>TXR40AC00-1410AI</b>			
<a href="#">144415-000</a>	NO			7-1191043-4, <b>TXR76AB00-1004BI</b>			
<a href="#">146995-000</a>	NO		RAY146995-000	3-1191062-0, <b>TXR40AB00-1410AI</b>			
<a href="#">152201-000</a>	NO			1191100-9, <b>TXR54AB00-1812BI</b>			
<a href="#">232199-000</a>	NO		RAY232199-000	7-1191705-7, <b>STXR54AB00-1412AI</b>			
<a href="#">263535-000</a>	NO		RAY263535-000	7-1191939-2, <b>STXR40AB00-1008AI</b>			
<a href="#">279435-000</a>	NO			1-1192068-9, <b>TX54AB00-1812</b>			
<a href="#">293973-000</a>	NO		RAY293973-000	7-1192227-3, <b>TXR40AB00-1612AI</b>			
<a href="#">296535-000</a>	NO			4-1192246-6, <b>TXR41AB00-1605AI</b>			
<a href="#">305189-000</a>	NO			8-1192310-6, <b>TXR41AB90-1406BI</b>			
<a href="#">320635-000</a>	NO		RAY320635-000	8-1192430-7, <b>TXR41AB00-1406AI</b>			
<a href="#">323201-000</a>	NO			4-1192446-7, <b>TXR40AB00-1414BI</b>			
<a href="#">396063-000</a>	NO		RAY396063-000	9-1192970-5,			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
				<b>TXR40AB00-2410AI</b>			
<a href="#">402333-000</a>	NO		RAY402333-000	4-1193037-3, <b>TXR54AB00-2206AI</b>			
<a href="#">404609-000</a>	NO			9-1193053-0, <b>TXR54AB90-1812AI</b>			
<a href="#">411287-000</a>	NO			9-1193101-2, <b>TXR21AB00-2012AI</b>			
<a href="#">423209-000</a>	NO		RAY423209-000	1193187-1, <b>TXR40AB00-0804AI</b>			
<a href="#">423509-000</a>	NO		RAY423509-000	2-1193189-8, <b>TXR40AB00-1608BI</b>			
<a href="#">433093-000</a>	NO			6-1193257-1, <b>TXR54AB90-1608AI</b>			
<a href="#">447297-000</a>	NO		RAY447297-000	3-1193361-8, <b>TXR76AB00-1605AI</b>			
<a href="#">470290-000</a>	NO			3-1193524-1, <b>TXR41AB00-1206AI</b>			
<a href="#">478803-000</a>	NO		RAY478803-000	9-1193584-9, <b>TXR40AB00-1606AI</b>			
<a href="#">497361-000</a>	NO		RAY497361-000	7-1193718-5, <b>TXR40AB00-1208AI</b>			
<a href="#">529029-000</a>	NO			9-1194154-8, <b>TXR40AB00-1807BI</b>			
<a href="#">562469-000</a>	NO		RAY562469-000	2-1194444-3, <b>TXR40AB00-2008AI</b>			
<a href="#">574595-000</a>	NO			6-1194560-8, <b>TXR40AB00-0808AI</b>			
<a href="#">581607-000</a>	NO		RAY581607-000	1194608-1, <b>TXR40AB00-2418AI</b>			
<a href="#">606079-000</a>	NO			9-1194794-5, <b>STXR41AB00-1008AI</b>			
<a href="#">627065-000</a>	NO			7-1194965-6, <b>TXR54AB00-2216AIJ</b>			
<a href="#">629267-000</a>	NO		RAY629267-000	2-1194981-0, <b>TXR40AB00-1608AI</b>			
<a href="#">638339-000</a>	NO		RAY638339-000	8-1195045-7, <b>TXR40AB00-1414AI</b>			
<a href="#">658819-000</a>	NO		RAY658819-000	9-1195193-4, <b>TXR40AB00-1006AI</b>			
<a href="#">664529-000</a>	NO		RAY664529-000	5-1195236-1, <b>TXR40AB00-1206AI</b>			
<a href="#">678333-000</a>	NO			7-1195332-4, <b>TXR76AB00-1006BI</b>			
<a href="#">697581-000</a>	NO		RAY697581-000	1195475-3, <b>TXR41AB00-1607AI</b>			
<a href="#">738073-000</a>	NO		RAY738073-000	9-1195761-9, <b>TXR40AB00-1605AI</b>			
<a href="#">754567-000</a>	NO			2-1195882-0, <b>TXR76AB00-1006AI</b>			
<a href="#">757063-000</a>	NO		RAY757063-000	4-1195899-5, <b>TXR40AB00-0807AI</b>			
<a href="#">782993-000</a>	NO		RAY782993-000	2-1196081-5, <b>TXR41AB00-1807AI</b>			
<a href="#">808520-000</a>	NO			1-1196277-3, <b>201M914-19G</b>			
<a href="#">809289-000</a>	NO			5-1196289-1, <b>225M510-19U</b>			
<a href="#">815689-000</a>	NO		RAY815689-000	8-1196356-4, <b>TXR40AB00-2208AI</b>			
<a href="#">820593-000</a>	NO		RAY820593-000	3-1196398-9, <b>TXR40AB00-2012AI</b>			
<a href="#">825981-000</a>	NO			6-1196451-0, <b>TXR18AB00C2008AI</b>			
<a href="#">889283-000</a>	NO		RAY889283-000	5-1196918-3, <b>TXR40AB00-1607AI</b>			
<a href="#">921653-000</a>	NO		RAY921653-000	1197151-4, <b>TXR40AB00-1006BI</b>			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">928279-000</a>	NO			1197198-1, TXR41AB90-1006AI			
<a href="#">929031-000</a>	NO		RAY929031-000	1197203-9, TXR40AB00-1814AI			
<a href="#">942153-000</a>	NO			6-1197294-7, TXR40AC00-1607AI			
<a href="#">961557-000</a>	NO		RAY961557-000	1197439-8, TXR76AB00-1205AI			
<a href="#">963563-000</a>	NO		RAY963563-000	1197453-9, TXR54AB00-1406AI			
<a href="#">966286-000</a>	NO		RAY966286-000	1-1197472-0, TXR40AB00-2218AI			
<a href="#">996637-000</a>	NO			4-1197706-8, TXR40AB00-0806AI			
<a href="#">A05958-000</a>	NO			3-1201548-2, STXR40AU00-1008BI			
<a href="#">A85293-000</a>	NO			5-1200390-7, TXR40AB00-0810AI			
<a href="#">C07299-000</a>	NO			TXR40AU00-1814AI			
<a href="#">C73862-000</a>	NO		RAYC73862-000	6-1200810-6, TXR40AU00-1006AI			
<a href="#">C91223-000</a>	NO			6-1200401-4, TXR40AU00-1206BI			
<a href="#">CH5545-000</a>	NO			7-1899671-3, TXR40AZ00-1610AI			
<a href="#">CL6086-000</a>	NO			6-1899358-9, TXR76AU90-1207BI			
<a href="#">CW0597-000</a>	NO			TX40AZ00-1814			
<a href="#">CW0601-000</a>	NO			TX54AZ00-1406			
<a href="#">CW0601N001</a>	NO						
<a href="#">CX9353-000</a>	NO			TX40AZ00-2016			
<a href="#">D11523-000</a>	NO			7-1200820-7, STXR40AB90-0806AI			
<a href="#">E03665-000</a>	NO			8-1200500-5, TXR40AU00-1410BI			
<a href="#">E47391-000</a>	NO			9-1200500-0, TXR40AU00-1006BI			
<a href="#">EB9458-000</a>	NO		RAYEB9458-000	TXR40AZ00-1006AI			
<a href="#">EB9459-000</a>	NO			TXR40AZ00-1006BI			
<a href="#">EB9460-000</a>	NO		RAYEB9460-000	TXR40AZ00-1206AI			
<a href="#">EB9465-000</a>	NO			TXR40AZ00-1410BI			
<a href="#">F17064-000</a>	NO		RAYF17064-000	8-1200561-2, TXR76AU90-1006BI			
<a href="#">F85976-000</a>	NO		RAYF85976-000	9-1200801-8, TXR76AU00-1006AI			



# Product Change Notification

Current Date: 11-Jun-2023

## TE Connectivity

**Product Change Notification:** P-23-024676

**PCN Date:** 08-JUN-23

**Customer:** TTI, Inc. ( 3057778 )

**Location:** Maisach-gernlinden

**Agreement:** Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

**General Product Description:**  
Polamco brand Backshells and accessories

**Description of Changes**  
Second source qualification. Following Part Numbers are being approved to be manufactured at an outside vendor.

**Reason for Changes:**  
Dear Customer, as a result of our continuous strive to aid our lead-time recovery initiative, we hereby inform you about the use of a second source for components used in these products, the secondary operations remain as today. The qualification is executed by following a strict transfer procedure, which guarantees no negative influence on quality, ability to supply and form-fit-function of the concerned products. The second manufacturing location is under a certified quality management system according to standard industry requirements. An internal release based on our specifications will be executed before any parts will be delivered, which guarantees the performance.

**Estimated Dates:**

<b>Last Order Date</b> (Obsolete Parts Only):	<b>First Date To Ship</b> (Changed Parts Only):
	07-AUG-2023
<b>Last Ship Date</b> (Obsolete Parts Only):	<b>Last Date for Mixed Shipments:</b> (Changed Parts Only):
	No Mixed Shipments

**Part Number(s) being Modified:**

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">002801-000</a>	NO		RAY002801-000	6-1190021-3, <b>TXR40AC00-0804AI</b>			
<a href="#">121571-000</a>	NO		RAY121571-000, RAYTXR40AB00-1610AI	9-1190884-5, <b>TXR40AB00-1610AI</b>			
<a href="#">131191-000</a>	NO		RAY131191-000	7-1190953-1, <b>TXR40AC00-1410AI</b>			
<a href="#">146995-000</a>	NO		RAY146995-000	3-1191062-0, <b>TXR40AB00-1410AI</b>			
<a href="#">232199-000</a>	NO		RAY232199-000	7-1191705-7, <b>STXR54AB00-1412AI</b>			
<a href="#">263535-000</a>	NO		RAY263535-000	7-1191939-2, <b>STXR40AB00-1008AI</b>			
<a href="#">293973-000</a>	NO		RAY293973-000	7-1192227-3, <b>TXR40AB00-1612AI</b>			
<a href="#">423209-000</a>	NO		RAY423209-000	1193187-1, <b>TXR40AB00-0804AI</b>			
<a href="#">423509-000</a>	NO		RAY423509-000	2-1193189-8, <b>TXR40AB00-1608BI</b>			
<a href="#">447297-000</a>	NO		RAY447297-000	3-1193361-8, <b>TXR76AB00-1605AI</b>			
<a href="#">470290-000</a>	NO			3-1193524-1, <b>TXR41AB00-1206AI</b>			
<a href="#">478803-000</a>	NO		RAY478803-000	9-1193584-9, <b>TXR40AB00-1606AI</b>			
<a href="#">497361-000</a>	NO		RAY497361-000	7-1193718-5, <b>TXR40AB00-1208AI</b>			
<a href="#">562469-000</a>	NO		RAY562469-000	2-1194444-3, <b>TXR40AB00-2008AI</b>			
<a href="#">574595-000</a>	NO			6-1194560-8, <b>TXR40AB00-0808AI</b>			
<a href="#">581607-000</a>	NO		RAY581607-000	1194608-1,			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
				TXR40AB00-2418AI			
<a href="#">629267-000</a>	NO		RAY629267-000	2-1194981-0, TXR40AB00-1608AI			
<a href="#">658819-000</a>	NO		RAY658819-000	9-1195193-4, TXR40AB00-1006AI			
<a href="#">664529-000</a>	NO		RAY664529-000	5-1195236-1, TXR40AB00-1206AI			
<a href="#">738073-000</a>	NO		RAY738073-000	9-1195761-9, TXR40AB00-1605AI			
<a href="#">815689-000</a>	NO		RAY815689-000	8-1196356-4, TXR40AB00-2208AI			
<a href="#">820593-000</a>	NO		RAY820593-000	3-1196398-9, TXR40AB00-2012AI			
<a href="#">889283-000</a>	NO		RAY889283-000	5-1196918-3, TXR40AB00-1607AI			
<a href="#">921653-000</a>	NO		RAY921653-000	1197151-4, TXR40AB00-1006BI			
<a href="#">929031-000</a>	NO		RAY929031-000	1197203-9, TXR40AB00-1814AI			
<a href="#">942153-000</a>	NO			6-1197294-7, TXR40AC00-1607AI			
<a href="#">961557-000</a>	NO		RAY961557-000	1197439-8, TXR76AB00-1205AI			
<a href="#">963563-000</a>	NO		RAY963563-000	1197453-9, TXR54AB00-1406AI			
<a href="#">966286-000</a>	NO		RAY966286-000	1-1197472-0, TXR40AB00-2218AI			
<a href="#">C73862-000</a>	NO		RAYC73862-000	6-1200810-6, TXR40AU00-1006AI			
<a href="#">CH5545-000</a>	NO			7-1899671-3, TXR40AZ00-1610AI			
<a href="#">EB9460-000</a>	NO		RAYEB9460-000	TXR40AZ00-1206AI			
<a href="#">EB9465-000</a>	NO			TXR40AZ00-1410BI			