



11-Jul-2023

PCN #: PCN-23-175836

Subject : Package (Carton size) change

Description of Change : Dear Customer,

In order to improve customer experience, a unified optimization adjustment will be made to the labels and box specifications on the external packaging box

Mainly changes,

1. Replace some old packaging boxes with unified specification packaging boxes, slightly dimension changes

Before- 759598-000 - 1279*252*254

After- CR7224-000 - 1300*270*270

759598-000 CR7224-000

Before- 394718-000 - 1280*256*130

After- CR7225-000- 1300*260*140

394718-000 CR7225-000

Before- 406079-000- 605*308*308

After- CR7226-000- 600*310*310

406079-000 CR7226-000

2. Modification of label position, which are unified on sealing surface.

This PCN will be effective in Sep.10th.

For any questions or concerns please contact your local Customer Care Professional.

Reason :

Key Dates :

Contact By Date:10-Sep-2023

Implementation Date:10-Sep-2023

Product Affected	Alias Part Number	Substitute Part Number	AliasSub Part Number
CP4937-000	7-1899572-0, ES2000-NO.4-B7-0-STK-SH		
576105P004	7-1194570-9, ES1000-NO.2-B9-X-STK		
121397P020	4-1190883-0, ES2000-NO.3-B8-0-80MM		
5201946022	1194087-8, RT-3-NO.3-0-1IN		
C02580-000	2-1200296-7, FL2500-NO.1-I8-0-50MM		
829131P020	7-1196474-8, ES2000-NO.1-C1-0-75MM		
926845P007	9-1197187-2, FL2500-NO.3-J1-0-65MM		
CW3316-000	2-1899776-3, ES1000-NO.3-B8-X-48MM		
EK5495-000	2-1899839-4, ES2000-NO.3-P2-8L-45MM		
063725P022	6-1190481-1, ES2000-NO.2-B9-0-STK, ES2000-2-4FOOT		
CP4931-000	6-1899572-4, ES2000-NO.4-B7-0-40MM-SH		
537637P057	9-1194219-9, SCT-NO.3-E3-0-25MM		
636901P034	1195036-7, QS1500-NO.3-F7-0-40MM		
926845P008	9-1197187-3, FL2500-NO.3-J1-0-101MM		
CV4196-000	RNF-100-1/8-BK-STK-SH		
CP4904-000	3-1899572-8, ES2000-NO.1-C1-0-65MM-SH		

829131P019	7-1196474-7, ES2000-NO.1-C1- 0-27MM		
ER6884-000			
CP4908-000	4-1899572-2, ES2000-NO.2-B9- 0-20MM-SH		
CP4899-000	3-1899572-3, ES2000-NO.1-C1- 0-25MM-SH		
189022-000	5-1199705-1, ES1000-NO.1-C1- X-60MM		
121397P024	4-1190883-3, ES2000-NO.3-B8- 0-STK		
415877P006	5-1193134-9, FL2500-NO.1-I8- 0-27MM		
5070062068	1-1193963-3, RNF-100-1/4-CL- STK, RNF-100- 1/4-CL-STK		
CP4903-000	3-1899572-7, ES2000-NO.1-C1- 0-60MM-SH		
130599P011	6-1190948-8, ES2000-NO.4-B7- 0-50MM		
543633P088	7-1197940-1, SCT-NO.1-E6-0- 15MM		
607381P041	4-1194804-8, SCT-NO.2-E5-0- 65MM		
543957P003	1194267-7, SR- 1500-NO.2-N2-6- 50MM		
063725P079	1190482-8, ES2000-NO.2-B9- 0-45MM		
063725P080	1190482-9, ES2000-NO.2-B9- 0-33MM		
CS9984-000	9-1899641-5, ES2000-NO.3-O5- 0-35MM-CS9156		
537637P056	9-1194219-8, SCT-NO.3-E3-0- 40MM		

CH25696001	CRN-3/8-0-90MM, 6-1899585-9		
EP7676-000	RT-3-NO.1-0-30MM		
926845P006	9-1197187-1, FL2500-NO.3-J1-0-27MM		
CP4924-000	5-1899572-7, ES2000-NO.3-B8-0-50MM-SH		
5070082131	2-1193965-3, RNF-100-1/2-CL-STK		
ER6564-000			
5053132120	5-1193851-9, RNF-100-1/4-WH-STK		
520194K050	3-1194087-2, RT-3-NO.3-0-0.5IN		
607381P038	4-1194804-5, SCT-NO.2-E5-0-27MM		
063725P020	5-1190481-9, ES2000-NO.2-B9-0-15MM		
5054552026	5-1193900-3, RNF-100-1/2-GN-STK		
CY1947-000	ES1000-NO.4-B7-X-55MM, 3-1899736-1		
ER7649-000			
520206P036	9-1194088-8, RT-3-NO.1-0-1IN		
829131P014	7-1196474-3, ES2000-NO.1-C1-0-65MM		
520197P055	1194088-2, RT-3-NO.2-0-0.81IN		
ER7387-000			
A04704-000	9-1202115-0, FL2500-NO.3-J1-0-35MM		
130599P007	6-1190948-5, ES2000-NO.4-B7-0-60MM		

5053912035	3-1193891-5, RNF-100-3/16- GN-STK		
CP4909-000	4-1899572-3		
EM7228-000			
829131P081	3-1196475-0, ES2000-NO.1-C1- 0-100MM		
035377P006	5-1190273-0, ES1000-NO.3-B8- X-50MM		
CB0936-000	FL2500-NO.4-J2- 0-25MM		
607381P039	4-1194804-6, SCT-NO.2-E5-0- 50MM		
CP4918-000	5-1899572-1, ES2000-NO.2-B9- 0-STK-SH		
035377P004	4-1190273-8, ES1000-NO.3-B8- X-STK		
E94629-000	7-1200297-3, RT- 3-NO.1-0-1.5IN		
CP4911-000	4-1899572-5, ES2000-NO.2-B9- 0-40MM-SH		
5053202040	3-1193865-0, RNF-100-1/2-RD- STK		
CP4913-000	4-1899572-7, ES2000-NO.2-B9- 0-50MM-SH		
063725P018	5-1190481-8, ES2000-NO.2-B9- 0-30MM		
130599P023	7-1190948-5, ES2000-NO.4-B7- 0-65MM		
006977P005	1-1190054-2, FL2500-NO.0-I7- 0-101MM		
206247P031	2-1191495-0, SCT-NO.4-E2-0- 65MM		
350582-000	1198890-4, ES2000-NO.3-B8- 0-35MM		

3371890003	7-1192545-9, ES-CAP-NO.1-C1-0-35MM		
130599P012	6-1190948-9, ES2000-NO.4-B7-0-80MM		
CB5626-000	FL2500-NO.1-I8-0-25MM		
E20530-000	1200424-6, ES1000-NO.2-B9-X-40MM		
829131P079	2-1196475-9, ES2000-NO.1-C1-0-15MM		
CS9985-000	9-1899641-6, ES2000-NO.2-O6-0-35MM-CS9156		
829131P011	7-1196474-0, ES2000-NO.1-C1-0-30MM		
033101P003	7-1190256-0, RNF-100-3/4-3X-A1-BK-50MM		
774185P007	8-1196028-5, QS1500-NO.1-F5-0-25MM		
607381P046	5-1194804-3, SCT-NO.2-E5-0-STK		
CZ6027-000	FL2500-NO.3-J1-0-15MM		
193197P023	6-1191401-6, ES1000-NO.1-C1-X-35MM		
063725P034	7-1190481-1, ES2000-NO.2-B9-0-35MM		
CP4925-000	5-1899572-8, ES2000-NO.3-B8-0-60MM-SH		
206247P030	1-1191495-9, SCT-NO.4-E2-0-50MM		
CP4906-000	4-1899572-0, ES2000-NO.1-C1-0-95MM-SH		
CV4204-000	RNF-100-3/8-BK-STK-SH		
826309-000	7-1196454-4, ES2000-NO.1-C1-0-45MM		

206247P040	2-1191495-8, SCT-NO.4-E2-0- 40MM		
2525592005	4-1191848-8, RBK-ILS-125- NR1-0-STK		
CH03286001	RBK-ILS-125- NR1-0-40MM, 4- 1899479-1		
130599P010	6-1190948-7, ES2000-NO.4-B7- 0-40MM		
EM4493-000	SCT-NO.0-E6-0- 50MM		
CP4901-000	3-1899572-5, ES2000-NO.1-C1- 0-40MM-SH		
926845P009	9-1197187-4, FL2500-NO.3-J1- 0-132MM		
636901P003	7-1195035-5, QS1500-NO.3-F7- 0-50MM		
0021032009	9-1190015-4, RBK-ILS-125- NR3-0-STK		
193197P024	6-1191401-7, ES1000-NO.1-C1- X-40MM		
063725P035	7-1190481-2, ES2000-NO.2-B9- 0-70MM		
758741-000	7-1195911-7, FL2500-NO.0-I7- 0-30MM		
063725P030	6-1190481-7, ES2000-NO.2-B9- 0-80MM		
CP4915-000	4-1899572-9, ES2000-NO.2-B9- 0-65MM-SH		
576105P003	7-1194570-8, ES1000-NO.2-B9- X-65MM		
CB0937-000			
035377P016	6-1190273-0, ES1000-NO.3-B8- X-120MM		
415877P009	6-1193134-2, FL2500-NO.1-I8- 0-127MM		

958133P003	1197417-2, QS1500-NO.4-F8- 0-50MM		
CP4930-000	6-1899572-3, ES2000-NO.4-B7- 0-30MM-SH		
269647-000	1-1191990-6, ES- CAP-HW-NO.3- M8-0-45MM		
121397P072	7-1190883-9, ES2000-NO.3-B8- 0-100MM		
5054112017	2-1193894-0, RNF-100-3/16- OR-STK		
5202002017	2-1194088-2, RT- 3-NO.4-0-STK		
063725P017	5-1190481-7, ES2000-NO.2-B9- 0-40MM		
206247P033	2-1191495-2, SCT-NO.4-E2-0- 90MM		
537637P041	8-1194219-5, SCT-NO.3-E3-0- STK		
CB0938-000	FL2500-NO.3-J1- 0-80MM		
CP4797-000	SCT-NO.4-E2-0- 95MM		
CX1665-000	FL2500-NO.2-I9- 0-40MM		
063725P029	6-1190481-6, ES2000-NO.2-B9- 0-95MM		
543633P086	6-1194264-7, SCT-NO.1-E6-0- 30MM		
E43149-000	3-1199653-6, FL2500-NO.2-I9- 0-STK		
520197P044	9-1194087-6, RT- 3-NO.2-0-1.125IN		
5202066047	7-1194088-9, RT- 3-NO.1-0-1.25IN		
EP0788-000			
829131P024	8-1196474-1, ES2000-NO.1-C1- 0-90MM		

CP4910-000	4-1899572-4, ES2000-NO.2-B9- 0-30MM-SH		
ER6880-000			
CP4900-000	3-1899572-4, ES2000-NO.1-C1- 0-30MM-SH		
2949076003	3-1192234-2, CGPE-HW-12- A1-0-15MM		
771113P005	4-1196007-2, FL2500-NO.2-I9- 0-27MM		
581913P002	9-1194609-1, QS1500-NO.2-F6- 0-50MM		
CP4914-000	4-1899572-8, ES2000-NO.2-B9- 0-60MM-SH		
CX7480-000	ES1000-NO.2-B9- X-19MM, 5- 1899719-6		
5053232077	1193868-6, RNF- 100-1/2-WH-STK		
CB0934-000	FL2500-NO.4-J2- 0-55MM, 2- 1899832-2		
193197P008	5-1191401-1, ES1000-NO.1-C1- X-50MM		
121397P021	4-1190883-1, ES2000-NO.3-B8- 0-30MM		
C27689-000	2-1200812-2, FL2500-NO.3-C7- 0-50MM		
C27598-000	7-1201782-3, FL2500-NO.4-J2- 0-30MM		
006977P006	1-1190054-3, FL2500-NO.0-I7- 0-27MM		
415877P007	6-1193134-0, FL2500-NO.1-I8- 0-65MM		
537637P033	7-1194219-7, SCT-NO.3-E3-0- 50MM		
CR7066-000	ES1000-NO.3-B8- X-30MM, 7- 1899719-9		

CM6969-000	1-1899435-2, SR-1500-NO.3-N3-6-60MM		
EL7182-000	ES2000-NO.2-P3-8L-45MM		
0021036034	1200078-1, RBK-ILS-125-NR3-0-40MM		
829131P017	7-1196474-6, ES2000-NO.1-C1-0-60MM		
CX7481-000	ES1000-NO.2-B9-X-32MM, 5-1899719-4		
CR7067-000	ES1000-NO.3-B8-X-70MM		
CX7482-000	ES1000-NO.2-B9-X-21MM, 5-1899719-7		
A03204-000	7-1201888-9, FL2500-NO.4-J2-0-70MM		
CJ5292-000	FL2500-NO.0-I7-0-40MM, 4-1899833-8		
CP4905-000	3-1899572-9, ES2000-NO.1-C1-0-80MM-SH		
130599P009	6-1190948-6, ES2000-NO.4-B7-0-30MM		
774185P017	9-1196028-5, QS1500-NO.1-F5-0-30MM		
799617P008	2-1196182-2, FL2500-NO.4-J2-0-65MM		
ER7386-000			
CP4923-000	5-1899572-6, ES2000-NO.3-B8-0-40MM-SH		
063725P021	6-1190481-0, ES2000-NO.2-B9-0-27MM		
CC0543-000	FL2500-NO.3-J1-0-40MM		
926845P011	9-1197187-6, FL2500-NO.3-C2-0-65MM		

537637P035	7-1194219-9, SCT-NO.3-E3-0- 65MM		
543633P062	4-1194264-8, SCT-NO.1-E6-0- 25MM		
363884-000	1-1199654-7, FL2500-NO.3-J1- 0-STK		
CB0931-000	FL2500-NO.4-J2- 0-120MM		
0989076011	7-1190724-4, RBK-ILS-125- NR2-0-30MM		
CP4935-000	6-1899572-8, ES2000-NO.4-B7- 0-65MM-SH		
085193P003	9-1190628-5, ES1000-NO.4-B7- X-STK		
576105P009	8-1194570-4, ES1000-NO.2-B9- X-50MM		
0021036022	1-1190016-3, RBK-ILS-125- NR3-0-35MM		
0081930003	4-1190063-2, ES- CAP-NO.1-C1-X- 35MM		
829131P039	9-1196474-6, ES2000-NO.1-C1- 0-20MM		
636901P004	7-1195035-6, QS1500-NO.3-F7- 0-30MM		
063725P011	5-1190481-1, ES2000-NO.2-B9- 0-50MM		
EM72496001	ES1000-NO.3-B8- X-20MM		
799617P006	2-1196182-0, FL2500-NO.4-J2- 0-27MM		
774185P002	8-1196028-0, QS1500-NO.1-F5- 0-50MM		
130599P006	6-1190948-4, ES2000-NO.4-B7- 0-STK		

5053092267	2-1193845-2, RNF-100-1/4-BK- STK		
F34465-000	5-1200761-4, FL2500-NO.2-I9- 0-30MM		
C20744-000	5-1201707-8, ES1000-NO.2-B9- X-45MM		
CV4208-000	RNF-100-3/4-BK- STK-SH		
829131P012	7-1196474-1, ES2000-NO.1-C1- 0-50MM		
581913P006	9-1194609-5, QS1500-NO.2-F6- 0-30MM		
CZ7809-000	ES2000-NO.0-O9- 0-50MM, 1- 1899770-4		
543633P051	3-1194264-7, SCT-NO.1-E6-0- 50MM		
829131P037	9-1196474-4, ES2000-NO.1-C1- 0-80MM		
CP4932-000	6-1899572-5, ES2000-NO.4-B7- 0-45MM-SH		
193197P003	4-1191401-6, ES1000-NO.1-C1- X-65MM		
EM9058-000	V2-5.0-0-20MM		
CV4184-000	RNF-100-1/4-BK- STK-SH		
CZ9852-000	6-1899770-2, ES1000-NO.2-O6- X-25MM-CS9156		
829131P043	1196475-1, ES2000-NO.1-C1- 0-35MM		
0989076013	7-1190724-6, RBK-ILS-125- NR2-0-27MM		
063725P012	5-1190481-2, ES2000-NO.2-B9- 0-65MM		
E95757-000	4-1199653-3, FL2500-NO.4-J2- 0-STK		

799617P007	2-1196182-1, FL2500-NO.4-J2- 0-42MM		
EF8979-000	ES2000-NO.4-B7- 0-47MM		
829131P036	9-1196474-3, ES2000-NO.1-C1- 0-95MM		
CL8309-000	FL2500-NO.2-I9- 0-20MM		
2525596002	5-1191848-0, RBK-ILS-125- NR1-0-50MM		
543633P064	5-1194264-0, SCT-NO.1-E6-0- STK		
E46595-000	2-1201799-8, FL2500-NO.1-I8- 0-30MM		
2525596014	5-1191848-9, RBK-ILS-125- NR1-0-45MM		
063725P046	7-1190481-7, ES2000-NO.2-B9- 0-100MM		
F71884-000	ES2000-NO.3-B8- 0-60MM, 1- 1200298-8		
7501716003	3-1195850-2, RBK-ILS-125- NR4-0-75MM		
537637P042	8-1194219-6, SCT-NO.3-E3-0- 35MM		
206247P038	2-1191495-7, SCT-NO.4-E2-0- STK		
121397P014	3-1190883-4, ES2000-NO.3-B8- 0-65MM		
543633P081	6-1194264-2, SCT-NO.1-E6-0- 35MM		
121397P015	3-1190883-5, ES2000-NO.3-B8- 0-75MM		
CB0929-000	FL2500-NO.0-I7- 0-STK		
CP4920-000	5-1899572-3, ES2000-NO.3-B8- 0-25MM-SH		

NB32696001	FL2500-NO.4-J2-0-170MM		
130599P003	6-1190948-1, ES2000-NO.4-B7-0-75MM		
D58196-000	9-1202115-6, FL2500-NO.2-I9-0-50MM		
EP70166001	FL2500-NO.4-J2-0-110MM		
CR2209-000	9-1899572-1, ES2000-NO.3-B8-0-45MM-SH		
576105P008	8-1194570-3, ES1000-NO.2-B9-X-25MM		
ER6832-000			
0021036003	9-1190015-7, RBK-ILS-125-NR3-0-65MM		
4367790003	1-1193283-5, ES-CAP-NO.2-B9-0-35MM		
3371890005	8-1192545-0, ES-CAP-NO.1-C1-0-40MM		
520197P061	1194088-4, RT-3-NO.2-0-1.5IN		
193197P007	5-1191401-0, ES1000-NO.1-C1-X-20MM		
CP4922-000	5-1899572-5, ES2000-NO.3-B8-0-35MM-SH		
006977P007	1-1190054-4, FL2500-NO.0-I7-0-65MM		
2949076002	3-1192234-1, CGPE-HW-12-A1-0-10.3MM		
5053142385	2-1193853-6, RNF-100-3/8-BK-STK		
CP4902-000	3-1899572-6, ES2000-NO.1-C1-0-50MM-SH		
CP4912-000	4-1899572-6, ES2000-NO.2-B9-0-45MM-SH		

EL7516-000	SR-1500-NO.3- N3-6-53MM		
193197P004	4-1191401-7, ES1000-NO.1-C1- X-STK		
CB0939-000	FL2500-NO.1-I8- 0-43MM, 2- 1899832-3		
193197P011	5-1191401-4, ES1000-NO.1-C1- X-30MM		
5202062019	5-1194088-8, RT- 3-NO.1-0-STK		
829131P051	1196475-3, ES2000-NO.1-C1- 0-40MM		
640138-000	4-1197978-1, QS1500-NO.4-F8- 0-40MM		
415781P003	6-1193133-3, SR- 1500-NO.1-N1-6- 50MM		
CP4927-000	6-1899572-0, ES2000-NO.3-B8- 0-80MM-SH		
5201942018	9-1194086-7, RT- 3-NO.3-0-STK		
8208596007	RBK-ILS-125-3A- 0-40MM, 6- 1899332-2		
121397P043	5-1190883-3, ES2000-NO.3-B8- 0-40MM		
EP22052001			
829131P021	7-1196474-9, ES2000-NO.1-C1- 0-STK		
121397P018	3-1190883-8, ES2000-NO.3-B8- 0-50MM		
ER7388-000			
063725P025	6-1190481-3, ES2000-NO.2-B9- 0-20MM		
D28653-000	4-1201736-5, ES2000-NO.4-B7- 0-55MM		
5201972022	4-1194087-6, RT- 3-NO.2-0-STK		

0021036014	1190016-7, RBK-ILS-125-NR3-0-45MM		
5070072080	1-1193964-8, RNF-100-3/8-CL-STK, RNF-100-3/8-CL-STK		
1335390003	8-1190969-8, ESCAP-NO.3-B8-X-40MM		
EP37046001	FL2500-NO.4-J2-0-210MM		
774185P008	8-1196028-6, QS1500-NO.1-F5-0-40MM		
D20444-000	1-1199653-5, FL2500-NO.1-I8-0-STK		
904269N001	3-1197027-7, VERSAFIT-3/16-0-F1IN		
D28553-000	FL2500-NO.4-J2-0-60MM		
174707P001	5-1191270-6, RT-3-NO.3-0-1.5IN-T.062		
121397P067	7-1190883-5, ES2000-NO.3-B8-0-25MM		
EM8245-000	FL2500-NO.0-I7-0-50MM		
829131P026	8-1196474-3, ES2000-NO.1-C1-0-25MM		
CP4916-000	5-1899572-0, ES2000-NO.2-B9-0-80MM-SH		
5053192266	1-1193862-2, RNF-100-1/2-BK-STK		
CP4919-000	5-1899572-2, ES2000-NO.2-B9-0-STK-F-SH		
CW4121-000			
1939238-2	ES2000-NO.2-B9-0-STK-F		
CP4921-000	5-1899572-4, ES2000-NO.3-B8-0-30MM-SH		

CM5884-000	6-1899833-6, SCT-NO.2-E5-0- 45MM		
5201976026	5-1194087-5, RT- 3-NO.2-0-1IN		
121397P028	4-1190883-6, ES2000-NO.3-B8- 0-95MM		
774185P003	8-1196028-1, QS1500-NO.1-F5- 0-45MM		
130599P044	9-1190948-6, ES2000-NO.4-B7- 0-35MM		
520197P042	9-1194087-5, RT- 3-NO.2-0-2IN		
193197P010	5-1191401-3, ES1000-NO.1-C1- X-25MM		
0081930005	4-1190063-3, ES- CAP-NO.1-C1-X- 40MM		
636901P014	8-1195035-6, QS1500-NO.3-F7- 0-STK		
CP4907-000	4-1899572-1, ES2000-NO.1-C1- 0-STK-SH		
0021036031	2-1190016-2, RBK-ILS-125- NR3-0-30MM		
CP4933-000	6-1899572-6, ES2000-NO.4-B7- 0-50MM-SH		
543633P079	6-1194264-0, SCT-NO.1-E6-0- 40MM		
415877P008	6-1193134-1, FL2500-NO.1-I8- 0-101MM		
851565-000	6-1197815-1, ES2000-NO.4-B7- 0-45MM		
CR6142-000	ES2000-NO.1-C1- 0-70MM, 1899833-7		
206247P032	2-1191495-1, SCT-NO.4-E2-0- 75MM		

5053082106	8-1193843-5, RNF-100-3/16- WH-STK		
CX7479-000	ES1000-NO.1-C1- X-28MM, 5- 1899719-3		
607381P077	2-1198070-1, SCT-NO.2-E5-0- 35MM		
440452-000	7-1199181-4, RT- 3-NO.1-0-2.25IN		
CF3679-000	FL2500-NO.4-J2- 0-135MM		
130599P014	7-1190948-1, ES2000-NO.4-B7- 0-100MM		
771113P006	4-1196007-3, FL2500-NO.2-I9- 0-65MM		
063725P028	6-1190481-5, ES2000-NO.2-B9- 0-25MM		
A27820-000	1200833-7, FL2500-NO.3-J1- 0-50MM		
CP4926-000	5-1899572-9, ES2000-NO.3-B8- 0-65MM-SH		
771113P007	4-1196007-4, FL2500-NO.2-I9- 0-101MM		
063725P016	5-1190481-6, ES2000-NO.2-B9- 0-60MM		
A21213-000	5-1201860-8, FL2500-NO.4-J2- 0-40MM		
520206K014	9-1194088-1, RT- 3-NO.1-0-1IN		
CP4929-000	6-1899572-2, ES2000-NO.3-B8- 0-STK-F-SH		
CP4934-000	6-1899572-7, ES2000-NO.4-B7- 0-60MM-SH		
CX7430-000	ES1000-NO.1-C1- X-19MM, 5- 1899719-5		
5053182074	9-1193860-3, RNF-100-3/8-WH- STK		

CP4928-000	6-1899572-1, ES2000-NO.3-B8- 0-STK-SH		
CF2205-000	FL2500-NO.2-I9- 0-25MM		
5201976049	6-1194087-6, RT- 3-NO.2-0-1.25IN		
CP4898-000	3-1899572-2, ES2000-NO.1-C1- 0-20MM-SH		
537637P043	8-1194219-7, SCT-NO.3-E3-0- 30MM		
581913P020	1-1194610-0, QS1500-NO.2-F6- 0-STK		
607381P064	6-1194804-9, SCT-NO.2-E5-0- 30MM		
D54837-000	8-1200832-1, FL2500-NO.4-J2- 0-50MM		
CP4936-000	6-1899572-9, ES2000-NO.4-B7- 0-75MM-SH		

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.

Alert document created by IHS Markit based on content provided by TE Connectivity.