



17-Nov-2023

PCN #: PCN-23-192356

Subject : Part and Drawing revision level match

Description of Change : Dear valued customer,

In an effort to maintain same revision level of parts across entire documentation and to avoid conflicts between revision in shipping labels to drawings, we are aligning Product drawing revision & Central Part Registry revision level.

Also we use this opportunity to fix rounding and conversion errors (from inch to mm / mm to inch) to avoid mismatch between Product drawing and shipping labels. This change is for administrative purpose only and there is no change in Form, Fit and Functions of the product.

This change will be processed with PPAP level 1 / First Article Inspection (FAI). If you need PPAP document, then apply for e-PPAP.

Existing inventory to be consumed in First In First Out (FIFO) basis. (There is a cooling period of 180 days upto which part with old labels can be shipped)

We thank you for your business and look forward to servicing you through our standard part offerings in the future.

Reason : Update made to improve document clarity

Key Dates :

Contact By Date: 16-Jan-2024

Implementation Date: 16-Jan-2024

Product Affected	Alias Part Number	Substitute Part Number	AliasSub Part Number
E17371-000	4-1200881-3, SCL-3/4-2-60MM		
C34252-000	1200827-7, ES1000-NO.3-B8- X-55MM		
CB5289-000	SST-12-17/FR/97, 5-1899230-3		

5500192011	5-1194330-0, SCL-3/8-0-STK		
E23494-000	4-1200881-5, SCL-1/2-0-STK- CS5279		
CB5339-000			
576105P009	8-1194570-4, ES1000-NO.2-B9- X-50MM		
5500316056	2-1194333-4, SCL-1/2-0- 300MM		
5500286064	1-1194332-9, SCL-3/16-0- 50MM		
CB5335-000	SST-48- 07/FR/97/NM		
CB5274-000			
CB5411-000	SST-6-07/FR/97, 5-1899230-4		
A52804-000	2-1200965-3, ES1000-HW- NO.2-O3-X- 35MM		
5500102028	2-1194329-8, SCL-1/8-0-STK		
5500316070	3-1194333-4, SCL-1/2-A1-0- 80MM		
CB5425-000			
CB5416-000	2-1899309-2, SST- 6-13/97		
CB5369-000	SST-48- 15/FR/97/RED/N M		
576105P004	7-1194570-9, ES1000-NO.2-B9- X-STK		
CB5279-000	SST-12- 11/RED/226		
CF3733-000			
193197P011	5-1191401-4, ES1000-NO.1-C1- X-30MM		
CB5404-000			
576105P005	8-1194570-0, ES1000-NO.2-B9- X-75MM		

C57775-000	1-1201012-9, SCL-1-0-55MM		
193197P002	4-1191401-5, ES1000-NO.1-C1- X-55MM		
C20744-000	5-1201707-8, ES1000-NO.2-B9- X-45MM		
CB5297-000	SST-12-27/FR/97, 7-1899279-6		
035377P006	5-1190273-0, ES1000-NO.3-B8- X-50MM		
CB5331-000	SST-48- 07/226/NM		
5500282020	6-1194331-8, SCL-3/16-0-STK		
CB5418-000			
CB5305-000	SST-24-27/97		
CB5340-000	SST-48- 07/RED/226/NM		
364171-000	5-1192730-5, ES1000-NO.2-B9- X-100MM		
CB5377-000			
CF3967-000	SST-48-11/226- CS8747		
CB5275-000	SST-12- 07/RED/226		
CF3734-000			
CB5296-000	9-1899238-3, SST- 12-27/97		
CB5370-000			
CB5354-000			
CB5283-000	SST-12-13/97		
CB5394-000	SST-48-30/226		
CB5288-000	SST-12-17/97		
CB5398-000			
193197P024	6-1191401-7, ES1000-NO.1-C1- X-40MM		
5500106013	4-1194329-2, SCL-1/8-0-50MM		

C63832-000	1-1201146-9, ES1000-NO.2-B9- X-150MM		
CB5322-000			
CF3966-000	SST-48-17/226- CS8748		
A04375-000	2-1201147-4, ES1000-KIT3- REFILL		
2670914004	6-1191971-6, SCL-NO.33-0-SP		
CB5371-000	SST-48- 15/FR/97/NM		
193197P005	4-1191401-8, ES1000-NO.1-A1- X-STK		
CB5364-000	SST-48-13/FR/97		
CF8124-000			
CB5428-000	SST-9-20/226, 2- 1899833-9		
CB5387-000			
5501052008	1-1194339-0, SCL-3/4-0-STK, SCL-3/4-0-STK		
193197P010	5-1191401-3, ES1000-NO.1-C1- X-25MM		
193197P022	6-1191401-5, ES1000-NO.1-C1- X-45MM		
CB5270-000			
CB5408-000			
CB5316-000	SST-30-04/226		
085193P014	1190629-6, ES1000-NO.4-F3- X-50MM		
5501096085	9-1194340-5, SCL-1/4-A1-0- 70MM		
CB5417-000			
5501062005	7-1194339-5, SCL-1-0-STK		
CB5310-000	SST-30- 03/226/NM		
CB5385-000			

189022-000	5-1199705-1, ES1000-NO.1-C1- X-60MM		
576105P003	7-1194570-8, ES1000-NO.2-B9- X-65MM		
5501096084	9-1194340-4, SCL-1/4-A1-0- 40MM		
CB5401-000			
5501092019	3-1194340-1, SCL-1/4-0-STK		
CB5273-000			
CB5350-000	SST-48- 11/FR/97/NM		
CB5362-000			
193197P004	4-1191401-7, ES1000-NO.1-C1- X-STK		
550086P005	1-1194338-0, SCL-1/4-A1-2- 75MM		
CB5397-000	SST-48- 30/RED/226/NM		
035377P003	4-1190273-7, ES1000-NO.3-B8- X-75MM		
576105P006	8-1194570-1, ES1000-NO.2-A1- X-STK		
CB5347-000			
CB5372-000	SST-48-15/97		
CB5330-000			
CB5336-000			
035377P004	4-1190273-8, ES1000-NO.3-B8- X-STK		
193197P008	5-1191401-1, ES1000-NO.1-C1- X-50MM		
5501066043	1194340-6, SCL- 1-0-300MM		
CB5395-000			
576105P002	7-1194570-7, ES1000-NO.2-B9- X-55MM		

576105P008	8-1194570-3, ES1000-NO.2-B9- X-25MM		
451673-000	8-1193391-3, ES1000-NO.2-B9- X-60MM		
CB5368-000			
CB5334-000	3-1899241-6, SST- 48-07/FR/97		
CB5304-000	SST-24-17/226		
CB5309-000	SST-30-03/226		
291451-000	1-1197908-4, SCL-1/4-0-BULK- COIL		
CF5668-000			
CB5413-000			
CB5291-000	SST-12-20/97		
CB5349-000			
CB5420-000			
CB5272-000	SST-12-07/226, 3- 1899241-7		
CB5328-000			
CB5410-000			
085193P006	9-1190628-8, ES1000-NO.4-B7- X-50MM		
CB5363-000			
193197P021	6-1191401-4, ES1000-NO.1-C1- X-100MM		
5501056037	4-1194339-0, SCL-3/4-0-6IN		
CB5346-000			
609564-000	5-1201145-1, ES1000-NO.1-C1- X-150MM		
D72328-000	4-1201146-9, ES1000-NO.4-B7- X-150MM		
CB5278-000			
5500042003	5-1194328-8, SCL-3/8-2-STK		
5500316053	2-1194333-2, SCL-1/2-0-6IN		

035377P008	5-1190273-2, ES1000-NO.3-A1- X-STK		
193197P003	4-1191401-6, ES1000-NO.1-C1- X-65MM		
CB5324-000			
5500106080	9-1194329-2, SCL-1/8-0- 300MM		
085193P002	9-1190628-4, ES1000-NO.4-B7- X-75MM		
E20530-000	1200424-6, ES1000-NO.2-B9- X-40MM		
193197P007	5-1191401-0, ES1000-NO.1-C1- X-20MM		
CB5378-000	SST-48-17/FR/97		
CB5355-000			
085193P003	9-1190628-5, ES1000-NO.4-B7- X-STK		
CB5286-000			
5500312016	8-1194332-3, SCL-1/2-0-STK		
CB5407-000	6-1899253-7, SST- 6-04/FR/97		
CB5403-000	SST-6-03/FR/97, 3-1899222-4		
5501096059	7-1194340-4, SCL-1/4-0-25MM		
035377P016	6-1190273-0, ES1000-NO.3-B8- X-120MM		
CB5284-000			
CB5383-000			
CB5422-000	SST-9-07/226		
550085P023	1194338-4, SCL- 1/2-A1-2-95MM		
5500196073	1194331-2, SCL- 3/8-A1-0-75MM		
CB5301-000	SST-18-45/FR/97, 5-1899214-7		
CB5333-000			

C22995-000	9-1199704-5, ES1000-NO.3-B8- X-25MM		
CB5348-000	SST-48-11/97/NM		
CB5351-000			
5500196022	6-1194330-9, SCL-3/8-0- 300MM		
CB5423-000	SST-9-07/97		
CB5402-000			
5501056039	4-1194339-1, SCL-3/4-0- 300MM		
CB5400-000	SST-48- 40/RED/226/NM		
CB5393-000			
193197P023	6-1191401-6, ES1000-NO.1-C1- X-35MM		
CF3964-000			
5501096028	5-1194340-5, SCL-1/4-0- 300MM		
CB5290-000	SST-12-20/226		
5500286078	3-1194332-2, SCL-3/16-0- 300MM		
CB5406-000	SST-6-04/97, 6- 1899222-4		
709246-000	5-1201145-5, ES1000-NO.3-B8- X-150MM		
035377P002	4-1190273-6, ES1000-NO.3-B8- X-65MM		
CB5317-000	SST-30- 04/226/NM		
761263-000	1-1195929-3, SCL-3/16-0- BULK-COIL		
CB5295-000	SST-12-27/226		
CB5419-000			
CB5412-000			
CB5271-000	SST-12-04- RED/226		
CB5390-000			

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.

Alert document created by IHS Markit based on content provided by TE Connectivity.