



19-Aug-2013
PCN #:E-13-008 804

Subject:AMPLIMITE Hardware and Cable Clamp Kits

Description of Change: Replace zinc plated yellow chromate hardware with zinc plated clear chromate hardware.

Reason: Product Improvement. Good quality, RoHS compliant yellow chromate coated hardware is difficult to cost-effectively produce with consistent color from lot to lot. In some cases, part numbers are being superseded with clear chromate versions. In other cases such as cable clamps, hardware will be changed to clear chromate as a running change.

Impact of Change:form - fit – function

Key Dates:

Contact By Date:30-Sep-2013

Implementation Date:30-Sep-2013

Last Order Date: 30-Sep-2013

Last Ship/EOL Date:31-Dec-2013

Product Affected

5205817-4

5207719-3

5745136-3

5206478-1

205204-4

(Alias Part Numbers:

"0-0205204-4")

5205817-3

(Alias Part Numbers:

"673-1082-01")

5205818-3
5745018-1

Product Affected

1658641-2

1-5207908-0

(Alias Part Numbers:

"4-27033-0484")

574508 1-1

5749914-2

1-5207908-3

5749916-2

2075 16-5

(Alias Part Numbers:

"4-27033-1630")

5206478-4

5207872-3

5206472-1

5745563-3

(Alias Part Numbers:

"CA5423-000"

"AMP-0-5 745563-3")

5205821-2

5207952-3

5747971-3

5206478-3

(Alias Part Numbers:

"4-16211-7350")

5205820-3

5745583-1

(Alias Part Numbers:

"1362234")

5206478-5

5207719-4

205204-8

(Alias Part Numbers:

"2-42934-5716")

205206-8

749809-9

5207908-4

749813-8

205210-7

5749914-1

5206471-1

Product Affected

5750733-3

5207883-3

205203-3

(Alias Part Numbers:

"0-0205203-3"

"2-42934-5726")

205210-3

5207908-7

5745 563-4

5207953-3

(Alias Part Numbers:

"CA5425-000"

"AMP-0-5207953 -3")

1-5206478-2

5749626-2

205206-3

(Alias Part Numbers:

"5021905"

"27-01519-00"

"1186904")

1658641-1

5207908-1

(Alias Part Numbers:

"4-27202-1747")

5745584-1

5745082-1

205209-2

(Alias Part Numbers:

"010-1145-00"

"2-42934-5729")

5206478-2

5205821-3

5205980-5

5206514-4

1658640-1

5745 134-1

205205-2

(Alias Part Numbers:

"2-42934-5727"

"1186906")

Product Affected

5205980-4

5205208-1

(Alias Part Numbers:

"2-30124-1025")

5205207-1

(Alias Part Numbers:

"4-16211-7349")

207516-6

205210-8

205209-7

205206-9

205205-7

205204-9

(Alias Part Numbers:

"2-30124-1009")

205203-8

(Alias Part Numbers:

"2-30124-2009")

1658641-3

1658640-2

(Alias Part Numbers:

"1067998")

5748271-3

5748271-1

5748270-2

(Alias Part Numbers:

"1364315"

"1363997")

5747242-1

5745647-1

5745584-3

5745583-7

5745583-5

5745578-3

5745563-1

5745407-1

5745404-1

5745137-2

5745136-2

5745136-1

Product Affected

5207953-2

5207952-1

5207883-2

5207872-1

5207871-1

5207720-2

5207719-2

5207719-1

(Alias Part Numbers:

"2-42935-9042")

5206942-2

5206942-1

5206807-2

5206514-7

5206514-6

5206514-3

52065 14-1

5205980-3

5205980-1

(Alias Part Numbers:

"2-30351-0010"

"1185341")

5205979-1

5205820-2

5205818-2

5205817-2

(Alias Part Numbers:

"1364442")

5205817-1

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.