



10-May-2011

**PCN #:**P-11-003987

**Subject:**Bracket material changed to pre zincd ST2 (1.0226)

**Description of Change:** Alternatively to the currently used ST2 material with copper/nickel post plating, pre zincd ST2 will be used.

**Reason:** Improve capacity situation and availability of components due to the current constrains in the galvanic process. No negative effect to the performance of the relay and the bracket itself.

**Impact of Change:**form - fit - function

**Key Dates:**

**Contact By Date:**01-Jun-2011

**Implementation Date:**01-Jun-2011

**Product Affected**

2-1393298-1

(Alias Part Numbers:  
"V23136B 1X 36")

1-1393298-6

(Alias Part Numbers:

**Product Affected**

"V23136B 1X 6")

4-1393298-7

(Alias Part Numbers:

"V23136J1004X 47")

4-1393298-6

(Alias Part Numbers:

"V23136J1004X 30")

1-1393298-3

(Alias Part Numbers:

"V23136A1001X 46")

4-1393298-1

(Alias Part Numbers:

"V23136J 4X 43")

1-1414121-0

1-1414697-0

1-1414552-0

1-1414122-0

1-1414602-0

3-1393298-1

(Alias Part Numbers:

"V23136J 4X 13")

7-1414921-9

1-1414498-0

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

Tyco Electronic's corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the Tyco Electronics Product Information Center at 800-522-6752 or your Tyco Electronics Sales Representative.