



09-Jun-2011

PCN #:P-11-004059

Subject:AMPSEAL plug assembly

Description of Change: The 8 and 14 position plug assemblies are being moved to an automatic machine for seal presence inspection and date coding. The assemblies will be on the automatic process from 9 June 2011 through approximately 8 July 2011. The date code will be changed from a hot stamp to a laser etched, the location will change to the shroud and the size will increase. The larger date code will be the visual indicator that the assemblies are from the automatic machine. All assemblies produced for the first week will be placed on safe launch inspection.

Reason: The current semi-automatic inspection and date code machine for the 8 and 14 position AMPSEAL Plug assembly is in need of repair. This repair will take approximately 4 weeks

Impact of Change:form - fit - function

Key Dates:

Contact By Date:13-Jun-2011

Implementation Date:13-Jun-2011

Product Affected

Product Affected

776286-2

776273-5

776286-1

776273-4

776273-2

776273-1

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

Tyco Electronic's corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the Tyco Electronics Product Information Center at 800-522-6752 or your Tyco Electronics Sales Representative.