



21-Sep-2011
PCN #:E-11-018063

Subject:FASTON & FASTIN-ON Receptacles-250/312 Series/All Style

Description of Change: Plating designation and thickness change

Reason: New specification. In an effort to standardize manufacturing practices, TE Connectivity has completed a review of our current tin plating thickness standards on FASTON Receptacles. This review has resulted in our decision to reduce the tin plating thickness on selected part numbers from the current requirement to 40 micro inches minimum. Other than thickness, no change is being made to the tin plating specification. It is also important to note that TE Connectivity offers several other industry accepted product families that have plating thicknesses in the 20-40 microinch range.

Impact of Change:form - fit - function

Key Dates:
Contact By Date:30-Nov-2011
Implementation Date:30-Nov-2011

Product Affected
1742291-1
60878-2

Product Affected

41774

42663-2

63467-1

42437-5

41194

42015

157480-2

42281-2

(Alias Part Numbers:

"0-0042281-2")

60290-2

63647-2

62418-2

42660-2

60249-2

42741-2

62090-1

63011-2

63677-1

63648-2

41898

(Alias Part Numbers:

"402534572")

63137-1

42100-2

63813-1

1742718-1

61188-1

62718-2

42743-2

62814-2

60413-1

62274-1

41729-2

63009-2

63651-1

42640-2

(Alias Part Numbers:

"402634513")

61202-2

Product Affected

63314-2

41802

42580-2

62891-1

61810-2

60274-2

1217148-1

63412-1

63012-2

60253-2

62056-4

63306-2

63365-2

60851-3

60384-2

42460-2

(Alias Part Numbers:

"0-0042460-2")

63539-1

63537-2

41274

62021-3

61399-1

60764-2

41728

(Alias Part Numbers:

"403034655"

"1300441")

61375-1

(Alias Part Numbers:

"402075402")

42511-2

42692-2

41450

(Alias Part Numbers:

"401808662")

41772

63993-1

63901-1

63010-2

Product Affected

63647-3

62811-2

60650-2

640416-2

60838-1

(Alias Part Numbers:

"962404-000"

"AMPS-0-0060838-1")

60851-1

(Alias Part Numbers:

"403385826")

63563-1

62253-2

61316-1

62057-5

60294-2

61944-2

(Alias Part Numbers:

"403546252")

60635-1

42400-2

42565-2

62057-3

60938-2

42563-8

60419-2

42437-2

41832

42563-2

1742754-1

61765-2

(Alias Part Numbers:

"367150-000"

"402387898"

"AMPS-0-0061765-2")

61368-1

62428-3

(Alias Part Numbers:

"406919118")

60279-2

Product Affected

60295-2

(Alias Part Numbers:

"0-0060295-2")

62056-7

61988-2

(Alias Part Numbers:

"403248123")

156503-2

62057-4

41800

60960-3

62056-6

63445-2

42025-1

60736-2

41729

62109-2

62049-2

42845-2

63315-2

62056-3

63445-4

62500-2

62223-2

63609-2

63314-4

42742-2

62813-2

63800-1

42021

63555-2

62022-2

60701-1

1217344-1

62553-3

60385-2

62057-8

61988-3

62998-2

41532

Product Affected

63541-1

62428-2

(Alias Part Numbers:

"528770-000"

"AMPS-0-0062428-2")

62866-1

62048-2

63655-1

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

Tyco Electronic's corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the Tyco Electronics Product Information Center at 800-522-6752 or your Tyco Electronics Sales Representative.