



06-Mar-2012

PCN #:E-12-003673

Subject:MTA-156 tin plate headers

Description of Change: Reduce pin length .100" on the connector side of header.

Reason: Product improvement. The pin tip is now aligned with the top of the housing, which will help to prevent reverse mating of connector and header.

Impact of Change:form - fit - function

Key Dates:

Contact By Date:28-May-2012

Implementation Date:28-May-2012

Product Affected

640384-4

1-640388-8

1-641938-1

644776-1

643960-1

1-640384-4

640388-5

1-640388-0

644999-1

644753-5

1-640384-6

644753-3

644750-3

1-644750-0

640388-3

Product Affected

1-640388-7
641938-6
640388-4
644753-9
1-640388-2
640388-7
640384-6
641938-9
641112-6
1-644753-5
644753-6
1-640388-6
1-640388-3
1-644753-0
1-640388-1
640384-3
640388-6
640384-7
2-644750-2
644739-1
641992-3
1-640384-2
640384-5
1-640388-4
1-640388-5
640384-2
1-644753-2
640388-8
644873-2
640388-9
1-640384-0
640384-8
644753-4
644753-8
1-644753-6
641112-4
644205-2
640388-2
644753-7

(Alias Part Numbers:

Product Affected

"1300907")

644000-1

1-640384-5

644753-2

2-640388-4

641112-5

644741-2

640384-9

641112-7

2-640388-0

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

Tyco Electronic's corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the Tyco Electronics Product Information Center at 800-522-6752 or your Tyco Electronics Sales Representative.