



31-Jul-2013

**PCN #:**P-13-009367

**Subject:**Pressure Sensor Implementation

**Description of Change:** Pressure sensors will be implemented at the plastic injection department, for the covers of the relay.

**Reason:** Product improvement. The aim of this improvement, is to avoid possible short shots that may occur during the mould injection, by controlling the plastic material pressure inside the mould, for each cover.

**Impact of Change:**form - fit - function

**Key Dates:**

**Contact By Date:**16-Sep-2013

**Implementation Date:**16-Sep-2013

**Product Affected**

6-1419137-0

(Alias Part Numbers:  
"V23074A1101X 51")

1-1414358-0

3-1414997-0

1-1414731-0

2-1393292-6

(Alias Part Numbers:  
"V23074A1001X 42")

2-1393292-7

(Alias Part Numbers:  
"V23074A1001X 42\*B")

3-1414977-4

1432592-1

## **Product Affected**

(Alias Part Numbers:  
"VFMA-15F41-Z26")

3-1414977-5

9-1393292-1

(Alias Part Numbers:  
"V23074A1301X 31")

2-1393292-0

(Alias Part Numbers:  
"V23074A1001X 10")

6-1393292-7

(Alias Part Numbers:  
"V23074A4001X 55")

1-1414742-0

4-1414979-7

8-1393292-4

(Alias Part Numbers:  
"V23074A1001A403")

3-1393292-3

(Alias Part Numbers:  
"V23074A1001X 52")

1-1414658-0

5-1414922-5

1-1414743-0

1-1414634-0

2-1414982-8

5-1393292-2

(Alias Part Numbers:  
"V23074A1301X 43\*B")

1-1904057-8

(Alias Part Numbers:  
"V23074-A1801-X106")

1-1414714-0

1393292-1

(Alias Part Numbers:  
"V23074A1001A302")

2-1414971-4

1-1414638-0

3-1393292-8

(Alias Part Numbers:  
"V23074A1002A403")

## **Product Affected**

6-1419137-1

(Alias Part Numbers:  
"V23074A1401X 53")

3-1414941-4

1-1415005-6

8-1393292-9

(Alias Part Numbers:  
"V23074A1002A402")

8-1414994-0

6-1414926-2

3-1414970-4

5-1393292-1

(Alias Part Numbers:  
"V23074A1301X 43")

8-1414780-8

6-1393292-2

(Alias Part Numbers:  
"V23074A2002A402")

4-1393292-7

(Alias Part Numbers:  
"V23074A1301X 22")

1-1904059-8

(Alias Part Numbers:  
"V23074-A2601-X108")

1-1393292-8

(Alias Part Numbers:  
"V23074A1001X 9")

6-1419137-2

(Alias Part Numbers:  
"V23074A1501X 38")

1-1414355-0

5-1414998-7

7-1414994-7

6-1393292-3

(Alias Part Numbers:  
"V23074A2002A403")

1432591-1

(Alias Part Numbers:  
"VFMA-11F41-Z19")

1-1414738-0

## **Product Affected**

1-1414058-0

5-1415011-2

(Alias Part Numbers:

"V23074-A2302-X096")

6-1414950-1

1-1414970-3

5-1414987-2

(Alias Part Numbers:

"V23074-A1001-X095")

7-1414994-9

6-1419137-5

(Alias Part Numbers:

"V23074B1701X 20")

2-1414967-9

1-1414580-0

1-1414972-4

1-1904057-9

(Alias Part Numbers:

"V23074-A1001-X107")

2-1393292-9

(Alias Part Numbers:

"V23074A1001X 47")

5-1419137-8

(Alias Part Numbers:

"V23074A1002X 44")

5-1419137-9

(Alias Part Numbers:

"V23074A1003X 8")

1-1414735-0

5-1393292-8

(Alias Part Numbers:

"V23074A2001A402")

6-1414772-6

7-1414994-8

7-1414995-0

6-1419137-4

(Alias Part Numbers:

"V23074A2001A403")

1393292-2

(Alias Part Numbers:

**Product Affected**

"V23074A1001A303")

1-1414165-0

7-1414983-4

1-1414715-0

1-1414625-0

1-1414183-0

6-1393292-4

(Alias Part Numbers:

"V23074A4001X 40")

1393292-5

(Alias Part Numbers:

"V23074A1001A402")

1-1414630-0

8-1414998-4

6-1414926-3

1-1414734-0

1-1414781-0

7-1415010-5

(Alias Part Numbers:

"V23074-A1002-X097")

1-1414717-0

1-1414306-0

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.