

TE CONNECTIVITY

PRODUCT CHANGE NOTIFICATION

CUSTOMER: Avnet Inc.
LOCATION: WORLDWIDE
CUSTOMER NO: 0000102000

**PRODUCT CHANGE NOTIFICATION
NO:** P-13-009596
PCN DATE: 18-OCT-13

We would like to inform you about the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

GENERAL PRODUCT DESCRIPTION:

MTC Connectors, Crimp Inserts, Shells, etc.

DESCRIPTION OF CHANGE:

Manufacturing location change. Following Part Numbers will be transferred from our TE Plant in Tijuana, Mexico to our TE Plant in Hermosillo, Mexico. TE Connectivity is optimizing the product lines by consolidating similar manufacturing processes in a single factory to achieve synergy in capacity and supply chain management. There is no change in raw material or raw material suppliers. All products will comply with current TE Customer Drawings and meet current performance requirements. There is no effect on fit, form or function as a result of this change.

REASON FOR CHANGE:

Dear Customer, as a result of our continuous strive for improving our processes, we hereby inform you about a transfer of tools and/or processes. The transfer is executed by following a strict transfer procedure, which guarantees no negative influence on quality, ability to supply and form-fit-function of the concerned products. The new manufacturing location is under a certified quality management system according the standard industry requirements. An internal release based on our specifications will be executed before any parts will be delivered, which guarantees the performance. Existing MTC assembly process at Tijuana, Mexico manufacturing process will be consolidated into a new manufacturing facility in Hermosillo, Mexico. The transition period begins in March 2014 and will be completed over the following few months. During this time TJ will continuing production while HMO starts up in parallel.

ESTIMATE DATE:**LAST ORDER DATE:**

(OBSOLETE PARTS ONLY)

LAST SHIP DATE:

(OBSOLETE PARTS ONLY)

FIRST DATE TO SHIP CHANGED**PARTS:** 01-JUN-2014

(CHANGED PARTS ONLY)

LAST DATE FOR MIXED**SHIPMENTS:** 15-SEP-2014

(CHANGED PARTS ONLY)

H	RCI	MTCP-116-05S1CS2797
H	RCI	CTA-0093
H	RCI	ECS-0004
H	RCI	CHA-0033
H	RCI	MTCR-303-04P
H	RCI	CHA-0268
H	RCI	CHA-0017-003
H	RCI	MTCPK1RJC02S
H	RCI	MTCR-KT1-0004
H	RCI	MTC100Q-SH1-R22
H	RCI	CTA-0099
H	RCI	CTA-0025CS072
H	RCI	MTCR-363-04S
H	RCI	CHA-0091
H	RCI	MTCR-333-04S
H	RCI	CTA-0094
H	RCI	MTCP-122-20P1-001
H	RCI	MTCP-122-20P1-001CS2820
H	RCI	CTA-1160
H	RCI	ECS-0002
H	RCI	MTCP-122-20P-022
H	RCI	MTCP-122-20P-001
H	RCI	MTCP-122-20P-001CS2820
H	RCI	CHA-0047-003
H	RCI	CHA-0071-003
H	RCI	MTCPQKT1P2PFDC
H	RCI	MTCPK1RJC02P
H	RCI	CTA-0115
H	RCI	MTCP-122-20P1-023CS2736
H	RCI	MTCP-KT2-0015
H	RCI	MTCP-116-05S1CS2820
H	RCI	MTCR-103-04S

H	RCI	ECS-0001
H	RCI	MTCPQKT1R2SGBC
H	RCI	MTCP-122-20PQ1
H	RCI	MTCP-116-05P2CS2820
H	RCI	MTCR-103-04P-001CS013
H	RCI	MTCPK1PJC02P
H	RCI	CHA-0018-103C2726
H	RCI	ECS-0003
H	RCI	CTA-0166
H	RCI	CHA-0018-003CS2566
H	RCI	CTA-0027CS072
H	RCI	MTCPK2PJC22SS
H	RCI	MTC100-YC1-006
H	RCI	MTCP-122-20S2CS2886
H	RCI	MTCP-122-20S1-CS2886
H	RCI	CHA-0270
H	RCI	CHA-0295
H	RCI	CHA-0018-003
H	RCI	CTA-0215CS1593
H	RCI	MTCP-122-20S1-022
H	RCI	CHA-0297
H	RCI	MTCPK2RJC22SS
H	RCI	CTA-0065
H	RCI	CTA-0068
H	RCI	CHA-0051-003
H	RCI	ECS-0005
H	RCI	MTCP-122-20S-023
H	RCI	MTCR-163-04S
H	RCI	MTC100-YC1-001
H	RCI	CHA-0299
H	RCI	MTCP-122-20S1-023
H	RCI	MTCP-KT1-0010
H	RCI	CHA-0092
H	RCI	CHA-0267
H	RCI	CHA-0016-003CS2566
H	RCI	CTA-0165
H	RCI	ECA-0183
H	RCI	MTCP-KT2-0016
H	RCI	MTCPQKT1R2PFAD
H	RCI	MTCP-122-20P-023
H	RCI	MTCC1R-COAX-01S-01

H	RCI	MTCC1R-COAX-01S-01CS013
H	RCI	ECA-0133
H	RCI	CHA-0047F-003
H	RCI	MTC100Q-SH1-P22
H	RCI	CHA-0298
H	RCI	MTC100Q-SH2-P22
H	RCI	CTA-1031
H	RCI	MTCC1R-COAX-01P-01
H	RCI	MTCC1R-COAX-01P-01CS013
H	RCI	MTCPK2RJC66SS
H	RCI	MTCPQKT2P26PFBA
H	RCI	MTCP-122-20P1-023
H	RCI	ECA-0217
H	RCI	MTCR-101-04S-002
H	RCI	MTCP-122-20P2-023
H	RCI	CHA-0093
H	RCI	MTCPK1PJC02S
H	RCI	MTCP-122-20PQ2
H	RCI	MTCP-122-20S2-023CS2736
H	RCI	CHA-0251
H	RCI	MTCP-KT1-0009
H	RCI	MTCP-122-20S1-023CS2736
H	RCI	CHA-0098
H	RCI	MTC100-YC1-004
H	RCI	MTCR-163-04P
H	RCI	CHA-0016-003
H	RCI	CTA-0050
H	RCI	CTA-0051
H	RCI	MTCPK2PJC22PP
H	RCI	MTCR-161-04P-002
H	RCI	MTCR-161-04P-002CS164
H	RCI	CHA-0028-003
H	RCI	CTA-0067
H	RCI	MTCP-116-05S2CS2820
H	RCI	CHA-0231
H	RCI	CTA-0034
H	RCI	D-659-0026
H	RCI	D-659-0026CS121
H	RCI	D-659-0039
H	RCI	D-659-0039CS121
H	RCI	CHA-0016

H	RCI	CTA-0050-01
H	RCI	MTCR-101-04P-001
H	RCI	MTCR-161-04S
H	RCI	MTCR-101-04P
H	RCI	MTCR-161-04P
H	RCI	MTCR-101-04S
H	RCI	CTA-0035
H	RCI	CTA-0036
H	RCI	CTA-0036CS2806
H	RCI	CTA-0028
H	RCI	CTA-0029
H	RCI	MTCB1R-COAX01P-01
H	RCI	D-659-0021-SHLD-TERM-KT-1
H	RCI	D-659-0044
H	RCI	D-659-0045
H	RCI	D-659-0047
H	RCI	D-659-0059
H	RCI	D-659-0060
H	RCI	D-659-0061
H	RCI	CTA-0022
H	RCI	CTA-0023
H	RCI	CTA-0024
H	RCI	CTA-0025
H	RCI	CTA-0026
H	RCI	CTA-0027
H	RCI	CTA-0028-003
H	RCI	MTCR-333-04S-028
H	RCI	CHA-0269
H	RCI	MTC100-YC1-003
H	RCI	CHA-0045
H	RCI	D-659-0062
H	RCI	CHA-0296
H	RCI	MTCPQKT2P22PGCB
H	RCI	MTC100-YC1-002
H	RCI	MTCR-103-04P
H	RCI	CHA-0049
H	RCI	CHA-0014-003
H	RCI	MTCPQKT1P2SFCA
H	RCI	CTA-0078
H	RCI	MTCR-103-04P-001
H	RCI	MTC100Q-SH2-R22

H	RCI	MTCP-116-05P1CS2820
H	RCI	MTCC1P-COAX-01S-01
H	RCI	MTCC1P-COAX-01S-01CS013
H	RCI	CHA-0046
H	RCI	CTA-0051CS119
H	RCI	CTA-0079
H	RCI	MTCP-122-20PQ
H	RCI	D-651-0004P
H	RCI	D-651-0004PCS2820
H	RCI	MTCP-122-20S2-022
H	RCI	MTCPQKT2P22PGDC
H	RCI	D-659-0087
H	RCI	D-659-0087CS043
H	RCI	CHA-0047
H	RCI	MTCR-KT1-0011
H	RCI	MTCP-122-20P2-023CS2736
H	RCI	MTC100-YC1-005
H	RCI	MTCPK2PJC66PP
H	RCI	CHA-0018-203
H	RCI	CHA-0018-203CS2726
H	RCI	MTCP-116-05P1CS2797
H	RCI	D-659-0086
H	RCI	D-659-0086CS043
H	RCI	CTA-0225
H	RCI	MTCPK2RJC22PP
H	RCI	D-651-0004S
H	RCI	D-651-0004SCS2820
H	RCI	D-659-0034-01-003
H	RCI	D-659-0034-01-003CS2819
H	RCI	MTCC1P-COAX-01P-01
H	RCI	MTCC1P-COAX-01P-01CS013
H	RCI	CHA-0017-003CS2566
H	RCI	CTA-0166-CS2824
H	RCI	MTCR-103-04S-001
H	RCI	MTCPQKT2P22SFAB
H	RCI	MTCPQKT2P26SFBD
H	RCI	CHA-0305
H	RCI	MTCPQKT1R2SFCD
H	RCI	MTCPQKT2R22SFBD
H	RCI	MTCPQKT2P22SFCA
H	RCI	MTCPQKT1P2SGCD

H	RCI	MTCPQKT2P22PGBD
H	RCI	MTCPQKT1R2PGAD
H	RCI	MTCPQKT1R2PFAC
H	RCI	MTCPQKT2P22SFBA
H	RCI	MTCPQKT1P2PFDB
H	RCI	MTCPQKT1P2PGCC
H	RCI	MTCP-116-05P2CS2797
H	RCI	MTCPQKT2P26SGCC
H	RCI	MTCP-122-20P2-001
H	RCI	MTCP-122-20P2-001CS2820
H	RCI	MTCPQKT2P26PFAD
H	RCI	MTCPQKT2R22SGAA
H	RCI	MTCPQKT1P2PFDA
H	RCI	MTCPQKT1R2SFCB
H	RCI	MTCPQKT1P2PGAA
H	RCI	MTCPQKT2P22PGAD
H	RCI	MTCPQKT1P2SGAD
H	RCI	MTCPQKT1P2SFDB
H	RCI	MTCPQKT1P2SGDC
H	RCI	MTCPQKT2P26SGBD
H	RCI	MTCPQKT2P26PFBC
H	RCI	MTCPQKT2P22PGCC
H	RCI	MTCPQKT2P22SGBA
H	RCI	MTCPQKT2P26PFAC
H	RCI	MTCPQKT2R22PGDD
H	RCI	CHA-0310
H	RCI	MTCPQKT1R2SGBA
H	RCI	MTCP-116-05S2CS2797
H	RCI	MTCPQKT1P2PFCD
H	RCI	MTCPQKT2P26SGAD
H	RCI	MTCPQKT1P2PFAA
H	RCI	MTCPQKT1P2SGAC
H	RCI	MTCPQKT1P2SGDA
H	RCI	MTCPQKT2P26PGAC
H	RCI	MTCPQKT2P22PGDA
H	RCI	MTCPQKT2P26PGAD
H	RCI	MTCPQKT1P2SGBC
H	RCI	MTCPQKT2P22PFAA
H	RCI	MTCPQKT2P22SGCD
H	RCI	MTCPQKT1P2PGAC
H	RCI	MTCPQKT2P22SGAD

H	RCI	MTCPQKT2P26SGBB
H	RCI	MTCPQKT1R2SGAA
H	RCI	MTCPQKT1R2PGAA
H	RCI	MTCPQKT2P26SGAB
H	RCI	MTCPQKT2R26SFCA
H	RCI	MTCPQKT1R2PFBA
H	RCI	MTCPQKT2P26SFDA
H	RCI	MTCPQKT2P22SFAA
H	RCI	MTCP-122-20S2-001
H	RCI	MTCP-122-20S2-001CS2820
H	RCI	MTCPQKT1P2PFBA
H	RCI	MTCPQKT1P2PGCD
H	RCI	MTCPQKT2R22PGCB
H	RCI	CHA-0307
H	RCI	MTCPQKT2P26SGAC
H	RCI	MTCPQKT1P2SFAA
H	RCI	MTCPQKT2P22SGAA
H	RCI	MTCPQKT2P26PFCB
H	RCI	MTCPQKT1P2SGDD
H	RCI	MTCPQKT2P22SGAB
H	RCI	MTCPQKT2P26PGCD
H	RCI	MTCPQKT2P22SGBC
H	RCI	MTCPQKT1P2SGAA
H	RCI	MTCPQKT2P22PGAA
H	RCI	MTCPQKT2P26SGDC
H	RCI	MTCPQKT2P22SGCB
H	RCI	MTCPQKT2P26SGCA
H	RCI	MTCPQKT2P22PFAD
H	RCI	MTCPQKT1R2PFAA
H	RCI	MTC100Q-SH2-F22
H	RCI	MTCPQKT1P2SGXX
H	RCI	MTCPQKT1R2SFDD
H	RCI	MTCPQKT2P26SFAC
H	RCI	MTCPQKT2R22SGDB
H	RCI	MTCPQKT1P2PFAC
H	RCI	MTCPQKT2R26PFBB
H	RCI	MTCPQKT2R26SFBB
H	RCI	MTCPQKT2P22SFAC
H	RCI	MTCPQKT1P2PGCB
H	RCI	MTCPQKT2P26PGBB
H	RCI	MTCPQKT1P2PFBB

H	RCI	MTCPQKT2P22PGDB
H	RCI	MTCPQKT1P2PGBD
H	RCI	MTCPQKT1P2SFDD
H	RCI	MTCPQKT1P2SFDC
H	RCI	MTCPQKT2P26PFAA
H	RCI	MTCPQKT1P2PGDC
H	RCI	MTCPQKT1P2PGBC
H	RCI	MTCPQKT2P26SFAA
H	RCI	MTCPQKT2P22SGCA
H	RCI	MTCPQKT2P22PGAC
H	RCI	MTCPQKT2P26SFCA
H	RCI	MTCPQKT1P2SGAB
H	RCI	MTCPQKT1R2SGBD
H	RCI	MTCPQKT1P2PGCA
H	RCI	MTCPQKT1P2PGAD
H	RCI	MTCPQKT1R2SFBB
H	RCI	MTCPQKT2P26SGDB
H	RCI	D-659-0034-04
H	RCI	MTCPQKT2R2SGBD
H	RCI	MTCPQKT2P26PFBD
H	RCI	MTCPQKT2P22SGDB
H	RCI	MTCPQKT2P22SFDD
H	RCI	MTCPQKT2P22PGBB
H	RCI	MTCPQKT2P22PGAB
H	RCI	MTCR-163-04P-001
H	RCI	MTCPQKT1R2SGAB
H	RCI	MTCPQKT1P2SGBD
H	RCI	MTCPQKT2R22PGBB
H	RCI	MTCPQKT1P2PGBB
H	RCI	MTCPQKT1P2SGCB
H	RCI	CTA-0165-CS2823
H	RCI	MTCPQKT2P26SFAB
H	RCI	MTCPQKT2P26SGAA
H	RCI	MTCPQKT2P26PGBA
H	RCI	MTCPQKT2R22PGBC
H	RCI	MTCPQKT2P22SGBB
H	RCI	MTCPQKT1P2SFAC
H	RCI	MTCPQKT2P26SFDB
H	RCI	MTCPQKT2P22PGBA
H	RCI	MTCPQKT1P2SFDA
H	RCI	MTCPQKT1R2SFAB

H	RCI	MTCPQKT1R2SGAC
H	RCI	MTCPQKT1P2PFDD
H	RCI	MTCPQKT1P2PGAB
H	RCI	MTCPQKT2P26PFBB
H	RCI	MTCPQKT2R22PGDA
H	RCI	MTCPQKT2R26PFAB
H	RCI	MTCPQKT1P2SGBB
H	RCI	MTCPQKT1P2PFCC
H	RCI	MTCPQKT2P26SGCD
H	RCI	MTCPQKT1P2SGBA
H	RCI	CHA-0313
H	RCI	MTCP-122-20S1-001
H	RCI	MTCP-122-20S1-001CS2820
H	RCI	MTCPQKT2P22SGDC
H	RCI	MTCPQKT2P22PGCA
H	RCI	MTCPQKT2P22SGBD
H	RCI	MTCPQKT2P22SFAD
H	RCI	D-659-0034-04CS2820
H	RCI	MTCPQKT2P26PGBD
H	RCI	MTCPQKT2P22SGAC
H	RCI	MTCPQKT2P22SGCC
H	RCI	MTCP-122-20S-001
H	RCI	MTCP-122-20S-001CS2820
H	RCI	MTCPQKT2P26SFAD
H	RCI	CHA-0306
H	RCI	MTCPQKT1P2PFCB
H	RCI	MTCPQKT1P2SGCC
H	RCI	MTCPQKT2P22SFCB
H	RCI	MTCPQKT1P2SFAD
H	RCI	MTCPQKT2R22PGAB
H	RCI	MTCPQKT1P2PGDB
H	RCI	MTCPQKT2P22PGDD
H	RCI	MTCPQKT2P22PGCD
H	RCI	MTCPQKT2R22SGCC
H	RCI	MTCPQKT1R2PGCA
H	RCI	MTCPQKT2P26PGAA
H	RCI	MTCPQKT1R2SFCA
H	RCI	MTCPQKT1P2SGCA
H	RCI	MTCPQKT1P2PFBC
H	RCI	D-659-0033-01-003
H	RCI	D-659-0033-01-003CS2825

H	RCI	MTCPQKT1P2PFAB
H	RCI	MTCPQKT2R22SGBA
H	RCI	MTCPQKT2P26PFCA
H	RCI	MTCPQKT1P2SGDB
H	RCI	MTCPQKT1P2PGBA
H	RCI	MTCPQKT2P22PFCD
H	RCI	CHA-0092-30
H	RCI	MTCPQKT2P22SGDA
H	RCI	MTCPQKT1P2PFCA
H	RCI	MTCPQKT1P2SFBB
H	RCI	MTCPQKT2P22SGDD
H	RCI	MTCPQKT2P22PFAB
H	RCI	MTCPQKT2R22SGAC
H	RCI	MTCPQKT2R22PGAD
H	RCI	CHA-0308
H	RCI	MTCPQKT1R2SFCC