

28-Jan-2014 **PCN #:**P-14-009879

Subject: Generation Y Terminal Contacts, 0.64mm

Description of Change: After multiple customer requests and in an effort to provide a better overall customer experience, TE Connectivity (TE) would like to inform you of a packaging change to the Generation Y 0.64mm Contact family. Today these terminals are packaged on reels and when there is a need for a splice, there is the use of an overlapping wire tie splice. TE has been made aware by our customers, that this method of splicing is difficult to detect and can have adverse effects to your processes. Therefore TE will be changing to a loose end splice method with the loose ends being contained within overlapping reel paper. This change is being made on any Generation Y product in which the splice is currently the wire tie method. There is no change to the actual Generation Y terminal products, just the method for splicing together strips on a reel

Reason: Customer <u>Request.If</u> a new PPAP is required, please contact your local TE Representative and a PPAP, consisting of a PSW Cover Sheet only, will be submitted on your behalf.

Impact of Change: form - fit - function

Key Dates:

Contact By Date:03-Mar-2014

Implementation Date:03-Mar-2014

Product Affected

2203242-2

2035334-7

2098762-2

1456968-3

2098762-4

Product Affected

- 1924955-2
- 2098762-8
- 1456574-6
- 1924968-6
- 2138699-4
- 1456968-1
- 2035334-5
- 1924955-1
- 2035170-4
- 1924955-4
- 1924727-5
- 2098762-5
- 2098753-6
- 2098762-7
- 2090/02-7
- 1924968-4
- 1456841-8
- 1456574-3
- 2138699-1
- 1924955-8
- 2035170-3
- 2098762-3
- 2098165-3
- 1924968-8
- 2098753-5
- 1456574-1
- 1924955-7
- 2035334-2
- 1456968-2
- 1456574-5
- 1456841-6
- 1430041-0
- 1456968-4
- 1456841-2
- 2035170-5
- 2035334-6
- 1456574-2
- 2138699-2
- 1456841-7
- 1924968-1
- 2035334-8
- 1-1456574-1

Product Affected

- 1924727-7
- 1924727-8
- 1924955-3
- 2035170-7
- 1924727-3
- 1924968-3
- 2098753-3
- 2098753-2
- 2035170-1
- 1924968-2
- 1924727-6
- 1924727-2
- 1456841-3
- 1450041-5
- 1456574-8
- 2035170-8
- 2098753-4
- 1456574-7
- 2203242-1
- 1924955-6
- 1924968-5
- 2035170-2
- 1456841-1
- 2035334-1
- 2098165-4
- 1456841-4
- 2098753-8
- 2035334-4
- 2098762-6
- 1924955-5
- 2098165-1
- 2070105-1
- 1924727-4
- 1-1456574-2
- 2098753-1
- 2098753-7
- 1456841-5
- 2098762-1
- 1924727-1
- 1924968-7
- 2035334-3
- 2138699-6

Product Affected

2138699-3

2035170-6

2138699-5

2098165-2

1456574-4

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.